



1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

National Transportation Safety Board
M/V Massachusetts Fire Factual Report

Accident

Vessel: SPV *Massachusetts*
Date: June 12, 2006
Location: Near Long Island Bridge, Boston Harbor, Boston, Massachusetts
NTSB No.: DCA06MF016

NTSB Investigation Staff

Brian Curtis, IIC/Engineering Group Chairman
Bill Woody, Deck Operations/Human Performance Group Chairman
Liam LaRue, Survival Factors Group Chairman
Joe Panatagiotou, Fire Group Chairman

Party Representatives to the Investigation

Ltjg. Cahli Carothers
CWO Ray Colicci
U.S. Coast Guard
Sector Boston
455 Commercial St.
Boston, Massachusetts 02109

Jay Spence, General Mgr.
Massachusetts Bay Lines, Inc.
60 Rowes Wharf
Boston, Massachusetts 02110

David Sears
VP, Customer Assurance & After Sales, N.A.
MTU Detroit Diesel, Inc.
13400 Outer Dr.
Detroit, Michigan 48239

1
2
3
4 **TABLE OF CONTENTS**

5
6 SYNOPSIS 3
7 EVENTS PRECEDING THE ACCIDENT 4
8 ACCIDENT NARRATIVE 7
9 MECHANIC'S ACTIONS 11
10 INJURIES 14
11 DAMAGE 14
12 PERSONNEL INFORMATION 15
13 Captain 15
14 Mate 16
15 Lower Deck Deckhand 17
16 Upper Deck Deckhand 17
17 Mechanic 17
18 VESSEL INFORMATION 19
19 General information 19
20 Vessel layout 19
21 Pilothouse equipment 21
22 Engine room equipment 22
23 Steering System 23
24 WRECKAGE 23
25 WATERWAY INFORMATION 24
26 OPERATIONAL INFORMATION 26
27 MANAGEMENT INFORMATION 28
28 METEOROLOGICAL INFORMATION 28
29 TOXICOLOGY TESTING 29
30 SURVIVAL ASPECTS 30
31 Emergency Response 30
32 Boston Fire Department Marine Unit 33
33 Firefighting Equipment 35
34 Fixed Firefighting Regulations 35
35 SMALL PASSENGER VESSEL STATISTICS 36
36 TESTS 37
37 FIRE GROUP FACTUAL DOCUMENTATION 37

1 SYNOPSIS

2

3 On Monday, June 12, 2006 at 1600¹, the M/V *Massachusetts*, a U.S. Small Passenger Vessel
4 carrying 65 passengers and 4 crewmembers, departed Rowe's Wharf in Boston Harbor for its
5 first scheduled afternoon commuter ferry run to Hingham, Massachusetts.

6

7 At approximately 1610, in the vicinity of Long Island Bridge, a fire was detected in the engine
8 room from black smoke coming out the stern engine room vents. The master maneuvered the
9 vessel into shallow water south of the bridge, anchored, and awaited shoreside assistance in
10 combating the fire. The master hailed the M/V *Laura*, another commuter vessel in the vicinity,
11 and safely transferred all passengers to that vessel. A Boston Fire Department fireboat was
12 dispatched to the scene, and subsequently extinguished the fire. There were no major injuries or
13 fatalities caused by the accident.

14

15 The fire's damage was contained to the engine space. Damage caused by the fire was estimated
16 at \$800,000.

¹ All times are local Eastern Daylight Savings Time (ZD+4)



Figure 1- Massachusetts Photo (Courtesy of Mass Bay Lines)

1
2
3

4 EVENTS PRECEDING THE ACCIDENT

5 At 0650, on the morning of June 12, 2006, the, M/V *Massachusetts* departed its berth at
6 Hingham Shipyard to begin the first of 3 morning commuter runs between Hingham Shipyard
7 and Rowes Wharf in Boston. The crew comprised a captain, mate, and two deck hands. The
8 vessel operated as a commuter vessel during the morning and afternoons Monday through
9 Friday. Outside of those times periods, it conducted sightseeing tours, and occasional whale
10 watching tours, including on weekends. About 30 minutes after departing Hingham, the vessel
11 arrived at Rowes Wharf, near Boston's financial district, and disembarked its passengers . The
12 next group of passengers boarded the vessel and it departed for its return trip to Hingham at
13 0730. Following its 0800 arrival in Hingham, the crew once again offloaded its passengers, took
14 on its final morning's group of commuters, and return to Rowe's Wharf, arriving at 0850. Each
15 commuter trip traveled a distance of approximately 10 miles and took about 30 to 40 minutes.

1 Following its morning commuter runs, the *Massachusetts* made 2 previously scheduled
2 sightseeing tours of Boston Harbor. The first began at 0930, returning to Rowe's Wharf at 1015.
3 The second tour departed Rowe's Wharf at 1100, and returned to Rowes Wharf at 1230.

4
5 After disembarking its sightseeing passengers, the captain got the vessel underway for
6 Charlestown, for some engine repairs scheduled to be conducted before the 3 afternoon
7 commuter ferry runs beginning at 1600 from Rowes Wharf. The vessel arrived dockside at
8 Charlestown about 1245. The captain had previously called ahead to the company's regular
9 contractor, a small company consisting of an owner, a diesel mechanic, a welder, and a mechanic
10 in-training. The contractor regularly serviced the propulsion and generator engines on
11 Massachusetts Bay Lines vessels. The mechanic had been informed about the vessels schedule
12 and met the *Massachusetts* at the Charlestown dock at approximately 1245. The mechanic and
13 captain discussed the scope of work to be perform, which included examining the starboard
14 outboard propulsion engine² for excessive blow-by³ from breathers on the valve covers, an
15 examination of the port generator for sparking that had been reported by a crewmember during
16 the past weekend, and the port inboard propulsion engine, which had been idling at a higher
17 speed than normal.

18
19 The mechanic first worked on the starboard, outboard propulsion engine, and diagnosed the
20 problem as a blown head gasket. After conferring with the captain, it was decided the repair
21 work would be started later that week. The mechanic then moved to the port generator. The

² The *Massachusetts* was fitted with four Detroit 12V71 main engines that turned four propellers and two 3V71 diesels that drove two 30 KW generators.

³ A condition where excessive engine cylinder combustion gases pass from the combustion space into the crankcase, and are vented through the valve cover breather.

1 mechanic removed the cover for the generator and tested the generator with a full electric load
2 applied, but found no sparking or other indication of faulty operation of the generator. The test
3 of the port generator, conducted by the mechanic, was also witnessed by the mechanic's
4 employer and the captain. The captain elected to call for a marine electrician to look further into
5 the matter, and decided to use only the starboard generator for meeting the vessel's electrical
6 needs until further examination of the generator could be conducted.


7
8 The mechanic's last task was to examine and repair the port inboard propulsion engine. The
9 owner of the repair company advised the mechanic to look for a faulty injector, which the
10 mechanic also suspected to be cause of the high idle RPM. The captain and Mass Bay Lines
11 general manager, operator of the vessel, also suspected that the high idle speed of the port
12 inboard engine was being caused by a stuck fuel injector. Then the owner of the repair company
13 left the vessel. The mechanic found that the rack (fuel control) for the No. 3 inboard injector was
14 frozen. He replaced the injector, and, after test-running the engine for about 15 minutes,
15 departed the *Massachusetts*. For additional detail, see "Mechanic's Actions" section of this
16 report.

17
18 At 1530, the captain got the vessel underway for Rowe's Wharf for its first afternoon commuter
19 trip scheduled for 1600. During the 15 minute trip to Rowes Wharf, the captain elected to use
20 the two outboard engines for propulsion, a usual practice, in the interest of fuel economy; hence,
21 both inboard engines were not operating.

22

1 ACCIDENT NARRATIVE

2 The vessel boarded 65 passengers, a typical passenger count for the 1600 trip from
3 Boston's Rowes Wharf to the Hingham Shipyard. The Massachusetts departed the dock on
4 schedule with the mate at the helm. See figure 2 below for a diagram of the Massachusetts
5 typical daily commuter route from Rowes Wharf to Hingham Shipyard. Prior to departing, the
6 master of the *Massachusetts* provided a safety briefing to passengers. This briefing was
7 delivered over the PA system to the inner accommodation areas, as well as the outer decks.
8 Passengers were informed about the location and type of lifesaving equipment on board and told
9 to follow the instructions of crewmembers in case of an emergency.
10 Soon after leaving Rowes Wharf, the captain went to the engine room to bleed air out of the air
11 conditioning system. He did not detect anything out of the ordinary at that time. The captain then
12 returned to the pilothouse. Approximately 10 minutes into the trip, about 1610, the upper deck
13 deckhand entered the pilothouse to report to the captain that she noticed black smoke at the
14 vessel's stern. At the same time, the port inboard propulsion engine high water temperature
15 alarm sounded. The mate secured the alarming engine and slowed the remaining 3 engines from
16 2000 to 1300 RPM, at the captain's directive. The captain proceeded to the engine room to
17 investigate the cause of the smoke.



1
2 Figure 2- Typical commuter trip route for *Massachusetts*

3 Upon opening the starboard door to the engine room, the captain encountered heavy smoke, and
4 immediately closed the door. The captain went to the phone at the main deck bar and called the
5 pilothouse, informing the mate of the situation and instructing him to secure 2 of the remaining
6 engines, and leave the starboard inboard engine running. The captain then made his way toward
7 the pilothouse. Along the way, he directed all main deck passengers and the main deck
8 deckhand to proceed to the upper deck. Once on the upper deck, he briefed the passengers about
9 the situation, and informed them he would be hailing another passing commuter vessel,
10 requesting that vessel take them on board. He directed the deckhands to have the passengers,
11 now all on the upper deck, don lifejackets, and then he continued on to the pilothouse. A

1 passenger on the vessel happened to be a Commander in the Coast Guard commuting home. The
2 captain apprised the Coast Guard officer of the fire, and asked for his assistance in contacting the
3 Coast Guard. The Commander notified Sector Boston Coast Guard about the fire, using his cell
4 phone.

5
6 When the captain returned to the pilothouse, the mate informed him that after he left the
7 pilothouse to assess the fire, the port outboard engine had lost RPM, and that he had secured the
8 engine at that time. By this time, the vessel had passed south of the Long Island Bridge. The
9 captain then relieved the mate at the helm, and ordered the mate and one deckhand to go to the
10 bow and prepare to drop the anchor. The mate also instructed the other deckhand to assist with
11 the anchor. While the mate and two deckhands were preparing to drop anchor, the captain,
12 contacted the M/V *Laura*, another nearby commuter ferry vessel, by VHF radio, marine channel
13 13. The captain informed the *Laura*'s captain that his vessel had suffered an engine room fire.
14 He requested the *Laura* come alongside to receive the Massachusetts 65 passengers. The *Laura*
15 was about a half mile south, headed north en route from Hingham to Rowes Wharf, with 3
16 passengers aboard. The *Laura* immediately altered course to assist the *Massachusetts*.

17
18 The Coast Guard Commander entered the pilothouse, and reminded the captain to secure
19 the engine room's ventilation supply blowers⁴, which the captain did at that time.

20

⁴ The two blowers that supplied air to the engine room could be turned off on the bridge. However, there were no ventilation dampers in either the two supply and two exhaust plenums (ducts); hence, there was no means to restrict ducted air flow to the fire.

1 Having made contact with the *Laura*, the captain navigated the *Massachusetts* to the east
2 just outside of the channel, approximately one half mile south of the Long Island Bridge, and
3 ordered the mate to drop the anchor. The *Massachusetts* anchor location is designated by the
4 anchor symbol in figure 2. Having safely anchored the vessel, the captain sent the mate to the
5 main deck to secure the emergency fuel oil shutoff valves, located behind the bar service area, on
6 the starboard side. The 2 deckhands returned to the upper deck to attend to the passengers. At
7 this time the captain shut down the starboard inboard engine. The generator shut down due to
8 fuel starvation about 30 seconds after the after the emergency shutoff valves were secured.

9

10 About 1620 the *Laura* came alongside and tied up on the starboard side of the
11 *Massachusetts*. The crew then led the 65 passengers, still in their lifejackets, down the forward
12 starboard ladder to the main deck, and out through the starboard forward side door directly onto
13 the *Laura*. It was an orderly transfer, taking less than 5 minutes, according to crew statements.
14 At 1635, the *Laura* untied, and departed the *Massachusetts* with its passengers, bound for
15 Hingham Shipyard.

16

17 At the same time the *Laura* was tying up on the starboard side, a Quincy marine police
18 vessel came along the port side, and ask the mate if they needed assistance from the fire
19 department and the mate stated that assistance was needed. The police boat then notified the
20 Coast Guard of the need for Boston Fire Department's fire vessel to assist in fighting the fire.
21 The fire department's vessel "*Firefighter*" was dispatched at that time.

22

1 Having transferred the passengers to safety, the captain gathered his crew, and realizing
2 the intensity of the fire in the engine room, informed them that they would not be fighting the
3 fire and that they would wait for city firefighting crews to extinguish the blaze. In his statement,
4 the captain indicated he did not want to introduce any additional oxygen into the engine room by
5 attempting to fight the fire.

6
7 At approximately 1645, the crew transferred from the *Massachusetts* to the Quincy
8 marine police vessel at the Coast Guard's request, and remained in the area until the fire was
9 contained.

10 The "*Firefighter*" arrived on scene at approximately 1730, and extinguished the fire at
11 1848. Except for a small burnt area in the rug near the port ventilation duct, all fire and smoke
12 damage was confined to the engine room.

13
14 The crew were later transferred to a Coast Guard vessel, and transported to the Hingham
15 Shipyard dock, arriving ashore at 2130.

16
17 The *Massachusetts* was taken under tow by a local harbor tug at 2240 and moved to a
18 pier at Deer Isle, in Boston Harbor.

19

20 **MECHANIC'S ACTIONS**

21 The mechanic⁵ who performed repairs on the vessel earlier on the afternoon of the day of the fire
22 had no formal training from the engine's manufacturer, Detroit Diesel. Federal regulations

⁵ Willis06-16-06 interview.

1 regarding small passenger vessels do not require mechanics or company personnel performing
2 engine work to have such engine-specific training or credentials in order to effect maintenance or
3 repairs to propulsion or associated machinery on small passenger vessels.

4 His experience and knowledge of these engines had been achieved exclusively by his having
5 been employed at his current employer for the past 12 years, through on the job training. He told
6 investigators that in his time working for his employer, he “specialized” in Detroit Diesel engine
7 work. He estimated that “80 percent “ of the work he does is spent working on Detroit Diesels.
8 He also stated that he had been doing work on Massachusetts Bay Lines vessel engines for
9 approximately 9 years. He stated that he would only work on their engines when he was called
10 in for some type of engine problem, and did not perform periodic inspections of the company’s
11 engines.

12 According to the mechanic’s interview with investigators, the following is a detailed description
13 of the steps he took in changing out the #3 injector on the starboard inboard bank of the port
14 inboard propulsion engine earlier in the afternoon the day of the fire:

15 ⁶After having addressed the concerns of the starboard outboard engine, and the
16 port generator, he turned his attention to the port inboard engine. He had been called to
17 look at this engine as well, as the captain told him that it was idling too fast, and would
18 not come down to its normal idle speed.

19 During his initial inspection of the engine, he removed the inboard valve cover to check
20 the 6 cylinder fuel injectors located on that side of the engine. On his inspection of these
21 injectors, he noticed the 3rd injector from the front of the engine was stuck in one
22 position. He tried to physically move the injector rack, and noted it was frozen in place.

⁶ Willis06-16-06 interview, page 8, line 20 through page 11, line 11.

1 At this time, he made the decision to replace the injector to correct the engine's high idle
2 speed problem.

3 In performing the change of the #3 injector, he then removed the supply and return fuel
4 lines connected to the injector. He then unbolted the fasteners holding the injector to the
5 engine, removed it, and bolted another in its place. The mechanic stated that in replacing
6 an injector on this engine, there are no calibrations or settings required once the new
7 injector is in place. When asked if he used a torque wrench during the new injector
8 installation, he stated that he did in fact use one, torquing the rocker stand to 104 foot
9 pounds, and the injector hold down to 25 foot pounds. He stated that he did not use a
10 torque wrench on the fuel supply and return lines because if they are over-tightened, the
11 flare nuts on them can split open. (It was one of these #3 injector's fuel lines
12 investigators found disconnected from its mating surface.)

13 Upon completing the installation of the new injector, the mechanic told investigators that
14 he ran the engine with the valve cover off to inspect the work he had just completed.

15 ⁷(The captain, in his interview, stated that he believed the valve covers were on during
16 the test run, but could not confirm it as he was running the engine from the pilothouse,
17 and the mechanic was in the engine space alone observing the engine.)

18 Having completed this task, the mechanic left the vessel at approximately 1530, and the
19 vessel departed Charlestown for Rowes Wharf to begin their afternoon commuter
20 schedule. The captain ran only the 2 outboard propulsion engines in navigating the
21 vessel back to Rowes Wharf.

22

⁷ Capt Bodie 6-29-06 interview, page 6, line 16.

1 **INJURIES**

2 The injuries sustained in the *Massachusetts* accident, shown in table 1, are categorized
3 according to the injury criteria of the International Civil Aviation Organization (ICAO). One
4 passenger suffered an asthma attack brought on by smoke inhalation and was treated at the
5 scene. Another passenger was treated and released at a local hospital for minor smoke
6 inhalation and a spike in a pre-existing blood pressure condition. The Safety Board uses the
7 ICAO injury criteria in all its accident reports, regardless of transportation mode.

8 **Table 1.** Injuries sustained in *Massachusetts* accident.

Type of Injury	Crew	Passengers	Total
Fatal	0	0	0
Serious	0	0	0
Minor	0	2	2
None	4	61	65

Title 49 CFR section 830.2 defines a fatal injury as any injury that results in death within 30 days of an accident. It defines serious injury as that which requires hospitalization for more than 48 hours, commencing within 7 days from the date the injury was received; results in a fracture of any bone (except simple fractures of fingers, toes, or nose); causes severe hemorrhages, nerve, muscle, or tendon damage; involves any internal organ; or involves second- or third- degree burns, or any burn affecting more than 5 percent of the body surface.

9 **DAMAGE**

10 The vessel suffered fire damage in the engine room, and to a much lesser degree, the interior of
11 the main deck level. The estimated costs of repairs necessary to return the vessel to service was
12 \$800,000. Additional information about the damage appears in the “Wreckage” section of this
13 report.

1 PERSONNEL INFORMATION

2 Captain

3 The captain of the *Massachusetts*, age 55, began his maritime career as an ROTC Midshipman in
4 college. At graduation in 1973, he received a commission as an officer in the U.S. Navy and was
5 assigned to an aircraft carrier. He served as a deck officer for three and a half years on the
6 aircraft carrier and qualified as an officer of the deck underway. After sea duty, he served a year
7 and a half as an instructor at the Navy's Surface Warfare School at Coronado, California. After
8 leaving the Navy, he did some work on various sail cruising vessels and various jobs ashore. In
9 1985, he obtained a U.S.C.G. 100-ton masters license and employment operating small
10 passenger vessels for a few months in Boston. After a few months, he obtained employment with
11 Massachusetts Bay Lines and has been employed with the company for over 20 years. He has
12 acquired experience operating various small passenger vessels owned and operated by the
13 company. During most of his employment with Massachusetts Bay Lines, he has been the
14 permanent captain⁸ of the *Massachusetts*. In fact, he has was the captain who worked aboard the
15 vessel during the time it was being constructed in the shipyard, and he delivered it to Boston
16 Harbor upon its completion in 1988. He is responsible for the material condition of the vessel
17 and arranges for repairs and ensures the repairs are satisfactory. He is personally involved in
18 changing oil in the diesel engines, starting up the engines, bringing generators on line and
19 starting the air conditioning systems. In preparation for his daily commuter trips, he receives
20 reports from other captains and crewmembers operating the *Massachusetts* on his days off about
21 any condition affecting the condition or functioning of the vessel, and takes action as necessary
22 for any needed repairs.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22

The captain works four days per week, operating the vessel Monday, Tuesday, Thursday, and Friday. He reports to work at 0600 and generally leaves work about 1845. On weekends he usually goes to bed around 2300, and gets up about 0730. He characterized his work/rest periods as pretty routine and that there had been no dramatic events to affect his schedule.

Mate

The mate, age 27, started work with Massachusetts Bay Lines as a deckhand in May 1997. In May 2001, he acquired a U.S.C.G. 100 ton masters license. The mate stated that he had taken a licensing school course to prepare for the license examination. During the nine years with the company, he had operated various vessels as the captain or mate. For the past two years, he normally works the commuter runs on the *Massachusetts* on Tuesday, Wednesday, Friday, and on other company vessels as needed, depending upon whether the vessels are chartered for various cruises. He is a fully qualified captain, but serves as the mate on the *Massachusetts* when the permanent captain is operating the vessel.

He normally works 50 to 55 hours per week. On Friday, prior to the Monday of the accident, he got to bed that night about 0030. The next day, he worked two cruises, one on Saturday afternoon and one on Saturday night lasting until 0230 Sunday morning. He departed the company a couple hours later, about 0400 and got to bed about 0445. He arose and attended a graduation party Sunday afternoon and went to bed about 2200 or 2230 that evening. He got up Monday morning at 0430, his usual time. He stated that he felt rested.

⁸ Each of the seven vessels operated by Massachusetts Bay lines has one captain permanently assigned,

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22

Lower Deck Deckhand

The lower deck deckhand, age 55, had been employed as a deckhand for approximately 8 months and was considered to be an experienced, reliable crewmember. All of his marine experience had been on the *Massachusetts*. His duties involved line handling, serving coffee to passengers at lower deck galley, assisting passengers, counting passengers as they board, and checking the engineroom at the midpoint of each commuter trip, in the vicinity of Long Island Bridge.

Upper Deck Deckhand

The upper deck deckhand, age 20, had been employed by Massachusetts Bay Lines since May 22, 2006. This was her first maritime employment. The captain had given her a familiarization tour of the vessel and had pointed out the storage for the life jackets and other safety equipment. Her responsibilities included line handling, assisting the passengers, and serving drinks at the upper deck bar. (She was the first to notice greater than normal amount of dark smoke astern of the vessel and to report the smoke to the pilothouse.)

Mechanic

The mechanic stated that he had attended Southern Maine Vocational Technical Institute in South Portland, Maine, for marine engineering, and then had shipped out on tankers with Sun Transport (SUNOCO) for a year and a half, and then he had been employed by Steve's Shop, his current employer, for almost 12 years as a diesel mechanic. His diesel repair and maintenance knowledge during his employment time with his current employer has been acquired solely

who is in charge of the vessel's maintenance and repair.

1 through “on the job” experience. He estimated that 80% of the diesel engines he works on are
2 Detroit diesels. He is the mechanic who normally works on engines in Massachusetts Bay Line
3 vessels. He described how an injector could cause a high idle speed and how he determined
4 which injector was faulty, the steps in changing the injector, and cited the torque values from
5 memory for the hold-down bolts. He characterized changing an injector as a very simple
6 procedure.

7
8 The mechanic stated he normally had a standard work/rest routine, and that he works
9 only at his primary employment, and that he was not involved in any other employment, a
10 second job, or volunteer work. He explained that he normally got up between 0445 and 0500
11 during the week, obtained coffee en route to the work, and arrived at the shop at 0600. He stated
12 that on the Friday, prior to the accident, he believed he had worked in the shop that day, and he
13 did not recall any unusual activity associated with the workday. He normally arrives home
14 between 1630 and 1700, and believed he did so on Friday. After dinner at home, he had done
15 some work on his car until about 2300, which he described as nothing strenuous. He recalled
16 going to bed around 2330 or 2400 on Friday and Saturday nights and getting up about 0600 on
17 Saturday and Sunday morning. He had dinner at home and he was not involved in any outside
18 activities. He recalled getting to bed Sunday evening about 2130. He states that he gets to sleep
19 soon after lying down and has no problem sleeping. He got up Monday at his usual time between
20 0445 and 0500. He stated that he felt fine on Monday. He considers his health to be good and
21 was not taking any prescribed medications. He does not wear glasses and states that he reads
22 comfortably. He had eaten lunch prior to going aboard the *Massachusetts* to carry out the
23 examination and repair of the two propulsion diesel engines, and the port generator.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21

VESSEL INFORMATION

General information

The *Massachusetts* was delivered in 1988 by builder Gulf Craft, Inc., located in Patterson, Louisiana. Massachusetts Bay Lines contracted Gulf Craft to build the vessel for them, to be used in the Boston Harbor commuter trade. It has been used by Massachusetts Bay Lines in the Boston Harbor commuter trade since its delivery in 1988. The *Massachusetts* is listed at 87.6 feet in length, 25 foot beam, and 99 gross tons on its Coast Guard Certificate of Inspection (COI). The *Massachusetts* was certified to carry 346 passengers, and 4 crewmembers, for a total of 350 persons.

Due to certification to carry more than 150 passengers, being registered less than 100 gross tons, and carrying passengers for hire, the *Massachusetts* falls under 46 CFR Subchapter K (Parts 114-122).

The vessel was not equipped, nor was it required to be equipped with, a either fire detection or a fixed fire suppression system.

Vessel layout

The hull is constructed of aluminum and divided into 6 compartments below the main deck. Each compartment is separated by a transverse aluminum bulkhead extending from the bilges upward to the main deck. All of the compartments below the main deck contained a bilge suction, and the 4 aftermost spaces were additionally equipped with high water alarms.

1 The forward most compartment, beginning at the bow, contained anchor rope and spare lines.

2 The next section aft contained only a sewage holding tank, and its associated macerator pump for
3 emptying the tank shoreside.

4 The third compartment from the bow contained an area where passengers could access, but
5 according to the lower deck deckhand, they generally did not tend to occupy that space during
6 commuter trips. This same space was also used by the crew for storage of stock amenities such
7 as coffee, etc. The space also contained a small workshop with vessel tools on the port side.

8 Immediately aft of this space was a narrow compartment, relative to forward and aft, which
9 contained the fuel and potable water tanks. The port and starboard fuel tanks were situated at the
10 far inboard section this compartment, divided at the vessel's centerline. Outboard of the fuel
11 tanks, separated by a void space to insure against contamination, were the potable water tanks,
12 stretching outward to the vessel's outer hull skin.

13 Aft of the fuel and water compartment is the engine room. Here the four propulsion engines, the
14 vessel's 2 electrical generators, and associated engineering systems piping and equipment are
15 contained.

16 The last compartment of the vessel below the main deck extended to the stern of the vessel. This
17 space contained the vessel's exhaust piping, steering hydraulic control ram, and its associated
18 rudder control linkages, to position the rudder from the pilothouse.

19 The *Massachusetts*' main (lower) deck was essentially an open area with folding chairs situated
20 throughout the space for commuter seating, as well as fixed seating in the forward area of the
21 deck. The entire main deck area was enclosed, to keep commuters out of the weather. Restroom
22 facilities were located at the aft end of the main deck. A small open stern deck area was aft of
23 the restrooms, allowing crewmembers to handle lines in securing the vessel during docking.

1 A small bar/serving area was located midships on the starboard side. Located within this bar
2 area were the emergency fuel shutoff levers for the propulsion engines and generators. The
3 upper deck was accessed by one of 2 main deck ladderways; one at the vessel's port stern, and
4 the other forward starboard on the main deck.

5 The upper deck had an enclosed section at the midpoint of the vessel for passengers to remain
6 out of the weather. This enclosed area contained the upper deck bar area as well. Passengers
7 could access open deck areas both forward and aft on the upper deck. This deck contained both
8 fixed and folding chairs for passenger seating.

9 Pilothouse equipment

10 The pilothouse (figure 3) was accessed from a short forward ladder on the upper deck. The
11 equipment available to the captain consisted of:

- 12 • 2 Furuno radars (x and s band)
- 13 • 2 Raytheon VHF marine radios
- 14 • 1 International depth sounder
- 15 • 1 Magellan GPS unit
- 16 • Horn
- 17 • Searchlight
- 18 • Magnetic compass


19 The pilothouse was also equipped with a vessel public address (PA) system to communicate with
20 passengers and crew throughout the vessel. This PA system was used to announce the their pre-
21 departure safety briefing.

22 The wheelhouse was also equipped with an engine room high temperature alarm, triggered by a
23 thermal device situated in the overhead between the main engines. According to the company
24 General Manager, this device was installed in the vessel prior to its delivery in 1988. It was
25 intended as a warning to the operator in the event a main engine should overheat.⁹ It consisted of

⁹ Jay Spence Interview summary 09-28-06

1 a red light labeled “heat” on a center alarm panel in the wheelhouse. If any alarms on that panel,
2 another included a high engine room bilge level alarm, sounded, it would ring a bell located in
3 the wheelhouse in addition to illuminating the panel light, to alert the operator. Years later, a
4 more sophisticated main engine monitoring panel was installed in the wheelhouse to alert the
5 operator to various, and more detailed, engine faults. Testing of this heat alarm was not
6 conducted on a regular basis, and results were not logged.

7



8
9 Figure 3- *Massachusetts* pilothouse

10

11 Engine room equipment

12 The *Massachusetts* was propelled by 4 propulsion diesel engines rated at 675 horsepower each.
13 All engines were of the same manufacturer, Detroit Diesel, and model, 12V71. These engines
14 were 12-cylinder, turbocharged engines coupled to individual drive shafts through reduction
15 gearboxes. They were situated in the engine space with 2 of the engines forward and inboard,
16 and the other 2 slightly aft and outboard. The engine identified earlier in this report that had
17 been worked on previously during the day of the fire was the port inboard engine.

1 The engine space also contained the vessel's 2 electrical generators. Each of these generators
2 was driven by Detroit Diesel 3 cylinder diesel engines. Each generator developed 30 kilowatts
3 of output power. Typically, one generator was used at a time, with the one in use alternated daily
4 to evenly distribute the hours put on each machine.

5 The day of the fire, the starboard generator was online and in use. The port generator was out
6 of service pending a service technician's looking at it.

7 Other equipment situated in the engine compartment were: the 2 hydraulic steering gear pumps
8 to control rudder movement; 2 engine space supply blowers (one on each side in the inlet air
9 supply ducting); 12 and 32 volt battery banks to supply power to vessel equipment being
10 serviced by DC power; 2 fire/bilge pumps; and other associated piping and pumps used in the
11 running of the vessel's engineering systems.

12 Steering System

13 The steering system was of the electro-hydraulic type. Input rudder commands initiated at the
14 pilothouse steering wheel were received at the pump control in the engine room. This in turn
15 would change the hydraulic cylinder position in the lazarette (aftermost stern section). This
16 hydraulic cylinder was connected by linkages to the 2 individual rudders in the same space, and
17 by the linkages' movement, would move the rudders together to the position ordered by the
18 operator in the pilothouse.

19

20 WRECKAGE

21 The *Massachusetts* exterior sustained minor damage, that being ostensibly sooting of the exterior
22 paint in way of the 4 engine space vents, 2 on each side of the vessel. However, no structural
23 damage was noted to the exterior surfaces of the vessel.

1 All interior space damage was contained to the main deck level. Even on this level, the damage
2 was limited to primarily cosmetics. Some carpet charring was observed adjacent to the casing of
3 the forward engine space vent ducting on the port side. Seven of the windows around the
4 periphery of the main deck were broken, those as a result of the firefighters efforts during the
5 containment of the fire.

6 The engine space sustained the majority of the Massachusetts damage. All four propulsion
7 engines encountered both damage from the fire, as well as that from firefighting efforts in their
8 use of water and foam to contain the blaze. The greatest fire-related heat damage was sustained
9 by the port inboard engine, and is detailed in the fire group factual report.

10 In essence, all machinery and components, including the propulsion engines, the generators, and
11 electrical wiring situated in the engine compartment, were totally lost to the fire.

12 The upper deck and pilothouse sustained no damage as a result of the fire.

13

14 WATERWAY INFORMATION

15 Boston harbor is a significant commercial port that has figured prominently in US
16 history. Many commercial piers, formerly needed for breakbulk shipping have been transformed
17 into residential complexes and retail shopping, or used for recreation purposed. The switch from
18 break bulk to container shipping starting in the early 1970s resulted in the construction in 1980
19 of the Paul W. Conley Terminal, a modern, large container terminal, which accounts for most
20 general cargo imported and exported through the port. The port is an important recipient of
21 refined petroleum products and Liquefied Natural Gas (LNG) supplying much of the energy
22 needs of Boston and neighboring cities. The port has one terminal dedicated to importing
23 shipments of foreign built autos. A dedicated cruise vessel terminal facilitates a growing cruise

1 industry operating from the port, with 81 passenger cruise ships calling, or scheduled to call, in
2 Boston, in 2006.

3
4 The harbor is well marked by navigation aids and traffic lanes provide for orderly flow of
5 marine traffic. The tidal range is approximately 9 to 9.5 feet, and maximum currents in the
6 harbor range from 0.8 to 1.5 knots. The weather is characteristic of northern Atlantic coastal
7 cities with cold winters and warm summers. There is no dry season and precipitation every few
8 days is normal and dry spells exceeding 2 weeks are rare, with November being the wettest
9 month. Coastal storms, or “nor’ easters” can result in heavy rain and snowfall. The main snow
10 season extends from December through March, and December is the month normally having the
11 greatest snowfall. Freezing weather can be expected from early November through early April,
12 and January is the coldest month with average temperatures ranging from 37°F down to 22°F.
13 Winds exceeding 27 knots or higher can occur in every month. Gales are more sever and more
14 common in winter and produce winds from the northeast and east. At other times winds prevail
15 from the west to northwest. Fog is prevalent throughout the year. Winds occurring from the east
16 to the southwest bring fog and westerly and northerly winds clear it away.

17
18 A wide range of services is available to serve the maritime industry. Repair facilities are
19 available for repairs to all sizes of vessels. One 1175-foot long drydock is available for
20 oceangoing vessels. And smaller drydocks are available for small vessels ranging from tugs to
21 large barges.

22

1 OPERATIONAL INFORMATION

2 Massachusetts Bay Lines, the operator of the M/V *Massachusetts*, is currently a family
3 owned corporation. Massachusetts Bay Line is a member of the Passenger Vessel Association, a
4 trade association representing most US small passenger vessels involved in commuter ferry and
5 tour/sight seeing service. The principals of the present corporation have been involved in
6 operating passenger vessels for over 40 years, and at one time their primary operations were
7 operating vessels in a ferry service from Boston to Nantasket primarily for those visiting the
8 beach or the former amusement park. Eventually, for a time the company was involved in other
9 ferry routes in the Boston area. By about 1980, the primary focus of operations comprised harbor
10 sight seeing tours, private party trips, whale watching trips, and some commuter operations in the
11 Boston area.

12
13 The company currently has 7 small passenger vessels¹⁰ in operation, including the M/V
14 *Massachusetts*. Each of the vessels has a permanently assigned captain who is in charge of the
15 vessel. The company utilizes forms for reporting emergency repair needs. (This form was used
16 to report the sparking by the port generator and excess smoke from the starboard outboard
17 propulsion engine.) The captain in charge makes arrangements for repair work, subject to
18 concurrence with the office, and is responsible for follow-up to ensure repairs are made
19 correctly. Routine vessel maintenance, such as oil changes and filter changes, were typically
20 performed and logged in the vessel maintenance book, by the respective vessel's permanently
21 assigned master.

¹⁰ Massachusetts Bay Line vessels and their maximum passenger capacity: *Harbor Belle* – 100; *Seaport Belle* – 120; *Nantascot* – 200; *Samuel Clemens* – 250; *Freedom* – 300; *Massachusetts* – 300; and *New Boston* – 325;

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23

The spring through early fall is the primary season for sight seeing tours, private party trips, and whale watching trips. Except for the *Massachusetts*, which is regularly dedicated to commuter service between Rowes Wharf and Hingham Shipyard, many vessels are inactive for much of the time during the winter months. However, in recent years large groups from Asia, occasionally booking harbor sightseeing tours throughout the year, have resulted in increased vessel employment during the winter months.

The Massachusetts Bay Transit Authority (MBTA), which has responsibility for urban mass transit needs in the Boston area, operates rail and bus service, and ensures that regularly scheduled ferry service is available on certain routes. The MBTA awards and manages contracts with commercial passenger vessel owner/operators to provide scheduled ferry service on routes prescribed by MTBA as follows:

- (1) Quincy – Hull – Boston,
- (2) Hingham Shipyard – Rowes Wharf, and
- (3) Long Wharf Boston –Charlestown Navy Yard

The contracts specify that vessels must be in compliance with Coast Guard requirements. Vessel operators having contracts with MBTA are permitted to subcontract with other vessel operators in order to meet the terms of their contracts. At the time of the accident, the *Massachusetts* was operating pursuant to a subcontract with Boston Harbor Cruises, which had a 5-year contract with the MBTA to provide ferry service between Rowes Wharf and Hingham Shipyard. (The

1 M/V *Laura*, which embarked the passengers from the *Massachusetts*, is owned and operated by
2 Boston Harbor Cruises.)

3

4 MANAGEMENT INFORMATION

5 ¹¹The *Massachusetts* operator, Massachusetts Bay Lines, Inc., is a family-owned corporation,
6 having been started in 1963. The family's father serves as corporation President. His son acts as
7 the General Manager, taking care of day-to-day operations of the commuter vessels. The sister
8 serves as Chief Financial Officer, and the mother as Secretary-Treasurer. Other management
9 staff include: the Operations Manager, who recently became a full-time employee after having
10 retired from the Massachusetts Bay Transit Authority (MBTA); and, the Maintenance Manager.
11 The Maintenance Manager's responsibilities include oversight of all aspects of the commuter
12 vessel maintenance and repair work being performed.

13 The number of company employees ranges from approximately 100 during the busy summer
14 months to 15-20 during the winter months, and not all of those are full time employees.

15

16 METEOROLOGICAL INFORMATION

17 ¹²Meteorological information was obtained from the National Weather Service. The nearest
18 reporting station was located at Boston's Logan Airport, which is equipped with an Automated
19 Surface Observation System (ASOS). This system was located approximately 5 miles from the
20 fire scene.

21 No hazardous weather advisories were issued for the day of the accident. Clear skies were
22 reported at 1600, with unrestricted visibility at 10 miles, and broken cloud cover. The air

¹¹ Spence06-15 interview, page 5, line 6.

1 temperature was 70 degrees Fahrenheit, with 10-knot winds, gusting to 12 knots, at 110 degrees.
2 The sea temperature at the ASOS was reported to be 60 degrees, with wave heights of
3 approximately 1 foot. The tide for that day was high at 1233 EDT, and low at 1828.

4

5 TOXICOLOGY TESTING

6 Following the fire, none of the crewmembers were tested for the presence of alcohol.¹³

7 Shortly before 1700, the general manager of Massachusetts Bay Lines attempted to reach the
8 contractor that conducts toxicology testing for he company, however, no one answered the after
9 hours telephone number. Once the crew was brought ashore in Hingham around 2130 aboard a
10 US Coast Guard vessel, they were met by the president of Massachusetts Bay Lines, and
11 transported by him to a local hospital for testing. However, the hospital emergency room was
12 too busy to conduct the testing and recommended that the crewmembers return the next day.

13 When the hospital was unable to conduct the testing, Massachusetts Bay Lines president
14 contacted the Coast Guard for assistance, but was informed that the Coast Guard was not set up
15 to conduct post accident testing. On the following morning about 0900, the crewmembers were
16 taken to the office of the testing contractor and urine specimens were collected. However, no
17 alcohol testing was conducted at that time because of the elapse of time since the accident. The

¹² NTSB Meteorological Factual report, dated June 28, 2006.

¹³ Post accident alcohol and drug testing is required by Federal regulations at 46 CFR 4.06 for any accident meeting the criteria of a Serious Marine Incident. The regulations at 46 CFR 4.03-2 describe a Serious Marine Incident as an accident involving: (1) One or more deaths, (2) Requiring Medical treatment beyond first aid, or that renders a crewmember unable to perform routine duties, (3) Property damage in excess of \$100,000, (4) Loss of an inspected vessel, (5) Loss of an uninspected vessel of 100 Gross Tons or more, (6). Discharge of oil of 10,000 gallons or more into navigable waters, or the discharge of a reportable quantity of hazardous substances into the environment of the United States. On June 20, 2006, new Coast Guard regulations, at 46 CFR 4.06, became effective, requiring post accident alcohol testing to be conducted within two hours of the accident meeting the criteria of a Serious Marine Incident. Also, internal Coast Guard directives require Coast Guard personnel to conduct the alcohol testing if the marine employer does not or is unable to conduct the alcohol testing within two hours.

1 testing for the 5 illicit drugs¹⁴ for which post accident testing is required were negative for all 4
2 crewmembers.

3 Coast Guard headquarters has informed the Safety Board that the new regulations at 46
4 CFR 4.06, in effect since 20 June 2006, requiring alcohol testing in two hours, will be enforced
5 through civil penalties levied against any marine employer failing to conduct the alcohol testing
6 as prescribed. Similarly, a failure to collect urine specimens for drug testing within 32 hours
7 will also result in civil penalties.

8 Subsequent to the accident, Massachusetts Bay Lines acquired saliva test kits for alcohol testing
9 and a training disc for the test kits. The company, using the training disc, has trained several
10 employees in the use of the test kits.

11

12 SURVIVAL ASPECTS

13 Emergency Response

14 At 1630 on 12 June 2006, the Quincy Police Boat *Protector* was approaching the Long Island
15 Bridge from the Southwest when the crew observed the *Massachusetts* “dead in the water with
16 smoke showing from its stern”¹⁵. At 1635 they came alongside the vessel and made contact with
17 the *Massachusetts* mate on the main deck, who informed them that the engine room was on
18 fire¹⁶. Police on board *Protector* immediately called the Coast Guard on VHF channel 16,
19 notified them of the emergency, and requested a fire boat be dispatched. The crew of *Protector*
20 also notified Quincy PD Headquarters of the fire.

¹⁴ Federal regulations at 46 CFR 16.113 require testing for (1) Marijuana, (2) Cocaine, (3) Opiates, (4) Phencyclidine (PCP), and (5) Amphetamines.

¹⁵ J. Flaherty, Quincy PD, Incident Report # 6029536

¹⁶ Quincy PD Incident Report #6029536

1 A passing vessel, M/V *Laura*, was called by the *Massachusetts* on VHF channel 13 and asked to
2 provide assistance. The *Laura* agreed to help, came alongside, and made fast to the starboard
3 side of the vessel¹⁷. Passengers came down the interior stairway on the starboard side forward,
4 and disembarked the vessel out the forward starboard side doorway. All passengers were
5 reported to be wearing life jackets¹⁸. The *Laura* backed away to a safe distance once all
6 passengers were on board. *Massachusetts*' crew did not remember counting passengers as they
7 left the vessel¹⁹. A count was taken and logged however, on board the *Laura*²⁰. The Captain of
8 the *Massachusetts* and its crew remained on board the burning vessel for a short time after
9 passengers departed. They made a final round of all accessible spaces before escaping to the
10 *Protector*²¹.

11 Boston Fire Department's dispatch operations center, called Fire Alarm, received calls from the
12 Coast Guard and then Quincy Police reporting the fire on the *Massachusetts* at 1641 and 1642
13 respectively. At 1644 Fire Alarm dispatched the Marine Unit, located at Burroughs Wharf in the
14 North End of Boston, to the Long Island Bridge²².

15 Upon receiving the call from Fire Alarm, marine unit personnel boarded M/V *Firefighter* and
16 were underway within 2-3 minutes²³. The Marine Unit's other vessel, *St. Florian*, was out of
17 service due to an electrical problem that had earlier drained the batteries. Marine Unit Standard
18 Operating Procedures dictate that the smaller faster *St. Florian* would normally have been
19 launched first, with the *Firefighter* following later with land companies as needed.

¹⁷ Tom Sullivan Interview

¹⁸ Steve Bodie Interview, p. 43, lines 2-5

¹⁹ Peter Noonan interview

²⁰ Tom Sullivan Interview

²¹ Noonan interview

²² Timeline from emergency calls

²³ Chris Mackin Interview

1 At 1656 Fire Alarm dispatched Engine Company 2 and Ladder Company 19 to Conley
2 Terminal²⁴, located at the southeast end of the reserved channel²⁵ in South Boston, to be picked
3 up by the Marine Unit²⁶. At 1703 Fire Alarm dispatched the District 6 Fire Chief John Evans to
4 Conley Terminal, also to be picked up by the Marine Unit²⁷.

5 In route to the fire, *Firefighter* stopped at Conley Terminal to pick up the land companies and
6 Fire Chief. According to the pilot of the *Firefighter*, it took around 12-15 minutes to get from
7 Burroughs Wharf to Conley Terminal, and another 10 minutes to get the assembled firefighters
8 and their gear loaded. The remaining trip out to the Massachusetts took an additional 25-30
9 minutes²⁸.

10 Upon arriving on scene, the *Firefighter* approached the vessel on its port side²⁹. By this time,
11 there were no passengers or crew on board the *Massachusetts*. Heavy black smoke was noted
12 coming out of the vents and doorways on the stern. There were numerous assets already on
13 scene including boats from the Quincy police, Environmental police, State police, and Coast
14 Guard. A MassPort³⁰ fireboat also stood by. *Firefighter* made fast to the *Massachusetts* and five
15 firefighters initially went on board to battle the fire. One 2-½ inch fire hose was placed down
16 each of the two engine room accesses aft on the main deck, with 2 men manning each hose³¹.

17 Because of the size of these accesses and the strength of the fire, firefighter were unable to
18 actually enter the engineroom. Fighting the fire amounted to simply filling the engine room up
19 with water. Firefighting foam was also used down the port engine room access with little

²⁴ Massachusetts Port Authority, Paul W. Conley Terminal

²⁵ Coast Pilot 1, p. 371. A dredged unmarked channel containing modern and extensive freight terminals.

²⁶ Pickup point marked on Boston Harbor Chart by Chris Mackin

²⁷ Timeline from emergency calls

²⁸ Chris Mackin interview

²⁹ John Evans interview, Bodie interview from 6/15, p 17, line 23

³⁰ Fire and rescue boat from Logan Airport

³¹ John Evans interview

1 effect³². Initial efforts did not successfully extinguish the fire. The District Fire Chief, who was
2 the On Scene Commander, described the main deck as having “steam coming out of the carpet”.
3 Firefighters requested the assistance of one of the ship’s crew in finding a better way to access
4 the engineroom and battle the fire. Massachusetts’ Captain was delivered to the fireboat by the
5 Quincy Police boat. He told them about soft patches³³ in the main deck, directly above the
6 engines, that could be opened to fight the fire.
7 Firefighters opened and propped up the soft patch over the port inboard engine, and were able to
8 put out the fire through the access from above. Firefighting efforts filled the engine
9 compartment with water to a height above the tops of the engines, nearly to the main deck
10 level³⁴. Worried about the stability of the vessel, firefighters commenced dewatering, and
11 pumped approximately 5-6 feet of water out of the engine compartment³⁵. When the water was
12 at a safer level, they entered the compartment, checked for hot spots, and provided a re-flash
13 watch³⁶. When the vessel was deemed safe to transport by the Coast Guard, it was towed to Deer
14 Island.

15 Boston Fire Department Marine Unit³⁷

16 Boston Fire Department’s Marine Unit consists of two Fireboats, both located at Burroughs
17 Wharf in the North End of Boston. M/V *Firefighter* is designated as Marine Unit #1. M/V *St.*
18 *Florian* is designated Marine Unit #2.

19 Vessel Characteristics:

20 *Firefighter* *St. Florian*

³² Mackin and Evans interviews
³³ Metal hatches - Steve Bodie interview, 6/15, p 18, line 16-23
³⁴ Chris Mackin interview
³⁵ John Evans interview
³⁶ Re-flash watch consists of firefighters assigned to the fire scene to be prepared to extinguish any subsequent fire outbreaks.

1	Length	76 feet	30 feet
2	Width	20 feet	12 feet
3	Pumping Capacity	6000 GPM	1000 GPM
4	4" hose	1000 feet	100 feet
5	2 ½" hose	1200 feet	200 feet
6	1 ¾" hose	800 feet	300 feet
7	Max speed	9-10 knots	23 knots

8 The *Firefighter* carries 500 gallons of 3% foam, FP-70, discharged through the two forward bow
9 monitors and one forward port side hydrant. Thirteen 5-gallon containers of foam are also
10 carried.

11 *St. Florian* carries two 5-gallon containers of foam.

12 Response Procedures:

13 Boston Fire Department Standard Operating Procedure Number 15 details operations for the
14 Marine Unit. For vessel fires in the outer harbor (beyond Castle Island Terminal) Marine Unit
15 #2 is designated to respond to the location. Marine Unit #1 is to remain in quarters and the Fire
16 Alarm Office will dispatch land companies in accordance with the running card³⁸ to the Marine
17 Unit. Members of the land companies will board Marine Unit #1 with their equipment and then
18 respond to the incident. The designated land companies as specified in Fire Alarm's running
19 card #763 for Boston Outer Harbor, Castle Island to Boston Light, are Engine Company 8 and
20 Ladder Company 1.

21

³⁷ This section comes from Marine Unit SOP
³⁸ Boston Fire Department's SOP outlining guidance for dispatch personnel, as to where equipment and personnel will be dispatched to fires in a particular area of the city's jurisdiction.

1 Firefighting Equipment

2 As required by Coast Guard regulations, the *Massachusetts* carried approved firefighting
3 equipment on board at all times. The vessel was equipped with one B-I portable fire
4 extinguisher, stored at the operating station, and six B-II portable fire extinguishers stored
5 throughout the ship. Two of the B-II portable extinguishers were mounted in the engine room.
6 The vessel had 2 fire pumps, located in the engine room. The pumps were capable of providing
7 a stream of water to any space on the ship by way of two fire stations, each containing a 50-foot,
8 1 ½ inch hose with a firefighting nozzle. The vessel also carried one fire axe.

9

10 Fixed Firefighting Regulations

11 When the *Massachusetts* began operating, there was one set of regulations for all small
12 passenger vessels. Subchapter T regulated all vessels under 100GT carrying more than 6
13 passengers for hire. This subchapter had minor distinctions for larger vessels of greater than 65
14 feet carrying one or more passengers, called subchapter T-L vessels. In 1996, a complete
15 overhaul to the regulations governing small passenger vessels (vessels under 100 GT, carrying
16 more than 6 passengers for hire) went into effect. One of the notable changes was the
17 implementation of more stringent requirements regarding fixed fire detection and extinguishing
18 systems. A separate subchapter for regulations pertaining to vessels like the *Massachusetts* that
19 carry more than 150 passengers was also created in 46 CFR Subchapter K.
20 Subchapter K fire protection equipment regulations are applicable to all vessels built on or after
21 March 11, 1996. An existing vessel³⁹ with a hull or machinery space boundary made of wood or
22 fiber reinforced plastic (FRP) had to comply with these regulations by March 11, 1999. The

³⁹ Not a new vessel. New vessel is defined in 46 CFR 114.400

1 Coast Guard viewed vessels with hulls made of combustible materials such as FRP and wood to
2 be in a higher risk category, hence, they were required to retrofit their vessels with fixed fire
3 extinguishing and detecting systems⁴⁰. Because it was constructed prior to the updated
4 regulations and because it has an aluminum hull, *Massachusetts* is grandfathered, and not subject
5 to the new fire protection equipment requirements. Regarding fire detection and suppression
6 systems, the *Massachusetts* is considered an existing vessel and is required to comply with the
7 fire protection equipment regulations applicable to the vessel on March 10, 1996. These
8 regulations do not require a fixed firefighting system or a means for detecting fire. The
9 applicable regulations only require fixed extinguishing systems in machinery and fuel tank
10 spaces of vessels using gasoline or other fuel having a flash point of 110 degrees F or lower⁴¹.
11 New vessels⁴², built after March 10, 1996, on the other hand, are required to be equipped with a
12 fixed gas fire extinguishing system and a fire detecting system for any spaces containing
13 propulsion machinery⁴³.
14 Forty-nine passengers is one of the regulatory breakpoints used by the Coast Guard. Vessels that
15 carry over 49 passengers fall under stricter regulations for several items, including fire pumps,
16 and bilge pumps.

17

18 SMALL PASSENGER VESSEL STATISTICS

19 Using data pulled from the Coast Guard's Marine Information for Safety and Law Enforcement
20 application, it was determined that there are approximately 416 vessels operating today that are
21 subject to Subchapter K regulations based on passenger capacity (>150 passengers). Of this

⁴⁰ Federal Register, Vol. 59, 1/13/94, p.2046

⁴¹ Old T regs, 46 CFR 181.20-1, p 223

⁴² Definition of New Vessel found 46 CFR 114.400

⁴³ 46 CFR Subchapter K, 118.400 (a) & (c)

1 total, 331 vessels were built in 1996 or earlier and therefore would fall under the old fire
2 protection regulations. Seven of these vessels had wooden hulls and would have been required
3 to meet the new regulations by March 11, 1999⁴⁴. This leaves a total of 324 Subchapter K
4 vessels operating today that are not required to have fixed firefighting in spaces containing
5 propulsion machinery.

6

7 TESTS

8 Examination of engine components has been conducted at NTSB laboratories. The port inboard
9 propulsion engine #3 injector fuel supply line found disconnected during the onscene phase of
10 the investigation was examined to assess whether it was disconnected due to thread failure,
11 engine vibration, some other mechanical factor, or possibly to substantiate failure of the
12 mechanic to connect the fitting to its mating surface during the time he worked on the engine
13 previous to the fire.

14 The same engine's inboard cylinder bank turbocharger was examined to establish the reason for
15 the turbochargers compressor side pronounced leading edge blade erosion, whether due to being
16 struck by particles of some type, or whether it is due to excessive heat.

17 A lab exam factual report of the findings will be distributed to parties as it becomes available.

18

19 FIRE GROUP FACTUAL DOCUMENTATION

20 See attached fire group factual report file titled "Fire Factual Final"

⁴⁴ Fire protection regulations were retroactive for wood or fiberglass vessels. 46 CFR 118.115(b)