

SERVED: March 7, 2016

NTSB Order No. EA- 5772

UNITED STATES OF AMERICA
NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C.

Adopted by the NATIONAL TRANSPORTATION SAFETY BOARD
at its office in Washington, D.C.
on the 4th day of March, 2016

_____)	
MICHAEL P. HUERTA,)	
Administrator,)	
Federal Aviation Administration,)	
)	
Complainant,)	
)	Docket SE-19747
v.)	
)	
MATT LAWSON,)	
)	
Respondent.)	
)	
_____)	

OPINION AND ORDER

1. Background

Respondent appeals the oral initial decision of Administrative Law Judge Stephen R. Woody, issued June 11, 2015.¹ By that decision, the law judge determined the Administrator

¹ A copy of the law judge’s initial decision, an excerpt from the hearing transcript, is attached.

proved respondent violated 14 C.F.R. §§ 43.9(a)(3),² 43.12(a)(1),³ 43.13(a) and (b),⁴ and 43.15(a)(1)⁵ when he performed improper maintenance on a Cessna model CE-172E, made false entries in the aircraft's maintenance logbook and associated FAA forms, and certified the aircraft was airworthy following an annual inspection when the aircraft was not airworthy. We deny respondent's appeal of the Administrator's emergency order of revocation.⁶

A. *Facts*

Respondent, who has been working on and operating aircraft since 1967, held a mechanic certificate with airframe and powerplant ratings, as well as an inspection authorization, before the Administrator's emergency revocation action. Respondent owns Lawson Aviation, where he alters Cessna 172s by putting float kits on them, as well as performing a variety of other

² Section 43.9(a)(3) requires each person who performs maintenance on an aircraft must make an entry in the maintenance record of that equipment containing the name of the person performing the work if other than the person approving for return to service the work performed.

³ Section 43.12(a)(1) states, "[n]o person may make or cause to be made ... [a]ny fraudulent or intentionally false entry in any record or report that is required to be made, kept, or used to show compliance with any requirement under this part."

⁴ Section 43.13(a) requires each person performing maintenance on an aircraft shall use the methods, techniques, and practices prescribed in the current manufacturer's maintenance manual or Instructions for Continued Airworthiness prepared by the manufacturer, or other methods, techniques, and practices acceptable to the Administrator. Paragraph (b) of the section requires each person performing maintenance on an aircraft must do the work in a manner and use materials of such a quality that the condition of the aircraft or part on which he or she works will be at least equal to its original or properly altered condition.

⁵ Section 43.15(a)(1) provides each person performing an inspection required by 14 C.F.R. parts 91, 125, or 135 must perform the inspection so as to determine whether the aircraft (or portions thereof under inspection) meets all applicable airworthiness requirements.

⁶ The Administrator initiated this case as an emergency under 49 U.S.C. §§ 44709 and 46105(c). Respondent subsequently waived the expedited procedures normally applicable to emergency cases for the purposes of this appeal.

structural repairs. Respondent completes approximately 12 FAA Form 337s (titled, “Major Repair and Alteration (Airframe, Powerplant, Propeller, or Appliance)”) per year.⁷

The owner of a Cessna CE-172E (hereinafter, N5683T) requested respondent’s alteration of the aircraft by placing a float kit on the aircraft and performing other work. In March 2011, respondent discussed major alterations he wanted to perform on N5683T with FAA Aviation Safety Inspector Daniel Moore. In particular, respondent and Inspector Moore discussed an engine and propeller installation. Respondent submitted a Form 337 to Inspector Moore, which described installation of a G model engine and a 78-inch propeller. Inspector Moore did not approve the form, due to insufficient technical data to support the major alterations. Respondent and Inspector Moore corresponded further, after which Inspector Moore assisted respondent with drafting a new Form 337 that referenced certain data in Block 8 of the form (titled, “Description of Work Accomplished”).⁸ Respondent submitted data to support the alteration, including Supplemental Type Certificate (STC) SA00728SE, which contains the Administrator’s approval for a type design change permitting the installation of certain Continental IO360 engine models for various Cessna model aircraft. On July 22, 2011, Inspector Moore signed the Form 337, approving installation of a Model IO-360-G (“G model engine”), and a 78-inch propeller, in accordance with STC SA00728SE. The only approved deviation from STC SA00728SE noted on the Form 337 was the propeller size would be 78 inches, in lieu of 76 inches, as the STC required.⁹ On December 26, 2012, respondent signed the form, certifying he had performed the work listed in Block 8, as described.

1. *Logbook Entries*

⁷ FAA Form 337 is available at http://www.faa.gov/documentLibrary/media/Form/Form_337.pdf.

⁸ Exh. A-2 (hereinafter “337(I)”).

⁹ Exh. A-2 at 2.

On December 20, 2012, respondent made a logbook entry in the maintenance records for N5683T, in which he certified the aircraft “had been inspected in accordance with [an] annual inspection and determined to be in an airworthy condition this date 12-20-12”¹⁰ Respondent also made entries in the maintenance logbook stating he:

- Installed a Continental engine model IO-360-G in accordance with STC SA00728SE and field approval dated July 22, 2011;
- Installed an oil pressure and oil temperature gauge in accordance with another STC;
- Repaired the lower firewall using parts from an aircraft of the same year and model;
- Installed a floatplane kit in accordance with Cessna drawing 0500044;
- Installed a tail cone removed from an aircraft of the same year and model;
- Complied with 14 C.F.R. § 91.207¹¹; and
- Reassembled, rigged, and test flew the aircraft.

2. *FAA Form 337s*

Respondent also completed four FAA Form 337s, certifying the work specified above, as well as additional work. On Form 337(I), as described above, respondent certified: the removal of the aircraft’s original engine, propeller, and firewall forward; the installation of a McCauley propeller; an increase in the size of the propeller diameter from 76 inches to 78 inches; the insertion of a supplemental document into the aircraft flight manual; and the performance of a functional flight test. On Form 337(II), respondent certified his replacement of the lower firewall and tail cone with parts from “same model aircraft”; the placement of a fixture to assure alignment of the fuselage and tail cone; and that he completed these alterations in accordance

¹⁰ Exh. A-1 at 2 (photograph of logbook, showing stamp respondent placed below notes, filled in the blanks shown in underline above, and signed adjacent to his certificate number).

¹¹ Section 91.207 sets forth requirements applicable to emergency locator transmitters.

with the applicable Cessna manual and “FAR AC 43.1&2.”¹² Form 337(III) included respondent’s certification that he installed an oil pressure and temperature kit including instrument, oil temperature sensor, and oil pressure sensor pursuant to an applicable STC. Finally, Form 337(IV) stated respondent installed a floatplane reinforcement kit pursuant to an applicable Cessna drawing and “AC 43-13-1&2.”¹³

Forms 337(II)-(IV) did not require additional “field” approval from Inspector Moore, because respondent was to perform the work described without any deviation from the approved data cited on the forms. Respondent obtained such approval from Inspector Moore for the work described in Form 337(I) because he intended to install a 78-inch, rather than a 76-inch, propeller on the aircraft, pursuant to his plans to install the floatplane kit.

3. *Discrepancies*

Over a year after respondent’s made his logbook entries and completed the aforementioned Form 337s, a different repair station performed an annual inspection of N5683T and contacted the FAA after inspecting the aircraft and reviewing the aircraft’s records. Staff at the repair station reported several discrepancies. Principal Maintenance Inspector Randy Steffes, of the FAA Flight Standards District Office in Grand Rapids, Michigan, conducted an inspection on March 21, 2014, and noted 21 discrepancies on the aircraft.

Among others, the discrepancies included: the use of an erroneous placard, which did not accurately identify the engine model used; an incorrect tail cone, which was not from the same model Cessna as N5683T, and therefore contained rivet holes that did not align; installation of rivets for the lower firewall that were aluminum, rather than stainless steel, as the Cessna 100 Series Structural Repair Manual required; no use of sealant for new lower firewall rivets;

¹² Exh. A-3 at 2.

¹³ Exh. A-5 at 2.

brackets on the tail cone and lower firewall that were damaged and, on the lower firewall, were incorrectly installed; installation of a floatplane/seaplane kit that was not in accordance with an STC that had been certified; installation of an 80-inch propeller, in violation of the previously-approved deviation (which permitted a 78-inch propeller); the lack of an alternator noise filter installed in accordance with the applicable STC instruction; the lack of a correctly installed fuel pump switch, which should have been located on the throttle arm of the throttle body; incorrectly installed oil pressure restrictor fitting, alternate air cable and spring-loaded alternate air door; the lack of required markings on engine instruments and the lack of a placard indicating sea level to altitude gallons per hour; and the substitution of an off-on switch for fuel pump, in lieu of the required HI-OFF-LOW switch.

Upon Inspector Steffes's inspection of N5683T, he determined it was not airworthy.¹⁴ Although respondent completed the records on the aircraft in December 2012 and Inspector Steffes inspected the aircraft in March 2014, Inspector Steffes noted no changes to the aircraft had occurred during the 15-month time period.¹⁵ After issuing a letter of investigation (LOI) on March 21, 2014, which contained an incorrect registration number for the aircraft, then issuing an amended LOI on March 24, 2014, Inspector Steffes met with respondent to discuss the discrepancies. Inspector Steffes testified respondent did not reply when Inspector Steffes inquired about what approved data respondent had used for many of the alterations. Respondent admitted he was aware the 80-inch propeller was on the aircraft. In response to Inspector Steffes's question about why the data plate indicated the engine was for a K model, respondent

¹⁴ Tr. 119, 167; Initial Decision at 418.

¹⁵ Tr. 113. Inspector Steffes noted the aircraft's maintenance logbook would have included entries if another mechanic had altered the aircraft. But see tr. 258 (respondent's testimony that, following his work on the aircraft, he recalled seeing the aircraft in Michigan and he noticed the installation of a new intercom system and a new interior in the aircraft).

said he must have overlooked it, and that a K model fuselage on an E model Cessna was appropriate, because “they’re all the same.”¹⁶ Respondent acknowledged the riveting on the fuselage was weak. Respondent also recalled he did not review the information Inspector Moore had included in Block 8 before completing the work, because the owner of N5683T took the form to keep with his records. Respondent did, however, receive the form and reviewed it before signing it.¹⁷

On April 7, 2014, respondent submitted a report to the National Aeronautics and Space Administration (NASA), under the Aviation Safety Reporting Program (ASRP), to disclose the discrepancies.¹⁸ Respondent sought to “tell his side of the story” in the report.¹⁹ He also testified he had no motive to falsify any of the records at issue.

B. Procedural Background

On December 9, 2014, the Administrator issued an emergency order revoking respondent’s Mechanic Certificate with Airframe and Powerplant ratings and Inspection Authorization. The order, which became the complaint in this case, alleged respondent violated 14 C.F.R. §§ 43.9(a)(3), 43.12(a)(1), 43.13(a) and (b), 43.15(a)(1), 91.403(d),²⁰ and that he

¹⁶ Tr. 116, 182, 349.

¹⁷ Tr. 262-63, 280-81.

¹⁸ Exh. R-11. Under the ASRP, the Administrator may waive the imposition of a sanction, despite the finding of a regulatory violation, as long as certain requirements are satisfied. Aviation Safety Reporting Program, Advisory Circular 00-46E at 4, ¶ 9c (December 16, 2011). The Program involves filing a report with NASA, which may obviate the Administrator’s imposition of a sanction where: (1) the violation was inadvertent and not deliberate; (2) the violation did not involve a criminal offense, accident, or action found at 49 U.S.C. § 44709; (3) the person has not been found in any prior FAA enforcement action to have committed a regulatory violation for the past five years; and (4) the person completes and mails a written report of the incident to NASA within 10 days of the violation.

¹⁹ Tr. 256.

²⁰ Section 91.403(d) prohibits alteration of an aircraft based on an STC unless the owner or operator of the aircraft holds the STC, or has written permission from the holder of the STC. The

lacked the qualifications necessary to hold a mechanic certificate. Respondent waived the applicability of the emergency procedures, and the case proceeded to hearing before the law judge on June 9 and 10, 2015. The law judge issued an oral initial decision the day after the conclusion of the hearing.

C. Law Judge's Oral Initial Decision

The law judge affirmed the majority of the Administrator's complaint. In his decision, he credited the testimony of Inspectors Moore and Steffes, especially with regard to the materiality of the maintenance records at issue. The law judge made specific, individual findings regarding each instance of intentional falsification contained in the Administrator's complaint. The law judge determined the Administrator failed to prove six of the 21 alleged discrepancies, and did not prove respondent violated 14 C.F.R. § 91.403(d), as charged. The Administrator did not appeal the law judge's findings; hence, this Opinion and Order does not address the charges the Administrator failed to prove.

Regarding the portions of the complaint the law judge affirmed, he determined the Administrator proved all three elements of the Hart v. McLucas standard for falsification. Under Hart v. McLucas, the Administrator must prove an airman: (1) made a false representation, (2) in reference to a material fact, and (3) with knowledge of the falsity of the fact.²¹ In this regard, the law judge made the following specific findings:

- The data plate for the engine clearly identified a K model engine, or a G model converted to a K model; however, both the maintenance entry in the logbook as well as the Form 337(I) concerning the installation of an IO-360-G model engine was not consistent with the data plate. As a result, the entry was intentionally false.²²

law judge determined the Administrator's evidence was insufficient to prove respondent lacked permission from the owner of N5683T to alter the aircraft in accordance with the STC.

²¹ Hart v. McLucas, 535 F.2d 516, 519 (9th Cir. 1976); see also Initial Decision at 437.

²² Initial Decision at 438.

- Respondent installed an 80-inch propeller, contrary to the “plain language” on Block 8 of Form 337(I), which permitted a 78-inch propeller.²³ Respondent signed the Form 337, to certify his compliance with the terms of Block 8. This was an intentional falsification.²⁴
- Respondent’s replacement of the tail cone for the aircraft was inappropriate, because he replaced the tail cone from a Cessna 172K in N5683T, which is a Cessna 172E. Respondent’s completion of the Form 337(II) in this regard, therefore, constitutes a false entry, in violation of § 43.13. However, respondent’s understanding that the different models’ tail cones were interchangeable shows a lack of knowledge of the falsity; therefore, the Administrator did not prove a violation of § 43.12(a)(1) in this regard.²⁵
- Respondent’s maintenance record entry concerning rivets on the firewall was false, and his work on it was not consistent with the structural repair manual requirements, because the rivets were aluminum, not stainless steel.²⁶
- Respondent’s entry on Form 337(III) concerning installation of the oil pressure sensors and temperature kit was intentionally false, because respondent affixed the sensors directly at the engine and mounted gauges in the cockpit in a location not visible to the pilot. These alterations did not comply with the applicable STC requirement; therefore, respondent’s certification on the 337 form, indicating compliance with the terms of the form and applicable STC, was intentionally false.²⁷
- Respondent’s entry on Form 337(IV) regarding installation of a floatplane reinforcement kit contained falsified information, because respondent certified compliance with the Form 337 when the kit was not installed in accordance with the Cessna drawing referenced in the form.²⁸
The law judge further affirmed various other portions of the Administrator’s complaint.²⁹

For example, he found respondent did not install an oil pressure restrictor fitting, nor did he install an alternate air cable and spring-loaded alternate air door. He also installed an incorrect switch for the fuel pump and did not mark engine instruments appropriately. Therefore, the law

²³ Initial Decision at 439; Exh. A-2.

²⁴ Initial Decision at 440.

²⁵ Id. at 443.

²⁶ Id. at 443-44.

²⁷ Id. at 445.

²⁸ Id. at 446.

²⁹ Id. at 449.

judge found respondent intentionally falsified the aircraft's maintenance logs in indicating he had performed the work in accordance with the relevant requirements and that the aircraft was airworthy when he returned it to service.

The law judge also discussed respondent's affirmative defenses. The law judge held the Board's stale complaint rule did not apply to require dismissal of the Administrator's complaint, because the complaint alleged respondent lacked the qualifications necessary to hold a mechanic certificate. The law judge also found respondent did not articulate a rationale for his argument that the doctrine of laches required dismissal of the case, notwithstanding respondent's listing of the defense in his answer. The law judge found respondent's failure to establish he suffered actual prejudice precluded the defense.

Finally, the law judge discussed the appropriateness of the sanction of revocation. The law judge found respondent's falsification and failure to ensure the accuracy of the maintenance records at issue indicated respondent lacks the necessary care, judgment, and responsibility to hold a certificate. The law judge determined respondent's filing of a report with NASA under the ARSP did not apply to obviate the imposition of a sanction, because he filed it more than 10 days after he was aware of the alleged violations; respondent met with Inspector Steffes and received the amended LOI on March 24, 2014, yet he filed the NASA report on April 7, 2014. Therefore, the law judge found respondent failed to show he fulfilled all four prongs of the ARSP standard.

D. Issues on Appeal

Respondent contends the law judge erred in determining respondent falsified the maintenance entries. First, respondent asserts FAA inspectors never saw the aircraft at the time he inspected it; respondent argues, under Board jurisprudence, the Administrator's charge

against him concerning the annual inspection entry—in which he certified the aircraft was airworthy—is deficient.

Concerning specific maintenance-related charges, respondent contends:

- The Administrator did not prove respondent’s description of the K model engine was erroneous, because he simply used the engine case from a K model, while the actual engine was a G model. Respondent further contends Inspector Moore led him to believe a field approval had been issued to cover the entire engine and propeller installation; respondent cites previous Board cases to show the Administrator’s staff’s implications are relevant to an intentional falsification charge. Respondent also asserts any deviations from the STC insofar as they relate to field approvals were not required to be described in the maintenance records, because the absence of a record does not amount to intentional falsification.
- An expert witness who testified during respondent’s case-in-chief opined installation of an 80-inch propeller for a seaplane configuration on a Cessna 172 was appropriate.
- Respondent’s replacement of the tail cone for the aircraft, which he acknowledges contained a data plate indicating the tail cone was from a Cessna 172K, was acceptable because a Cessna 172K is sufficiently similar to a Cessna 172E.
- Use of aluminum rivets, rather than stainless steel, is acceptable to Cessna; respondent asserts mechanics frequently use aluminum rivets.
- The STC that applied to the engine and propeller installation did not address the installation of an electronic oil pressure system; however, the Administrator charged respondent with failing to install the oil pressure restrictor fitting in accordance with the engine/propeller STC instruction.
- Respondent did not falsify Form 337(IV), regarding installation of a floatplane reinforcement kit.³⁰

Respondent asserts, overall, he did not falsify the records as charged, mainly because Inspectors Moore and Steffes did not communicate concerning the field approval process. Respondent argues the STC the inspectors claimed he did not follow was unavailable, and Inspector Moore drafted the text of Block 8 in Form 337(I), which contains the basis for many of

³⁰ Respondent’s appeal brief contains a general statement that he did not falsify any Form 337s. Appeal Br. at 19. The brief does not contain assertions specific to the Administrator’s contention that he intentionally falsified a certification of a floatplane reinforcement kit because he failed to install the kit fully in accordance with the Cessna drawing referenced in the form.

the charges in the Administrator's complaint. Respondent argues he performed the modifications in accordance with the plans he discussed with Inspector Moore and that he did not intend to falsify any records.

Lastly, respondent renews his arguments concerning the stale complaint rule, the sanction, and the applicability of the ASRP. Respondent cites Administrator v. Tarascio³¹ for the notion that the time that passed between the Administrator's discovery of the violations in the case *sub judice* and the pursuit of the charges against him indicates the complaint was stale. He also argues revocation is excessive because Inspector Moore was principally involved in the confusion of the applicable STCs' requirements. Finally, respondent argues his NASA report was timely because he was unaware of which allegations the Administrator sought to pursue against him until the meeting he had with Inspector Steffes on April 2 or 4, 2014; therefore, he contends he is eligible for a waiver of sanction under the ASRP because the report was timely, notwithstanding the fact that he received the first LOI on March 21, 2014, followed by the amended LOI, dated March 24, 2014.

2. Decision

On appeal, we review the law judge's decision *de novo*, as our precedent requires.³²

A. Intentional Falsification and Failure to Comply with Acceptable Standards

³¹ NTSB Order No. EA-5116 at 7 (2004) (citing Administrator v. Alvarez, 5 NTSB 1906 (1987), and stating, "[i]n our view, since the allegation of false entries was unsustainable on its face, in light of Alvarez, no issue of lack of qualification was presented and the law judge was thus free to determine whether the Administrator had taken more than six months to bring the airworthiness and carelessness charges").

³² Administrator v. Smith, NTSB Order No. EA-5646 at 8 (2013), Administrator v. Frohmuth and Dworak, NTSB Order No. EA-3816 at 2 n.5 (1993); Administrator v. Wolf, NTSB Order No. EA-3450 (1991); Administrator v. Schneider, 1 N.T.S.B. 1550 (1972) (stating, in making factual findings, the Board is not bound by the law judge's findings).

With regard to the issue of intentional falsification, we long have adhered to a three prong test. The Administrator must prove an airman: (1) made a false representation, (2) in reference to a material fact, and (3) with knowledge of the falsity of the fact.³³

1. *Logbook Entries*

Respondent does not dispute he certified N5683T as airworthy in the aircraft's logbook on December 20, 2012. However, the evidence establishes the aircraft was not airworthy at the time of the annual inspection.³⁴ In addition to its lack of compliance with its STCs, the aircraft also contained numerous discrepancies that left it in a condition that was not safe for operation. For example, respondent used aluminum rivets on the engine's firewall, did not completely line up the rivets in the tail cone area, did not use an appropriate type of sealant for new lower firewall rivets he installed, and cut his own brackets for lower firewall installation. In addition, respondent did not install an oil pressure restrictor fitting, nor did he install an alternate air cable and spring-loaded alternate air door. He also installed an incorrect switch for the fuel pump and did not mark engine instruments appropriately. All these discrepancies are inconsistent with either Cessna's maintenance guidelines in the Cessna 100 Series Structural Repair Manual or data supplied for applicable STCs. Such a lack of consistency constitutes non-conformity with the aircraft's type design and amounts to a violation of 14 C.F.R. § 43.13(a) and (b).

³³ Hart v. McLucas, *supra* note 21.

³⁴ Under longstanding Board jurisprudence, in order to be considered airworthy, an aircraft must both (1) fulfill the criteria established by its type certificate; and (2) be in a condition for safe operation. Administrator v. Surratt and Walkers, NTSB Order No. EA-5514 at 6 (2010) (citing Administrator v. Anderson, NTSB Order No. EA-3976 at 2 (1993); Administrator v. Nielsen, NTSB Order No. EA-3755 at 4 (1992); Administrator v. Copsey, 7 NTSB 1316, 1317 (1991); and Administrator v. Doppes, 5 NTSB 50, 52 n.6 (1985)). An STC functions to supplement or amend an aircraft's type design, in accordance with FAA authorization. Administrator v. Smith, NTSB Order No. EA-5646 at 5, 9 (2013).

In addition to erring in determining the aircraft was airworthy, respondent's logbook entries also did not accurately describe the work he performed. The fact that respondent placed a data plate indicating a K model engine was aboard the aircraft, rather than the Continental 10-360-G model engine listed in the logbook and required by the applicable STC, amounts to an intentional falsification. The data plate was incorrect, and even if respondent believed it would be acceptable to use the casing from a different model engine, he still did not provide the appropriate data or document his activities in the logbook to explain the true type of engine to the FAA or mechanics who might later work on the aircraft. This erroneous, incomplete entry was material, because it would undoubtedly affect decisions inspectors, mechanics, or operators might make concerning work on the aircraft. As Inspector Steffes explained, a few prominent differences among a G model and a K model engine exist: the engines maintain different levels of horsepower, oil capacity, and operating ranges.³⁵

Logbook entries such as those mentioned above contain information that is material to the Administrator's inspectors' assurance that the aircraft is airworthy and to the assessments and determinations mechanics in the future may make concerning work on the aircraft. Respondent's entry in the logbook indicates he intended to certify the aircraft was airworthy, yet the aircraft maintained numerous discrepancies and did not comply with the documents, such as STCs, airworthiness directives, and a Cessna drawing, all of which respondent referenced in the logbook. As a result, with regard to the logbook entries, the Administrator presented ample evidence to establish respondent intentionally falsified the entries he made. Moreover, respondent's entries, combined with his testimony concerning several of the discrepancies,

³⁵ Tr. 119-120. Inspector Steffes further explained, "[t]he type of certificate number for a 172E is an A-12; the type certificate data sheet for a K model is A-7. Obviously there's enough of a difference between the two that it requires an entirely different type certificate." Tr. 123.

unequivocally shows respondent did not perform the work pursuant to the methods, techniques, and practices established by the manufacturer and/or acceptable to the Administrator. Overall, reviewing the logbook alone establishes the Administrator proved respondent violated 14 C.F.R. §§ 43.12(a)(1), 43.13(a) and (b), and 43.15(a)(1).

2. *FAA Form 337 and STCs*

A mechanic must have approval to deviate from the terms of an STC; without prior approval, the deviation amounts to a lack of adherence to the aircraft's type design, thereby rendering it unairworthy. Respondent's choice to install an 80-inch, rather than 78-inch, propeller on the aircraft was an admitted deviation from the applicable STC. Respondent acknowledges he did not obtain approval for this deviation from the Administrator.³⁶ Hence, his placement of an 80-inch propeller, in lieu of a 78-inch propeller, resulted in the aircraft not complying with its type design (as amended by the STC), and therefore not being airworthy. Accordingly, respondent's certification of the aircraft as airworthy in the maintenance logbook, as well as signing the appropriate Form 337 indicating compliance with the terms of the Form 337—in particular, those listed in Block 8 of the form—amounted to an intentional falsification. In this regard, Block 8.D. includes the following certification:

I certify that the repair and/or alteration made to the unit(s) identified in item 5 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.³⁷

³⁶ See tr. 265, 269; see also tr. 174 (Inspector Steffes testimony that a mechanic must obtain approval to deviate from an STC, and no such approval occurred here).

³⁷ Exh. A-2 at 2.

The evidence establishes respondent knew the 80-inch propeller was not approved.³⁸ In addition to respondent's deliberate choice to install the 80-inch propeller, we note the accuracy of records concerning the correct size propeller is material to the maintenance of the aircraft. Hence, the Administrator established all three prongs of the intentional falsification standard, as well as proving respondent failed to use the methods, practices, and techniques acceptable to the Administrator with regard to the installation of the propeller.

Likewise, installing a K model engine in N5683T was impermissible under the applicable STC. As indicated in the analysis above, respondent's entries in *both* the maintenance log³⁹ and his completion of the STC⁴⁰ concerning the engine model were false. Respondent informed Inspector Steffes that all engines were essentially the same, and leaving a data plate indicating a K model on an engine that was not a K model was simply an oversight.⁴¹ Notwithstanding respondent's assessment that the models were indistinct, respondent was evasive in response to questions concerning his awareness that the alteration did not comply with the appropriate STC. Respondent opined, "I guess some of the old brochures on this that I had back in 2004 saying it was A, C, D, F, G, GB, HB, KB, K, all those were approved. I don't know where anybody got the idea that K couldn't be used."⁴² We find, based on respondent's apparent unwillingness to consult the STC in order to ensure he replaced the engine in an appropriate manner and used an accurate

³⁸ Tr. 116, 182 (Inspector Steffes's testimony, recalling respondent told Inspector Steffes that he was aware the 80-inch propeller was on the aircraft), 222 (respondent's testimony, in which he admitted he instructed the owner of N5683T to refrain from operating the aircraft with the 80-inch propeller until respondent completed more work on it, such as attaching the floats).

³⁹ Exh. A-1 at 1.

⁴⁰ Exh. A-2 at 2.

⁴¹ Tr. 116.

⁴² Tr. 209.

data plate, combined with the law judge's credibility finding adverse to respondent,⁴³ establishes respondent intentionally falsified the logbook record indicating he had installed a Continental 10-360-G model engine in accordance with the STC.

The record contains additional evidence showing respondent certified compliance with STCs regarding his installation of an oil pressure temperature system, yet the work did not adhere to the STC. Respondent was uncertain as to which potentially applicable STCs applied, but when Inspector Steffes inspected the aircraft he found the work did not adhere to any applicable STC. Concerning the oil pressure temperature system, he could discern immediately that the oil pressure gauge was mounted in an incorrect location.⁴⁴

As stated above, the FAA must approve any deviation from the requirements of an applicable STC. Respondent did not obtain such approval with regard to the oil pressure temperature system but he signed a Form 337 to certify he correctly installed the oil pressure and temperature kit including instrument, oil temperature sensor, and oil pressure sensor, all pursuant to an applicable STC. The precise installation of the oil pressure temperature system is material to the safe operation of the aircraft; hence, the need for adherence to the STC concerning its installation. In particular, Inspector Steffes confirmed the installation of the oil and temperature pressure gauge sensor directly affects the engine of the aircraft because "if the sensor fails or it breaks right up there at the elbow [where respondent installed it], you have no restriction of the

⁴³ The law judge stated:

I found Mr. Lawson's testimony that the engine was, in fact, a G model engine and he had simply failed to appropriately stamp the data tag to be less than credible. Thus, I find that the preponderance of evidence establishes not only that the entry was false but that Respondent knew it was false at the time that he made the logbook entry and signed off on the Form 337.

Initial Decision at 438.

⁴⁴ Tr. 109, 161-62.

oil escaping and flowing out of the engine.”⁴⁵ Respondent was aware he needed to comply with the STC in installing the system, yet he elected to refrain from doing so.

With regard to the tail cone installation, respondent certified in the logbook that his replacement of the lower firewall and tail cone with parts from “same model aircraft,” and stated he had placed a fixture to assure alignment of the fuselage and tail cone.⁴⁶ Respondent also certified he completed these alterations in accordance with the applicable Cessna manual FAA Advisory Circular. However, the placard on the tail cone indicated the part was from a Cessna 172K, rather than a 172E. Respondent asserts the difference is inconsequential. However, the record establishes the work he completed was unacceptable because the accuracy of the listing of the correct aircraft model number on the placard for the tail cone is critical for maintenance considerations.⁴⁷

Our affirmation of the law judge’s determination concerning the tail cone is relevant to paragraph 16(d) of the Administrator’s complaint, which states, “the maintenance log for N5683T Forms 337 referenced ... [t]he tail cone installed was not from an aircraft of the same model as N5683T, as the tail cone placard indicated it was from a Cessna R172K with a Serial Number 17257583, therefore the rivet holes did not align.”⁴⁸ We reject respondent’s argument that the difference is inconsequential, because accuracy of data plates is critical to compliance with the provisions of 14 C.F.R. part 43.⁴⁹

⁴⁵ Tr. 124.

⁴⁶ Exh. A-1.

⁴⁷ Tr. 210. As described above, the law judge found the Administrator did not prove a violation concerning of the regulations, as charged, concerning the installation of the tail cone with regard to Form 337(II). Initial Decision at 452. The Administrator did not appeal this finding.

⁴⁸ Compl. at ¶ 16(d); Initial Decision at 453.

⁴⁹ See, e.g., Administrator v. Potanko, NTSB Order No. EA- 3937 at 9-10 (1993) and Administrator v. Lott, 5 NTSB 2394, 2397 (1987), in which the Board stated, “the true identity

As with the logbook, we find the evidence establishes the certifications on the Form 337s themselves show the Administrator proved respondent violated 14 C.F.R. §§ 43.12(a)(1), 43.13(a) and (b), and 43.15(a)(1). Respondent did not provide rationale or evidence to establish the law judge erred in determining the Administrator proved the allegations with regard to the Form 337s. To the extent respondent contends he did not need to describe approvals of deviations in the maintenance logs, we disagree, as such approvals are a key component of the airworthiness of the aircraft and maintenance records must be scrupulously accurate.⁵⁰ We affirm the law judge's determinations that respondent's failure to adhere to the STCs and his certification of compliance with the Form 337s constituted both an intentional falsification and a failure to adhere to the methods, techniques, and practices acceptable to the Administrator.⁵¹

B. *Procedural Arguments and Sanction*

1. *Stale Complaint Rule*

Respondent contends the law judge erred in not dismissing the Administrator's complaint pursuant to the Board's stale complaint rule, which is codified at 49 C.F.R. § 821.33.⁵² We

of an aircraft is highly material since it is essential in determining the maintenance, repair and alteration history of that aircraft and its conformity to its type design and applicable airworthiness directives.”). Such logic is also applicable to aircraft components.

⁵⁰ See, e.g., Administrator v. Guerin, NTSB Order No. EA-3827 at 5 (1993) (quoting Administrator v. Morse, NTSB Order No. EA-3766, at 12 (1992), in which the Board stated, “[a]n individual who does not ensure the scrupulous accuracy of his representations in records on which air safety critically depends cannot be said to possess the necessary care, judgment, and responsibility”).

⁵¹ As noted above, the Administrator also charged respondent with violating 14 C.F.R. § 43.9(a)(3) by failing to include an appropriate notation in the logbook to name the person performing work. The law judge affirmed this charge. The parties did not address this charge on appeal. We affirm the law judge's finding that respondent violated § 43.9(a)(3).

⁵² The stale complaint rule provides a respondent may move to dismiss a complaint when the allegations of offenses occurred more than six months prior to the Administrator's advising the respondent as to the reasons for proposed actions. However, the rule also states the six-month rule of limitations does not apply to cases in which the Administrator alleges the respondent's

disagree with respondent's assertion. The complaint at issue clearly alleges a lack of qualifications, on several accounts. As the United States Court of Appeals for the District of Columbia Circuit recently clarified, a falsification charge alone functions to raise a lack of qualifications.⁵³ The Administrator's complaint against respondent alleges not only intentional falsification of critical maintenance records but also contains several detailed allegations with regard to respondent's failure to perform maintenance in accordance with the methods, techniques, and practices suitable to the Administrator.

The Administrator's assertion in the complaint that respondent lacked the qualifications necessary to hold a mechanic certificate was well-founded and based on multiple charges. Unlike Administrator v. Tarascio,⁵⁴ on which respondent relies for his argument that the stale complaint rule requires dismissal of the charges not proven, the charges in the case *sub judice* were indeed sustainable on their face. In addition, in Administrator v. Morse, the Board clearly held a mechanic who does not make accurate logbook entries lacks the care, judgment, and responsibility to hold his mechanic certificate.⁵⁵

The complaint in the case *sub judice* lists myriad charges, all of which indicate a lack of qualifications. Even though the law judge determined the Administrator failed to prove charges concerning installation of the engine mounts, tail cone, and exhaust muffler system, as well as maintenance of the lower firewall rivet edge, the stale complaint rule does not provide for *post*

conduct reflects a lack of qualifications necessary to hold a certificate. In cases where the Administrator alleges a respondent intentionally falsified a document, Board jurisprudence makes clear that such conduct shows, *per se*, that the respondent lacks the qualifications necessary to hold a certificate. Administrator v. Ducote, NTSB Order No. EA-5758 at 3 (2015) (following remand from United States Court of Appeals for District of Columbia Circuit, Huerta v. Ducote and NTSB, 792 F.3d 144 (D.C. Cir. 2015)).

⁵³ Ducote, 792 F.3d at 155; see also NTSB Order No. EA-5758 at 5.

⁵⁴ NTSB Order No. EA-5116 (2004).

⁵⁵ Administrator v. Morse, *supra* note 50 at 12.

hoc application to dismiss the complaint. In this regard, we reject respondent's argument that any of the charges were suitable for dismissal under the stale complaint rule.

2. ASRP

Respondent further contends he is eligible for a waiver of sanction under the ASRP. However, he has failed to fulfill the requirement that he prove all four prongs of the ASRP standard.⁵⁶ Respondent did not file the NASA report until April 7, 2014, even though he had met with Inspector Steffes on March 24, 2014 and discussed the discrepancies with him. Respondent cannot legitimately claim he did not become aware of the discrepancies until April 2 or 4, when he learned the Administrator sought to bring an action against his certificate. Respondent does not dispute the meeting that occurred on March 24, 2014, consisted of a detailed discussion concerning the discrepancies.⁵⁷ FAA Advisory Circular 00-46E provides, to be eligible for a waiver of sanction under the ASRP, respondents must report the violation to NASA "within 10 days after the violation, or date when the person became aware or should have been aware of the violation."⁵⁸ Respondent clearly was aware of the violations at the time of the March 24, 2014 meeting; indeed, Inspector Steffes inspected the aircraft on March 21, 2014, and then immediately began drafting a letter of investigation to deliver to respondent. At a minimum, respondent should have been aware of the violation at the time of the March 24 meeting. Therefore, his April 7, 2014 report to NASA cannot avail him of a waiver of sanction pursuant to the ASRP.

⁵⁶ Supra note 18.

⁵⁷ Tr. 114-18.

⁵⁸ Supra note 18 at 4, ¶ 9(c)(4).

3. *Sanction Determination*

Finally, we also find meritless respondent's argument that the sanction of revocation of his certificate is excessive. Respondent presented several arguments at the hearing and in his appeal brief, in an attempt to explain his various decisions in the maintenance he performed on N5683T. The evidence, however, clearly shows respondent did not comply with applicable STCs and numerous required standards, yet he certified the aircraft as airworthy. Such conduct warrants revocation, because "an individual who does not ensure the scrupulous accuracy of his representations in records on which air safety critically depends cannot be said to possess the necessary care, judgment, and responsibility required of a mechanic."⁵⁹ In this regard, the Administrator relies on the accuracy of maintenance records, because the FAA cannot fulfill its responsibility in promoting aviation safety unless "logbooks are free of knowing misrepresentations of fact."⁶⁰ Respondent's disregard for the adherence to the requisite standards in performing maintenance on N5683T, and his falsification of logbook records, warrants revocation.

ACCORDINGLY, IT IS ORDERED THAT:

1. Respondent's appeal is denied;
2. The law judge's decision is affirmed; and
3. The Administrator's emergency revocation of respondent's Mechanic Certificate with Airframe and Powerplant ratings and Inspection Authorization is affirmed.

HART, Chairman, DINH-ZARR, Vice Chairman, and SUMWALT AND WEENER, Members of the Board, concurred in the above opinion and order.

⁵⁹ Olsen v. NTSB, 14 F.3d 471, 476 (9th Cir. 1994) (quoting Guerin, *supra* note 50); *see also* Morse, *supra* note 50 at 12.

⁶⁰ Cassis v. Helms, 737 F.2d at 545, 547 (6th Cir. 1984).

UNITED STATES OF AMERICA NATIONAL
TRANSPORTATION SAFETY BOARD OFFICE
OF ADMINISTRATIVE LAW JUDGES

* * * * *

In the matter of: *

MICHAEL P. HUERTA, *
ADMINISTRATOR, *
FEDERAL AVIATION ADMINISTRATION, *

Complainant, *

v. *

Docket No.: SE-19747
JUDGE WOODY

MATT LAWSON, *

Respondent. *

* * * * *

Kluczynski Federal Building
230 South Dearborn Street
Courtroom 3908
Chicago, Illinois

Thursday,
June 11, 2015

The above-entitled matter came on for hearing, pursuant
to Notice, at 2:00 p.m.

BEFORE: STEPHEN R. WOODY
Administrative Law Judge

APPEARANCES:

On behalf of the Administrator:

LAUREN HOYSON, Esq.
Federal Aviation Administration
Great Lakes Region
Office of the Regional Counsel
2300 East Devon Avenue
Des Plaines, Illinois 60018
(847) 294-7165
lauren.hoyson@faa.gov

On behalf of the Respondent:

DERRICK J. HAHN, Esq.
Hahn Law Firm, P.C.
900 Jackson Street, Suite 180
Dallas, Texas 75202
(214) 744-3200
dhahn@hahnlawfirm.com

1

2

3

4

5

ORAL INITIAL DECISION

6 ADMINISTRATIVE LAW JUDGE WOODY: This is a proceeding
7 under the provisions of 49 U.S.C. Section 44709, and the
8 provisions of the Rules of Practice in Air Safety Proceedings of
9 the National Transportation Safety Board. This matter has been
10 heard before this Administrative Law Judge. As provided by the
11 Board's rules, I have elected to issue an oral initial decision in
12 this matter.

13 Pursuant to notice, this matter came on for hearing on
14 June 9th through 11th, 2015, in New York City [sic]. The
15 Administrator is represented by staff counsel, Ms. Lauren Hoyson,
16 Esquire, of the FAA Great Lakes Region Regional Counsel's Office.
17 Respondent was represented by Mr. Derrick Hahn, Esquire.

18 Sir, are you having trouble hearing me?

19 MR. LAWSON: No, I'm okay. I just have to turn my head.
20 I'm sorry.

21 ADMINISTRATIVE LAW JUDGE WOODY: That's okay. I just
22 want to be sure you can hear me.

23 The parties were afforded a full opportunity to offer
24 evidence, to call, examine, and cross-examine witnesses, and make
25 arguments in support of their respective positions. I will not

1 discuss all the evidence in detail. I have, however, considered
2 all the evidence, both oral and documentary. That which I do not
3 specifically mention is viewed by me as being corroborative or as
4 not materially affecting the outcome of this decision.

5 The Respondent, Mr. Matt Lawson, has appealed the
6 Administrator's Emergency Order of Revocation, which was dated
7 December 9th, 2014. Pursuant to the Board's rules, the
8 Administrator filed a copy of that order on December 22nd, 2014,
9 which serves as the complaint in this case. Respondent
10 subsequently waived his right to an expedited proceeding.

11 The Administrator ordered the emergency revocation of
12 Respondent's mechanic certificate with airframe and powerplant, or
13 A&P, ratings and inspection authorization based on Respondent's
14 alleged violations of Section 43.12(a)(1), 43.13(a), 43.13(b),
15 43.15(a)(1), 43.9(a)(3), and 91.403(d) of the Federal Aviation
16 Regulations, which are codified at 14 Code of Federal Regulations,
17 and for ease I'll refer to the Federal Aviation Regulations as FAR
18 provisions.

19 More specifically, the Administrator's complaint alleges
20 that between December 20th and December 26th, 2012, Respondent
21 made fraudulent or intentionally false entries in maintenance
22 logbooks and associated Forms 337 for civil aircraft tail No.
23 N5683T, a Cessna Model 172E, Serial Number 17251583, in violation
24 of 14 C.F.R. 43.12(a)(1); that he failed to use methods,
25 techniques, and practices prescribed in the current manufacturer's

1 maintenance manual or instruction for continued airworthiness, or
2 other methods, techniques, and practices acceptable to the
3 Administrator in performing maintenance, alteration, or preventive
4 maintenance on N5683T in violation of Section 43.13(a); that when
5 maintaining or altering or performing preventive maintenance on
6 N5683T, he failed to do the work in such a manner and used
7 materials of such quality that the condition of N5683T afterwards
8 was at least equal to its original or properly altered condition,
9 in violation of Section 43.13(b); that when performing an annual
10 inspection of N5683T, failed to perform the inspection so as to
11 ensure that the aircraft met all applicable airworthiness
12 requirements, in violation of 43.15(a)(1); and he failed to make
13 an entry in the logbook of N5683T containing the name of the
14 person or persons other than Respondent who performed work on the
15 aircraft, in violation of Section 43.9(a)(3); and that he altered
16 N5683T based on the supplemental type certificate without being
17 the holder of the STC or having written permission from the holder
18 of the STC to do so in violation of Section 91.403(d).

19 In his answer to the Administrator's complaint,
20 Respondent admitted to paragraph 1 of the complaint and denied the
21 remaining paragraphs of the complaint. So for our purposes,
22 paragraph 1 is deemed established for purposes of this decision.

23 The Administrator's Exhibits A-1 through A-17 were
24 admitted into evidence; that is, with the exception of the first
25 two pages of Exhibit A-6, which were not admitted into evidence.

1 The following Respondent's exhibits were admitted into
2 evidence: R-1 through R-6, R-8 through R-11, R-15, R-16, R-19,
3 R-22, R-24, 25, and 30. Exhibits R-26 and R-28 and, as noted,
4 pages 1 and 2 of Exhibit A-6 were not admitted into evidence.

5 The Administrator presented the testimony of Inspectors
6 Daniel J. Moore and Arthur Randy Steffes. Mr. Moore testified
7 first and testified that he has worked for the FAA since 1998, is
8 currently a supervisory airworthiness inspector and front-line
9 manager for the Denver Flight Standards District Office, or FSDO.
10 Prior to moving to Denver, he was assigned to the Grand Rapids
11 FSDO where he held positions as aviation safety inspector, or ASI,
12 as an assistant principal maintenance inspector, or PMI, as a PMI,
13 as a front-line manager, and as the acting FSDO manager.

14 Before joining the FAA, he worked in the aviation
15 industry for 19 years in a variety of maintenance-related
16 positions, including as a mechanic, lead mechanic, director of
17 maintenance, quality assurance representative, and quality
18 manager.

19 He holds a mechanic's certificate with A&P rating since
20 1979 and a private pilot certificate.

21 Mr. Moore indicated he first discussed with Mr. Lawson
22 his desire to install a modified engine in N5683T during an IA
23 seminar in March 2011. According to Mr. Moore, there are a number
24 of ways to accomplish a major repair or alteration to an aircraft.
25 If an individual already has approved data supporting the

1 alteration or repair such as a type certificate data sheet, an
2 STC, designated engineering report, or airworthiness directive,
3 then he can complete the Form 337 and does not have to involve the
4 FAA in the approval process. For instance, if an individual has
5 purchased an STC from the STC holder, he can complete the Form 337
6 and the major alteration or repair and does not have to get
7 further approval from the FAA since the FAA has already approved
8 the STC. However, if he wished to deviate from the approved data,
9 then he would need a designated engineering report or field
10 approval from a qualified ASI first. He noted that field approval
11 is a one-time approval pertaining to a specific aircraft.

12 For field approval, a mechanic needs to put together a
13 field approval request, including a draft Form 337 with supporting
14 data and normally with a cover letter. Mechanic is responsible
15 for the completeness and accuracy of the 337 setting forth the
16 scope of the repair or alteration. The package is submitted to
17 FSDO for review by a qualified ASI. The ASI reviews the Form 337
18 and all supporting data to ensure airworthiness and safety of the
19 aircraft. If the scope of repair or alteration isn't clear or is
20 insufficient, then typically the ASI will contact the submitter to
21 clarify. If the ASI rejects the field approval request, normally
22 he would call the mechanic to make him aware of why he did not
23 approve. Mr. Moore indicated he has never issued a field approval
24 without some discussion with the mechanic.

25 Once the ASI determines the data is sufficient, then he

1 signs Block 3 of the Form 337 indicating the data is approved
2 subject to a conformity inspection. The scope of the work is set
3 forth in Block 8 of the form. Once approved, the Form 337 is
4 returned to the mechanic. The mechanic should review the form to
5 ensure he knows and understands what data to follow. If the
6 mechanic desires to use data not in Block 8 or to deviate from the
7 data in Block 8, then he would have to essentially start over,
8 submitting a new request for review and approval. The mechanic
9 can't simply do what he thinks is appropriate if it deviates from
10 the approved data.

11 Then once the work is done, a repair station or
12 individual with an inspection authorization has to complete a
13 conformity inspection. The inspection is to determine that the
14 modifications were done in accordance with the data in Block 8 and
15 that the aircraft meets all airworthiness requirements and is in a
16 condition for safe flight. The inspector signs the form and
17 provides a copy to the owner of the aircraft and sends a copy to
18 Oklahoma City where it is maintained in the permanent records for
19 the aircraft.

20 Mr. Lawson submitted a Form 337 for field approval. The
21 package included a couple of prior field approvals along with
22 other reference data. Mr. Moore did not approve the initial field
23 approval request. He indicated typically one would consider the
24 prior field approvals only if they were very similar to the
25 request submitted and including all supporting data.

1 He stated Mr. Lawson included a copy of the STC, which
2 covered all the modifications except the deviation for the
3 propeller from 76 inches to 78 inches diameter. He agreed that
4 Mr. Lawson indicated that the STC was not available because he
5 could not reach the STC holder. Mr. Moore also stated he had no
6 reason to believe the STC would not become available later.
7 Mr. Moore said he approved the data only, that it was Mr. Lawson's
8 responsibility to get permission to use the STC from the owner.
9 He indicated he contacted Mr. Lawson after he had approved the
10 data and signed off on the field approval but that he wasn't
11 present when the Form 337 at Exhibit A-2 was picked up by
12 Mr. Lawson. He also pointed out that the Form 337 requires a
13 conformity inspection which was signed off on by Mr. Lawson.

14 Mr. Moore agreed that he has not worked on an aircraft
15 for 18 years. He also confirmed that the modifications completed
16 under this Form 337 were to install a modified engine and a
17 constant speed propeller. He was unaware that Mr. Lawson was also
18 going to do a floatplane kit.

19 Mr. Moore confirmed that Mr. Lawson submitted a field
20 approval checklist with his request as well as copies of prior
21 field approvals. Mr. Lawson did indicate the STC was not
22 available although Mr. Moore had no information about whether it
23 would be available in the future. He agreed that Mr. Lawson did
24 not say he had permission to use the STC. Mr. Moore confirmed the
25 prior field approvals were out of the Grand Rapids FSDO. He was

1 not aware if Mr. Lawson had worked with Mr. Miller on this field
2 approval before it was assigned to him. He could not recall who
3 drafted the final language in Block 8 of the form, although he did
4 remember a conversation with Mr. Lawson about changes needed to
5 Block 8.

6 Mr. Moore agreed that Mr. Lawson sent a modified 337 to
7 Mr. Moore that was not finally approved. Mr. Moore stated he did
8 not formally reject the submission but called to discuss further
9 changes that were needed. He disagreed that Mr. Lawson used the
10 STC just for reference. He submitted information about the STC.

11 Mr. Moore did not provide Mr. Steffes correspondence
12 with Mr. Lawson or copies of any prior drafts of the 337s, nor did
13 he tell Mr. Steffes that they discussed the STC, that the STC was
14 not available, or discuss with Mr. Steffes how the language in
15 Block 8 came about. He agreed that if it was a matter of just
16 following the STC, then field approval was not necessary. If the
17 STC was not available, supporting data could be approved by field
18 approval. Mr. Moore stressed that the Form 337 approved only the
19 data. Mr. Moore indicated policy is to do data approval only and
20 not to do on-site inspections of any aircraft being modified under
21 a field approval to ensure compliance with the approval. He
22 indicated he could notify an individual either orally or in
23 writing about rejection of a Form 337 as drafted. Typically he
24 would do so in writing only if it was a final rejection at the end
25 of the process.

1 Mr. Moore stated he did not keep files with any copies
2 of the draft 337s, and he indicated he had not experienced any
3 falsification issues with Mr. Lawson in the past.

4 With respect to the prior field approvals submitted by
5 Mr. Lawson, Mr. Moore could not remember specifically, but did not
6 believe that those involved the same make and model aircraft. He
7 reiterated that field approval only applied to the specific
8 aircraft involved and the data considered and not to other
9 aircraft, even if they were the same make and model. He was not
10 involved with the prior field approval, so he's not sure what data
11 was considered. He stated there's no policy that requires formal
12 rejection of a field approval request, and his practice has been
13 to discuss necessary changes orally with the applicant.

14 Mr. Moore testified that he did not tell Mr. Lawson he
15 must have the STC before signing off on the Form 337. He assumed
16 that as a seasoned A&P mechanic with an inspection authorization
17 that Mr. Lawson was aware that he must have permission from the
18 STC holder before using the STC. He indicated they had no
19 discussions to clarify when Mr. Lawson intended to perform the
20 modifications or when the STC might become available.

21 Next Inspector Randy Steffes testified that he is
22 currently assigned to the Grand Rapids FSDO as a PMI. He's been
23 with the FAA since 2008 and was previously employed in the
24 Scottsdale FSDO as both an ASI and assistant PMI. He has been an
25 A&P mechanic since 1984 and holds an inspection authorization as

1 well as commercial pilot certificate, both rotor and fixed wing.
2 He has prior maintenance experience in the Marine Corps, both
3 active and reserve, and with filling pilot and maintenance
4 positions in the commercial aviation industry. He stated this
5 matter first came to his attention in the form of a complaint by
6 another mechanic performing an annual inspection on N5683T and who
7 identified a number of discrepancies that caused him concerns
8 about the airworthiness of the aircraft. Mr. Moore and
9 Mr. Steffes met with the individual who filed the complaint who
10 raised a number of concerns.

11 After their meeting, the determination was made to
12 initiate an investigation. Mr. Steffes inspected the aircraft at
13 the Complainant's maintenance facility. He also reviewed all
14 aircraft records along with the aircraft's airworthiness
15 certificate and logbooks. He indicated the maintenance logbooks
16 are required to be completed by individuals performing maintenance
17 to ensure compliance with approved data and airworthiness of the
18 aircraft.

19 Logbook entries in Exhibit A-1 and the Form 337 in
20 Exhibit A-2 revealed that Respondent completed certain alterations
21 or repairs to the aircraft in December 2012 and signed off as
22 having completed those modifications, then inspected the aircraft
23 and signed off approving its return to service as airworthy. He
24 identified Block 8 from Exhibit A-2 as setting forth the scope of
25 work with the only deviation noted from the STC being the change

1 of propeller size from 76 to 78 inches in diameter. Mr. Steffes
2 said the 337 form identified the engine as an IO-360-G engine as
3 does the logbook entry; however, the engine data plate identifies
4 the engine as an IO-360-K model, more specifically a G model
5 modified to a K model. The propeller on the plane was measured at
6 80 inches in diameter. There were no logbook entries noting any
7 maintenance or modification after Mr. Lawson returned the aircraft
8 to service.

9 Mr. Steffes stated the mechanic is required to obtain
10 the written permission from the STC holder prior to using the STC.
11 The written permission is done by model and serial number of the
12 aircraft involved. Mr. Thomas Anderson holds the STC referenced
13 in the Form 337, and that STC or part of that STC was Exhibit
14 A-10.

15 In inspecting the aircraft and comparing it against the
16 installation instructions for the STC, Mr. Steffes noted numerous
17 discrepancies between the two. For instance, he stated the engine
18 mounts were inconsistent with TIG welding called for by the STC,
19 as exhibited in Exhibit A-6 -- he noted that was important because
20 the greater heat signature from a different welding method which
21 could change the heat characteristics of the metal which could
22 lead to cracks or the need for it to be re-treated -- nor did the
23 bracing match the installation instructions.

24 Reviewing specific installation instructions in Exhibit
25 A-10, Mr. Steffes noted that Instruction 1(j) called for

1 installation of a noise filter that was not installed; Instruction
2 4(b) requires a fuel boost microswitch that was not installed; no
3 oil pressure restrictor elbow was installed as required by
4 Instruction 4(j); the tachometer had no range markings; and the
5 oil temperature and oil pressure gauges were not marked as
6 required; there was no high-low fuel pump boost control switch as
7 called for by the STC; and an 80-inch propeller was installed
8 rather than one of the two options provided for by the STC for the
9 field approval, which were the 76- and 78-inch propellers.

10 An additional Form 337 in Exhibit A-3 refers to the
11 firewall and tail cone replacement with a tail cone from the same
12 model aircraft done in accordance with the Cessna structural
13 repair manual and FAR Advisory Circular 43-1&2; however, the tail
14 cone was not from the same model but was identified by its data
15 tag as a model 172K rather than 172E. Rivets on the firewall were
16 not stainless steel as required by the Cessna repair manual, but
17 were aluminum and, therefore, not fireproof. He also indicated
18 the spacing on the rivets was not done correctly. There were
19 elongated holes that were not filled, rivet heads overlapped, and
20 brackets were installed at the top of other rivets, and rivets
21 were installed too close to the edge of material. The Form 337
22 was signed off and inspected by Respondent. Exhibit A-4 was
23 identified as another Form 337 signed off, inspected, and returned
24 to service by Respondent which addressed installation of
25 oil temperature and pressure sensors and gauges. The sensor

1 was installed directly on the engine which wasn't in
2 compliance with the STC referenced. Further, the gauges
3 were placed under the yoke and were unreadable while sitting in
4 the seat.

5 Mr. Steffes identified Exhibit A-5 as a Form 337 for
6 installing a floatplane reinforcement kit in accordance with a
7 Cessna technical drawing and with Advisory Circular 43.13-1 and 2;
8 however, the engine modification STC says the engine modification
9 applies only to land-based planes nor did the modifications
10 conform with the Cessna drawing. For instance, the float mount
11 brackets installed in the firewall were not Cessna parts
12 identified in the drawings and appeared to be cut from bulk
13 material.

14 After reviewing the logbooks, Forms 337, and the
15 aircraft records, Mr. Steffes drafted a letter of investigation,
16 or LOI, dated March 21st, 2014, with a corrected copy of that LOI
17 dated March 24th, 2014. Mr. Lawson elected to have an in-person
18 meeting with the FSDO to discuss the discrepancies rather than to
19 formally respond to the LOI in writing. Mr. Moore and Mr. Steffes
20 were present for that meeting.

21 According to Mr. Steffes, he asked Mr. Lawson about the
22 G versus K model engine, and Mr. Lawson said they were the same
23 except the oil capacity and corresponding dipstick markings. He
24 indicated he re-marked the dipstick. He could not say what
25 technical data he relied on in determining the engines were the

1 same. When questioned about the 80-inch diameter propeller, he
2 stated Mr. Lawson indicated he knew it was an 80-inch propeller
3 but stated that the plane was going to be a floatplane as the
4 reason the large propeller was installed. He conceded that the
5 plane was not a floatplane when he returned it to service. When
6 queried about the aft fuselage, Mr. Lawson offered that the
7 fuselages were all the same. When asked about the different
8 model, he indicated he must have missed that.

9 Mr. Lawson also indicated that someone else performed
10 work on the fuselage replacement. He noted that he inspected the
11 riveting and it was a little weak. Mr. Steffes noted the logbook
12 entry does not say the work on the fuselage was done by others.
13 Mr. Lawson confirmed his signature on all the Forms 337 and stated
14 that he must not have looked at them very closely.

15 Mr. Steffes opined that the aircraft was not airworthy
16 because it did not conform to its type certificate or properly
17 altered condition and wasn't safe for flight. As to the
18 differences between IO-360-G and K model engines, Mr. Steffes
19 noted the horsepower was different, the oil temperature range
20 differed, as did the tachometer range and oil capacity. He also
21 noted that the K model engine was not certified or certificated in
22 that aircraft at the time. He noted that the propeller
23 discrepancy could affect RPMs and might result in a prop strike;
24 that the aft fuselage brackets and rivets could affect structural
25 strength and integrity; the aluminum firewall rivets could allow

1 an engine fire to reach the occupants in the aircraft; that the
2 engine mount heat signature change from the welding discrepancy
3 could cause cracks, could cause a reduced tensile strength; that
4 the lack of a high-low fuel pressure switch could affect
5 appropriate pressure in critical situations; and incorrectly
6 marked gauges could result in operation outside operating limits
7 and result in damage or failure. Mr. Steffes opined that the
8 aircraft was, therefore, not airworthy when Mr. Lawson returned it
9 to service.

10 He also reviewed the sanction policy guidance table and
11 noted that the appropriate sanction for even one intentional
12 falsification was revocation.

13 Mr. Steffes stated that he had no involvement in the
14 field approval or drafting the Form 337 and was not present during
15 any meetings between Mr. Moore and Mr. Lawson. He agreed no field
16 approval was needed if alterations were done under an STC and that
17 you can't use an STC if it is not approved and/or you don't have
18 permission from the STC holder. He noted Block 8 of the Form 337
19 addresses approved data, and if the data is not approved, then it
20 shouldn't be in Block 8. He stated prior field approvals could be
21 used as accepted data to review for approval of a new field
22 approval if they were applicable to the pending field approval.
23 In his opinion, Block 8 should be completed by the mechanic and
24 not an ASI.

25 He testified that if Block 8 is not acceptable, then an

1 ASI could return it to the mechanic with a rejection letter or may
2 just discuss the information with the applicant. Mr. Steffes
3 reviewed Block 8 of Exhibit A-2 as part of his investigation which
4 includes both an STC and field approval. The only exception to
5 the STC noted in Block 8 was the changed prop diameter from 76
6 inches to 78 inches.

7 Mr. Steffes was aware that Mr. Moore signed Block 3.
8 From his review of the Form 337, it was clear to him that
9 modification was being done in accordance with the STC and he
10 would assume Mr. Lawson had the STC and permission to use it.
11 Mr. Moore did not inform Mr. Steffes that he had discussed with
12 Respondent that the STC was not available at the time. Mr. Moore
13 did not provide any draft copies of Forms 337 or prior field
14 approvals, and Mr. Steffes did not ask for any such documentation.

15 He did not discuss with Mr. Miller any involvement he
16 may have had. Mr. Steffes had no knowledge that the field
17 approval was intended to cover both the propeller change and
18 engine change. He was not aware if the FSDO had approved prior
19 similar modifications under field approval.

20 Mr. Lawson did indicate to him that the STC was
21 unavailable. Mr. Steffes agreed that the LOIs he sent to
22 Mr. Lawson on March 21st and 24th, 2014, contained administrative
23 errors. He indicated those were mistakes and not intentional
24 falsifications.

25 In reviewing the complaint at Exhibit R-6, paragraph 16,

1 he stated he had no knowledge of any special engine mounts
2 required by the STC and was not aware of the STC holder rejecting
3 welds as not meeting STC requirements. As to subparagraph (c), he
4 agreed that if the engine was, in fact, a G model engine, then
5 there will be no falsification on that point, but he disagreed
6 that the STC allowed for use of either a G or K model engine.
7 Mr. Steffes did not do any comparison of any tail cones from other
8 model Cessna 172s to determine if they were the same. He
9 understood the entry to mean a Cessna 172E and noted that the 172K
10 model came out 12 years after the 172E.

11 He disagreed that there was just three or four rivet
12 holes that had problems and stated that there were many rivets
13 that there were issues with, which he opined absolutely affected
14 the airworthiness of the aircraft. As to the brackets with tool
15 damage, he noted that tool damage weakens the metal and affects
16 airworthiness. As to use of the aluminum versus stainless rivets,
17 he stated that he looked at the certification data for the
18 aircraft and the Cessna repair manual and that determined aluminum
19 rivets were not acceptable. He also noted the rivet edge distance
20 will be in the drawings approved for production certification as
21 well as Advisory Circular 43-13.

22 He indicated he wasn't aware if Mr. Moore signed off on
23 a field approval to install the float kit, nor is he aware of an
24 80-inch propeller being approved for installation on a C-172
25 floatplane. As to the alternator noise filter, he did not know

1 why the STC required installation on the firewall, but that is
2 what the STC requires and the noise filter was not there. He
3 stated that he has not seen an on/off fuel pump switch as opposed
4 to the STC required high-low switch in fuel-injected engines. He
5 could not say whether a 24-volt switch could work with a 12-volt
6 system on the Cessna 172E.

7 With respect to the oil pressure restrictor fitting, he
8 saw no indication that Mr. Lawson reconciled and complied with
9 conflicting STC requirements and cannot speak to that. He noted
10 that there were no range markings on the instrument gauges. He
11 did not know how many hours the plane was flown since being
12 returned to service by Mr. Lawson, but believed that the
13 tachometer indicated approximately 9 hours.

14 There were no maintenance entries after Mr. Lawson
15 returned the plane to service in December 2012, and Mr. Steffes
16 relied on the fact that any maintenance would have been properly
17 documented. As for the automatic alternate air being installed,
18 he stated that the STC did not provide for such installation. He
19 did assume the installation was to be done in accordance with the
20 STC. Mr. Lawson did say that the placards were all installed when
21 the plane left his facility, and he agreed that Mr. Lawson would
22 not be responsible if someone else removed the placards.

23 Mr. Steffes agreed that N5683T was not airworthy when he
24 inspected it in 2014. He took no steps to revoke its airworthiness
25 certificate at that time because he understood the plane was being

1 sold for parts. He recently, within the past few weeks, learned
2 that the plane has been flying and steps are now being taken
3 towards revocation of its airworthiness certificate.

4 He indicated the data tag on the tail section of the
5 aircraft was not a stock Cessna data tag, and he assumed someone
6 fabricated the tag. He tried to track down the tail cone from the
7 N number on the tag but was unable to do so. As for the firewall,
8 he does not know where it came from other than what was indicated
9 on the data tag.

10 With respect to the brackets on the firewall, they
11 appear to him to be permanently installed, which was part of the
12 basis for his conclusion that they were not authorized.
13 Mr. Steffes indicated he would not typically discuss with the ASI
14 what was approved by the field approval since he saw nothing
15 ambiguous in the language in Block 8 of the Form 337. He noted
16 authority to use data is different than approval of the data and
17 that field approval only applies to one particular aircraft by
18 serial number and not to any other aircraft. He stated that the
19 person installing a part is responsible for the airworthiness of
20 the part.

21 He indicated that Mr. Lawson told investigators that the
22 engine was a K model engine but that the engines were the same.
23 He noted that there is no approved data to allow installation of a
24 K model engine under the STC, nor was there approved data under
25 the STC for the plane to be put on floats. It was approved for

1 land plane only. He also noted that the plane was a land plane
2 when Mr. Lawson returned it to service and when he inspected it in
3 2014.

4 The Form 337 specifically indicated a deviation to
5 install a 78-inch propeller, but an 80-inch propeller was on the
6 plane. The Form 337 did not indicate a deviation from the high-
7 low off switch called for in the STC. He testified that if
8 further deviation from the STC is necessary, then you would need
9 further approval to do so such as through another field approval.
10 Mr. Steffes indicated there is no FAA signature on any of the
11 other Forms 337 at issue here and no indication that Mr. Moore was
12 aware of them.

13 He stated that when they interviewed Mr. Lawson, he
14 stated that he understood that the entire installation had been
15 approved under field approval by Mr. Moore. He also stated that
16 the engine models and aft fuselages were basically all the same.
17 As to the 80-inch propeller, Mr. Lawson indicated he knew the
18 propeller was 80 inches. Mr. Moore told Mr. Steffes that he
19 approved the data on the Form 337 at Exhibit A-2 but did not
20 approve the entire installation.

21 The Respondent presented the testimony of Mr. Matt
22 Lawson himself and Mr. Jean Bland. Mr. Lawson testified first
23 that he began working on aircraft in 1967 when he first started
24 learning to fly. He indicated he had a passion for the North
25 Country and he soon began learning to put float kits on planes.

1 He has a mechanic certificate with A&P rating since 2004 and an
2 inspection authorization since 2008. He's done a variety of
3 aircraft maintenance work including airframe work, rebuilding
4 aircraft, engine maintenance, structural repairs, et cetera. He
5 also holds single-engine land and seaplane commercial pilot
6 certificates and has approximately 10,000 flight hours. He noted
7 that he completed a 4-year sheet metal apprenticeship and has 26
8 years of sheet metal experience. He has been certified in all
9 facets of welding and has 10 to 15 years of welding experience.
10 He has also taught vocational school including classes in
11 blueprint reading, vocational drawing, and welding.

12 He is the owner of Lawson Aviation, previously B & L
13 Aviation. He indicated his company does aircraft modification
14 such as installing float kits, structural repairs, as well as
15 various major repairs and alterations. He indicated he is
16 familiar with completing Forms 337 and completed approximately a
17 dozen forms per year for the past 10 years.

18 He stated he has completed work under both STCs and
19 field approval and the STCs are much simpler. Although field
20 approval is harder, he has worked with the Grand Rapids FSDO in
21 the past and with other ASIs to successfully obtain field approval
22 on several aircraft. He indicated his interaction and
23 relationship to Mr. Moore was more difficult than with other ASIs
24 in the Grand Rapids FSDO. He stated he has received prior field
25 approval to install float kit at the same time as an engine

1 modification on the Cessna 172E, and the ASIs he worked with were
2 Mr. Miller and Mr. Goldman.

3 Mr. Lawson indicated he had dealt with Mr. Tom Anderson,
4 the STC holder, in the past. He purchased motor mounts from
5 Mr. Anderson that didn't work as designed. He modified the motor
6 mounts and completed technical drawings that he sent to
7 Mr. Anderson which were eventually incorporated into an STC by
8 Mr. Anderson. He indicated he also designed and fabricated a
9 header tank for Mr. Anderson.

10 As to N5683T, the scope of the work on the plane when it
11 initially came in was to convert it to a floatplane for Mr. Boedt
12 to use on a lake. There was also damage to the firewall and tail
13 cone that needed to be repaired and a STOL kit that was to be
14 installed. He stated it was later that they decided to do the
15 engine and propeller modifications. He found out that the STC
16 wasn't available and he would need field approval. He stated he
17 told the FSDO he wanted to install an IO-360-G engine. His request
18 included a field approval checklist and copies of Forms 337 from
19 prior field approvals. He indicated he contacted Mr. Moore after
20 the 337 had been rejected, but he did not talk with him at the IA
21 seminar in March of 2011. He met with Mr. Moore in Grand Rapids
22 at the FSDO. Mr. Moore advised him he needed to make changes to
23 his application, and Mr. Lawson scribbled notes from which he made
24 changes to the Form 337. He indicated he told Mr. Moore during
25 their meeting that the STC was not available.

1 Mr. Lawson stated he made changes to the form and
2 resubmitted it to the FSDO. He said he did not get a call from
3 Mr. Moore when it was approved and got no indication that his
4 submission was not approved. Instead, he said he received the
5 approved Form 337 in the mail. He stated he did not draft Block 8
6 of the approved 337. He figured Mr. Moore was his boss and this
7 form was what he wanted so he signed it and did the work on that
8 basis.

9 With respect to paragraph 16 of the complaint, Exhibit
10 A-2, Mr. Lawson stated the engine mount he used was one he
11 received from Mr. Anderson previously, and he saw no problem with
12 the engine mount welds and had no information that they were
13 rejected by the STC holder. Mr. Lawson stated that the engine
14 used was a G model engine he built using the old case from a G
15 model that had been converted to a K model. He admitted he should
16 have stamped out the data tag to make that clear.

17 He stated the tail cones were from the same model
18 aircraft, a Cessna 172. Whether it was a E or a K model doesn't
19 make a difference in his opinion. According to him, there were
20 only three or four rivets that had issues.

21 He noted when he inspected the airplane in early 2015,
22 there were a number of items that should have had corresponding
23 logbook entries, such as a new interior replacement tachometer.
24 He said he knew one individual that did some work on the aircraft,
25 and with respect to the tool damage on the tail cone, he said he

1 had no idea what that referred to. There was no damage when he
2 returned the aircraft to service. He stated he used aluminum
3 rivets on the firewall which he believes are acceptable. No
4 sealant was necessary on the firewall because they did not break
5 the seal. He stated they did not change the rivet edge distances,
6 that they used Cessna rivet holes. He stated the brackets
7 installed on the firewall were temporary and to establish a bolt
8 pattern for a later float kit installation and that they did not
9 serve any purpose. He indicated the intent was to remove rivets
10 that were covered by the brackets later when the floats were
11 attached. He stated he had previously installed a floatplane kit
12 simultaneously with an IO-360 conversion.

13 He indicated his intent was to install an 80-inch
14 propeller for the plane's later conversion to a seaplane. He
15 stated that he advised the owner he should not fly the plane until
16 the floats were attached.

17 As to the fuel boost pump system, he indicated the high-
18 low switch was a 24-volt system and he doubted it could be used
19 with a 12-volt system such as the Cessna 172E.

20 As for the oil pressure restrictor fitting, Mr. Lawson
21 stated that he used a transducer with the restrictor built in and
22 it was installed on the firewall when it left his shop. He stated
23 that the automatic alternate air was an option under the STC.
24 With respect to instrument markings, Mr. Lawson stated the range
25 markings were on the instruments when he returned the aircraft to

1 service. He assumed Mr. Boodt removed the placards. He noted the
2 exhaust system he used was appropriate for a Hawk XP and works
3 perfectly with this aircraft.

4 As to Exhibit R-1, Mr. Lawson stated that those were
5 draft 337 forms he prepared for field approval and presented to
6 the FSDO. Pages 1 and 2 of that exhibit was rejected by the FSDO
7 and contains his handwritten notes from his meeting with
8 Mr. Moore. Pages 3 and 4 is the modified 337 he resubmitted with
9 changes he discussed with Mr. Moore.

10 He identified R-2 as the Form 337 returned to him by
11 Mr. Moore for the field approval. He stated that he did not
12 prepare the information in Block 8 and assumes Mr. Moore did,
13 noting that the N number in Block 8 of the approved form is not
14 filled in as it was in his previous submissions and that his
15 computer automatically fills in that information for him. He
16 stated the description of work is not as he would describe.
17 Mr. Lawson stated that he checked and confirmed that the aft
18 fuselage he installed was compatible. He opined that the firewall
19 riveting inspection called for in the Cessna service bulletin was
20 not applicable. He also stated that the vertical brackets were
21 already installed in the firewall when he purchased it.

22 In reviewing paragraph 6 of the complaint, that's at
23 Exhibit R-6, page 2, Mr. Lawson noted that he reassembled, rigged,
24 and test flew the aircraft. He performed the ELT testing per FAR
25 Section 91.207. He advised that his logbook entry referenced only

1 the model number of the tail cone and did not reference a year,
2 and when referring to model, he was referring to the Cessna 172
3 model only. He stated he did install a floatplane kit in
4 accordance with Cessna drawing 0500044. He repaired the lower
5 firewall using parts from an aircraft of the same year and model.
6 He indicated that he installed an oil temperature and oil pressure
7 gauge in accordance with the STC. And he stated he installed an
8 IO-360-G model engine in accordance with the STC and field
9 approval.

10 Mr. Lawson identified Exhibit R-11 as a NASA report
11 under the Aviation Safety Reporting program that he filed on April
12 7th, 2014, after his meeting with Mr. Moore and Mr. Steffes on
13 either April 2nd or 4th. He stated he filed the report because he
14 realized after that meeting that there was a problem. Mr. Lawson
15 stated that he last saw N5683T in Coldwater, Michigan, in February
16 or March 2015 and that the aircraft looked different. It had a
17 new intercom and electronic tachometer installed and the
18 transducer was no longer on the firewall.

19 He reiterated that he did not try to conceal any work
20 done on the aircraft and had no intent to falsify and that he told
21 everyone what he was doing and how he was doing it. Mr. Lawson
22 indicated he considers himself conscientious and when he signs a
23 form, he means what he signs. This was not his first field
24 approval and he has completed numerous Forms 337. He understands
25 that when he signs Block 6 of the form, he is certifying that the

1 repairs or alterations are made in accordance with the
2 requirements of Part 43 of the Federal Aviation Regulations. He
3 agreed that "in accordance with" means the same as "in conformity
4 with."

5 Initially he stated that he read the Form 337 received
6 from Mr. Moore before beginning work and that he did not recall
7 telling Mr. Steffes in April 2014 that he did not read the form.
8 He then conceded that he read only the approval in Block 3, that
9 the owner took the form and he did not read Block 8 of the form
10 before doing the work. He stated there was no point in reading
11 Block 8 because he assumed the Form 337 would be as he submitted
12 it for approval.

13 He read Block 8 after he received it back from the
14 owner. He indicated he had concerns about the form at that point
15 but did not contact Mr. Moore or anyone else to clarify. His
16 reason for not contacting Mr. Moore is that he did not have a good
17 working relationship with him.

18 He agreed that he prepared the Form 337 at page 3 and 4
19 of Exhibit R-1 and that the language in Block 8 references an IO-
20 360-G model engine and the same 78-inch propeller referenced in
21 the 337 form he received from Inspector Moore; and although
22 Mr. Lawson testified that the language in Block 8 of Exhibit R-2
23 was not what he wanted but what Mr. Moore wanted, he did not go
24 back to Mr. Moore or anyone else to address his concerns.

25 He understands the need for a mechanic to accurately and

1 truthfully report maintenance performed and that the FAA and
2 others rely on information in the forms. He also said he
3 understands what constitutes approved data and that a mechanic
4 must have approved data and be sure to conform to that data on the
5 Form 337 before signing off on it. When Mr. Lawson signed off on
6 the 337, the STC did not authorize installation of a 78-inch
7 propeller on a land plane, nor did it authorize an 80-inch
8 propeller on a land plane. He agreed the 80-inch propeller was
9 only authorized on a seaplane.

10 Initially Mr. Lawson stated that the STC authorized
11 installation of an IO-360-K model engine, but after reviewing
12 Exhibit A-10 agreed that the STC did not authorize installation of
13 a K model engine.

14 Mr. Lawson indicated he did install an 80-inch propeller
15 on December 20th, 2012, but that he took it back off and installed
16 a 76-inch propeller. He initially indicated he did not recall
17 making an entry in the propeller logbook indicating an 80-inch
18 propeller was installed but agreed there was such an entry after
19 being shown the logbook.

20 On further questioning, he indicated that the 80-inch
21 propeller was installed but had a vibration issue at higher RPM,
22 so he removed the propeller and installed a 76-inch propeller that
23 was used to test-fly the plane. He later reinstalled the 80-inch
24 propeller when the plane was delivered to the owner, but told the
25 owner he shouldn't fly the plane until the floats were attached.

1 He also confirmed there was no logbook entry for the swap out of
2 the propellers or reinstallation of the 80-inch propeller.

3 With respect to the Form 337 for replacement of the tail
4 cone and firewall at Exhibit R-3, he confirmed that he identified
5 the model of the aircraft in Block 1 of the form as a Cessna 172E.
6 He indicated that what went through his mind when he read Block 8
7 of the field approval Form 337 was that it was not the 337 he
8 filed. He stated he did not discuss a delay with Mr. Moore to
9 await the STC becoming available. Mr. Lawson stated he did not
10 need any FAA approval to build up a G model engine.

11 Next Mr. Bland testified that he's been involved in
12 aviation since 1963 when he began as a smokejumper and mechanic's
13 helper. He joined the Army in 1965 for 4 years where he worked on
14 aircraft and was a parachute rigger. He finished college in 1972
15 and went to work for Fairchild. In 1977 he went to work for
16 Piedmont Aviation where he worked in the engine and propeller
17 shops and earned his mechanic certificate with A&P rating in 1978.
18 He also holds a pilot certificate since 1979 and an inspection
19 authorization since 1984 and is a master parachute rigger. He's
20 held a variety of positions related to aviation maintenance
21 including as a director of maintenance for a Cessna dealer,
22 operating an FBO and as a coordinator for a Part 147 mechanic
23 school. He was also employed by the FAA between 1990 and late
24 2006. In his activities with certification of aircraft, he is
25 familiar with returning aircraft to service after performing STC

1 work.

2 He testified that he's also very familiar with filling
3 out Forms 337 and has been doing so since obtaining his inspection
4 authorization. He also has experience obtaining field approval
5 and using the STCs as approved data. He stated he reads and
6 interprets advisory circulars and FARs routinely in his work. He
7 was qualified as an expert in airworthiness.

8 Mr. Bland indicated he inspected the engine for N5683T
9 on March 4th, 2015. Although he did not annual the aircraft and
10 did not run the engine, he felt like the aircraft and engine were
11 airworthy. He indicated he read the Continental service bulletin
12 regarding changing data tags, and it appeared the engine data tag
13 was appropriately marked for converting a G engine to K engine.
14 He stated that in order to change the engine back to a G engine,
15 you could go to Continental for a new data tag or could remove the
16 C-K markings from the data tag and make a note in the logbook that
17 the engine was changed back to a G engine.

18 With respect to the airworthiness of the propeller,
19 Mr. Bland indicated that the type certificate data sheet and the
20 STC in question allow for installation of an 80-inch propeller on
21 a seaplane configuration. He stated he would review the logbook
22 to see if the engine was run and the fuel injection set up for the
23 larger propeller.

24 He testified that he inspected the tail cone section and
25 rivets and felt like it was within airworthiness standards. He

1 saw maybe three or four rivets that were not good. He stated that
2 it was not easy to tell without pulling the tail cone and looking
3 at the bulkhead since the plane was recently painted. As far as
4 the holes for the rivets not lining up, he indicated that even
5 when you use the same make and model, the holes don't always line
6 up. He discussed the fail-safe design where the plane is
7 essentially overbuilt and stated he saw nothing with the rivets or
8 tail cone that he believed was beyond fail-safe design. He did a
9 visual inspection of the firewall and said he saw nothing that
10 caused him any concern with its airworthiness. He concluded use
11 of aluminum rivets in the firewall was acceptable based on his
12 inspection on a number of Cessna 172 aircraft and discussions with
13 the structural consultant at Cessna. His inspection of the other
14 172 aircraft revealed older model aircraft with aluminum rivets,
15 some with rusting rivets that looked like some sort of steel and
16 some had perhaps monel rivets.

17 As to the floatplane kit, he saw provisions for a
18 floatplane kit to be installed on the aircraft, meaning templates
19 have been provisionally installed for later installation of the
20 floatplane kit. He said the Form 337 should identify the
21 installation as provisional, but then offered that use of the word
22 "reinforcement" in the Form 337 suggested to him that the
23 installation was provisional. He indicated he did not review the
24 Cessna drawing called out in the Form 337 pertaining to the
25 floatplane kit. He noted that the type certificate data sheet

1 provides for Cessna 172 to be converted to a seaplane. With
2 respect to the alternator noise filter, he opined that it does not
3 affect safety of flight so it's not an airworthiness issue. He
4 also stated he has seen the alternator noise filter located in a
5 variety of locations on the firewall, on the alternator, et
6 cetera. In his opinion, the location does not affect the function
7 of the filter.

8 As to what constitutes an aircraft model, Mr. Bland
9 indicated that any aircraft listed on the same type certificate
10 data sheet are the same model aircraft.

11 As to the high-low fuel boost switch, he reviewed the
12 STC requirement, but suggested that the high-low switch could not
13 be or would not be compatible because it is a 24-volt system for a
14 12-volt aircraft. He opined the installed switch met
15 airworthiness requirements based on the field approval. He
16 concluded that the automatic alternate air as opposed to the
17 manual cable adjustment presented no airworthiness issues and
18 stated it is typical to have automatic alternate air with fuel-
19 injected engines, such as here.

20 He stated there was no way to tell where the placards
21 were when the aircraft was returned to service in December of
22 2012. He noted that there was an electronic tachometer installed
23 when he inspected the aircraft in March 2015, which was different
24 than what Mr. Lawson had installed.

25 Mr. Bland also found no airworthiness issues with the

1 exhaust system installed by Mr. Lawson. He found it very unusual
2 to have Block 8 of the Form 337 changed by a FSDO inspector.
3 Based on his inspection of the aircraft, the materials he
4 reviewed, and his discussion with others, including Mr. Lawson, he
5 opined that in December of 2012 when the aircraft was returned to
6 service, it met its type design, was properly altered and was in
7 condition for safe flight; thus, it was airworthy.

8 Mr. Bland noted that he saw N5683T for the first time on
9 March 4th, 2015. He agreed that safe for flight does not equal
10 airworthy. He also agreed that field approval must be based upon
11 approved or acceptable data.

12 Next, Inspector Steffes was recalled as a rebuttal
13 witness. He testified that he based his investigation on the
14 complaint he received, documentation he reviewed, and what he
15 observed when he inspected the aircraft. He indicated the
16 complaint he received contained a couple of pages of
17 discrepancies. He concurred that safe for flight does not equate
18 to airworthy.

19 Inspector Steffes reviewed the engine mount invoice at
20 Exhibit R-16 and noted that the date of the invoice was 2004. It
21 references an aircraft with a different N number, and it indicates
22 an unidentified STC is pending. There is a part number and serial
23 number listed for the engine mount, but Inspector Steffes
24 indicated he could not locate a part number or serial number on
25 the mount during his inspection of the aircraft to determine if

1 that engine mount corresponded to the invoice, nor could he
2 determine a part number or serial number from any of the photos
3 taken.

4 He also noted the STC at issue here was approved in 2006
5 per Exhibit A-15, and he has no way of knowing if the STC
6 referenced on the invoice is pending, is the same one, or what the
7 finally approved data was. The approved STC gave specific
8 instructions for the engine mount and installation, and he
9 indicated the engine mount he observed during the inspection was
10 not in compliance with the STC requirements.

11 Inspector Steffes indicated that during their interview
12 of Mr. Lawson, he did not state that the engine was a G model as
13 he testified here. When he was advised that the data plate
14 identified the engine as a K model engine, he did not argue
15 otherwise. Rather, he suggested that the K model and G model
16 engines were basically the same engine.

17 As to the aft fuselage, Mr. Steffes stated that the 172E
18 and 172K models were not from the same type certificate data sheet
19 and the data plate on the replacement aft fuselage identified it
20 as being from a 172K model aircraft.

21 He stated that most of the rivets on the aft fuselage
22 did not comply with Advisory Circular 43.13. He was not aware of
23 any aircraft manufacturer that allows the edge spacing to be as
24 close as he observed. With respect to the firewall rivets, the
25 Cessna structural repair manual, which was the approved data

1 referenced on the Form 337, requires stainless steel rivets be
2 used. It contains no provision for using aluminum rivets. As for
3 sealant, he stated any overlap in material must be sealed with
4 Pro-Seal 700 or an equivalent sealant.

5 Mr. Steffes noted that the oil pressure and temperature
6 sensors noted in the Form 337 in Exhibit A-4 were installed
7 directly at the engine, which is contrary to the requirements that
8 the STC referenced and indicated that just because they work does
9 not mean they were airworthy. The alteration and repair has to be
10 done in accordance with approved data, in this case the STC, in
11 order to meet its type design, or be properly altered.

12 With respect to the float kit, Mr. Steffes stated that
13 the vertical brackets in the kit drawing were not consistent with
14 the brackets installed, which had no cutouts in the brackets;
15 thus, the installation did not meet the reference drawing and
16 there was no other approved data referenced. He disagreed that
17 the language in the Form 337 indicated the installation was
18 provisional. He also indicated that a floatplane was not
19 authorized under the Thomas Anderson STC.

20 Mr. Steffes testified that Mr. Lawson told them that he
21 installed the 80-inch propeller when the work was done. Today
22 he's now saying that he installed, pulled, and later reinstalled
23 the propeller. Mr. Lawson also testified that he didn't install a
24 78-inch propeller even though he signed off on a 337 that gave
25 field approval to increase the propeller from 76 to 78 inches.

1 Mr. Steffes admitted that he did not know precisely
2 where to look for the part number or serial number markings on the
3 engine mount so he can't say one way or the other whether the
4 engine mount on the invoice corresponds to the one installed on
5 the aircraft. He also agreed that he did not look at the engine
6 logbook to determine if any work had been done to build up the G
7 model engine. He stated he had no reason to look at whether it
8 was a G model engine because Mr. Lawson told him it was a K model.

9 He did not contact Cessna regarding the fuselage repair
10 parts. He used the Cessna parts manual and type certificate data
11 sheet. He stated his testimony was not intended to suggest that
12 there were no log entries after the aircraft was returned to
13 service by Mr. Lawson but only that there were no logbook entries
14 related to the issues at hand. He noted that there was one
15 logbook entry for installation of a new intercom between the time
16 that Mr. Lawson returned the aircraft to service and Mr. Steffes
17 inspected the aircraft in March of 2014. He testified that there
18 was no entry for an annual inspection in March 2014 because the
19 annual was never actually completed. Where paragraph 13 of the
20 complaint indicates that an annual was performed, that would be
21 inaccurate in the sense that "performed" suggests one was
22 completed, and it was not.

23 Inspector Steffes understood that a float kit was
24 installed and not floats. He agreed there is much more to the STC
25 at issue than is contained in Exhibit A-10.

1 All right. Having summarized the evidence and the
2 testimony of the witnesses, I'll now discuss the evidence in
3 relation to the allegations in this case.

4 With respect to the alleged violation of FAR Section
5 43.12(a)(1), the elements of an intentionally false statement are:
6 (1) a false representation; (2) in reference to a material fact;
7 and (3) made with knowledge of its falsity. Those elements are
8 based on the Hart v. McLucas case and a litany of cases that have
9 applied that standard since that case was published in 1976.

10 Now, with respect to the materiality element, there is
11 little question that the logbook and Form 337 entries in question
12 are material. Both Inspector Steffes and Inspector Moore
13 testified this information is the type relied upon by the FAA and
14 others to ensure that maintenance has been appropriately performed
15 and to determine the airworthiness and the safety of the aircraft.
16 Nor has Respondent contradicted their testimony or otherwise
17 substantially contested the materiality of the entries at issue.
18 In fact, in his testimony, he conceded that he understood the
19 importance of the accuracy and completeness of the maintenance
20 entries and that the FAA and others relied on that information.

21 Accordingly, I find that materiality of the entries in
22 question is established by the evidence. Thus, the key elements
23 to be determined are whether the entries in question are false,
24 and if so, if they were made by Respondent with knowledge of their
25 falsity.

1 First with respect to the entry regarding installation
2 of an IO-360-G model engine, the engine data plate clearly
3 identified the engine as a K model engine, or more accurately as a
4 G model converted to a K model engine. And when interviewed by
5 investigators in April 2014, Mr. Lawson admitted to them that
6 engine was a K model engine but asserted that the two engines are
7 essentially the same save for oil capacity and dipstick markings.

8 I found the investigators' testimony on this point to be
9 consistent and credible, particularly when considered in
10 conjunction with the draft Form 337 submitted by Mr. Lawson for
11 field approval, and that's at Exhibit R-1, which also originally
12 identified the engine as a K model engine. Nor was the data tag
13 altered or any entry made in the logbook to note the conversion of
14 the engine back to a G model as Mr. Bland testified should be
15 done.

16 In light of that testimony and evidence, I found
17 Mr. Lawson's testimony that the engine was, in fact, a G model
18 engine and he had simply failed to appropriately stamp the data
19 tag to be less than credible. Thus, I find that the preponderance
20 of evidence establishes not only that the entry was false but that
21 Respondent knew it was false at the time that he made the logbook
22 entry and signed off on the Form 337.

23 Similarly, as Respondent has testified and as he
24 admitted during his interview with investigators, he was aware
25 that the propeller installed on the aircraft was an 80-inch

1 propeller, contrary to the plain language in Block 8 of the Form
2 337 in Exhibit A-2. Even accepting that he may have intended to
3 configure the plane as a seaplane, his obligation was to ensure
4 the accuracy of the records and reconcile any discrepancies.

5 Further, even in the draft Form 337 at R-1, Respondent
6 identifies the same propeller by model and serial number as was
7 set forth in the final Form 337 which received field approval, and
8 that propeller was identified in testimony as 78-inch and not an
9 80-inch propeller; and when the aircraft was returned to service
10 and even when inspected in March 2014, it was a land-based plane
11 and not a seaplane. Nor did the finally approved Form 337 or any
12 previous drafts for that matter discuss seaplane configuration or
13 installation of an 80-inch propeller. And as credibly testified
14 to by Inspector Steffes, no floatplane or seaplane version of the
15 STC referenced in the Form 337 was certified.

16 For similar reasons, I find that the multiple
17 discrepancies noted between the modifications performed by
18 Respondent under the field approval and the requirements of the
19 STC in question were not only false but made with knowledge of the
20 falsity. And I will address the specific allegations individually
21 momentarily.

22 Now, while Respondent and his expert have testified in
23 many instances that the STC requirements were unnecessary or
24 incompatible, Respondent had an obligation to comply with the
25 plain language of the approved data in that Form 337 or to seek

1 modification of the field approval to address any necessary
2 changes. He chose to do neither and to simply make adjustments he
3 believed were necessary or appropriate.

4 In that regard, I have carefully considered his argument
5 that Inspector Moore filled out Block 8 of the Form 337 in Exhibit
6 A-2 and that the language in Block 8 was not what he intended or
7 requested. It is fairly clear from the evidence in prior Form 337
8 submissions that Mr. Moore did, in fact, complete Block 8 of the
9 Form 337 granting field approval. Now, whether that was done in
10 an attempt to assist Mr. Lawson in finally completing the form
11 after several failed attempts or for some other reason is unclear.
12 However, it is clear per the testimony of both Mr. Steffes and
13 Mr. Bland that having an ASI complete Block 8 of the Form 337 is
14 at best unusual and certainly not the preferred practice. No
15 doubt that created the potential for some degree of confusion or
16 miscommunication; however, that does not absolve Respondent of the
17 responsibility to carefully and completely review the form and
18 ensure that his activities are in compliance with the approved
19 data or to seek clarification or modifications as necessary.

20 Here the language in the form is clear in that it
21 requires the alterations to be done in accordance with the STC,
22 with only one exception for substituting a 78-inch propeller for a
23 76-inch propeller. Now, by his own admission, Mr. Lawson
24 voluntarily chose not even to read or review Block 8 of the 337
25 when he received it despite the fact that he testified to prior

1 failed attempts to obtain field approval and to reach some agreed-
2 upon language. Instead, he chose to complete the work prior to
3 reviewing the form and without reference to the approved data on
4 the form. Just as critically, when he received the 337 back from
5 the owner before signing off on the work and returning the
6 aircraft to service, he chose not to seek clarification or
7 guidance despite his testimony that he had concerns with the
8 language and the incorporation of the STC.

9 Now, I find this to be analogous to the situation
10 addressed by the Board and the Court in the Cooper and Boardman
11 cases, which addressed an airman's failure to read questions on
12 medical certificate applications. Now, the Boardman case is NTSB
13 Order EA-4515; it's a 1996 case. Administrator v. Cooper, NTSB
14 Order EA-5538, 2010, affirmed at 660 F.3d 476; it's a D.C. Circuit
15 case from 2011.

16 And in Boardman, the Board stated, "It seems to us that
17 an airman who, knowing that the Administrator relies on the
18 accuracy of these answers, tenders an application that turns out
19 to have a wrong answer to one or more of the many questions he
20 freely chose not even to read, much less to thoughtfully answer,
21 cannot reasonably argue that he lacked the intent to give false
22 information." And further, that an airman, "having acted in a manner
23 that could be viewed as evincing a willful disregard of the truth
24 should be determined to have intended that whatever answer he gave
25 be utilized."

1 Similarly here, Respondent demonstrated a willful
2 disregard for the truth of the information provided by first not
3 even reading Block 8 of the Form 337 before completing the work
4 and then failing to seek clarification or modification of the
5 information or ensuring his compliance with the plain language of
6 the approved data before signing off on logbook entries and Form
7 337 returning the aircraft to service. Having failed in his
8 responsibility to ensure the correctness of his representations,
9 he would be hard-pressed now to claim ignorance of the falsity of
10 the information supplied.

11 Regarding the Form 337 in Exhibit A-3 for the
12 replacement of the tail cone of the aircraft, I find that evidence
13 to be less convincing regarding intentional falsification.

14 First with respect to the tail cone, there is
15 conflicting evidence regarding what constitutes a same model
16 aircraft. On the one hand, Inspector Steffes credibly testified
17 that the Cessna 172E is not the same model as a 172K and that the
18 two aircraft have different type certificate data sheets. Even
19 Respondent's expert testified that aircraft with the same type
20 certificate data sheets are the same model aircraft. Yet,
21 Mr. Bland and Mr. Lawson both testified as to their understanding
22 that the tail cone sections for all Cessna 172 aircraft are
23 interchangeable and that even two Cessna 172E model aircraft will
24 have rivet holes that will not align properly.

25 Having considered the totality of the evidence and

1 testimony on this issue, I conclude that the Cessna 172E and 172K
2 model aircrafts are different models given their differing type
3 certificate data sheets as explained by both Mr. Bland and
4 Mr. Steffes. Accordingly, I conclude that the information in
5 Block 8 of the Form 337 regarding the tail cone is inaccurate or
6 false. However, based on that same evidence, I conclude that the
7 Administrator has failed to carry his burden of establishing that
8 Respondent made the false representation with knowledge of its
9 falsity. While the entry constitutes a violation of FAR Section
10 43.13, I do not find sufficient evidence of violation of FAR
11 Section 43.12(a)(1).

12 Now, as to the lower firewall, the Administrator
13 presented little or no evidence that the replacement firewall was
14 not from an aircraft of the same year and model as testified to by
15 Respondent; but what is clear based on the testimony is that the
16 new rivets for the firewall were aluminum rather than stainless
17 steel, as testified to by Inspector Steffes and as admitted by
18 Respondent and Mr. Bland.

19 Where there is disagreement is on the issue of whether
20 that constitutes work performed in accordance with the Cessna
21 structural repair manual. Mr. Steffes' testimony is that the
22 structural repair manual requires the use of stainless steel
23 rivets. Neither Respondent nor Mr. Bland addressed the structural
24 repair manual requirements, which is the approved data relied upon
25 on the Form 337; however, both testified that aluminum rivets are

1 acceptable per Cessna guidance and observation of use in other
2 C-172 aircraft. Even accepting Mr. Bland and Mr. Lawson's
3 testimony that Cessna provided after-the-fact guidance that use of
4 aluminum rivets was not objectionable, the fact remains that the
5 approved data relied upon by Respondent on the Form 337 requires
6 stainless steel rivets, and his use of materials not authorized by
7 the data relied upon constitutes a misrepresentation. Whether he
8 reviewed the data and chose to ignore the requirement or simply
9 chose not to review and comply with the guidance, I find that his
10 misrepresentation was a knowing one.

11 As to the rivets on the aft fuselage and lower firewall
12 section, there is widely conflicting evidence regarding the number
13 and nature of issues with those rivets. Mr. Steffes described
14 widespread problems with the rivets while Mr. Bland and Respondent
15 both testified that there were some rivet issues but only
16 affecting about three or four rivets that they were able to
17 observe when inspecting the aircraft in 2015.

18 With such widely varying testimony, what would have been
19 helpful in making a determination as to the extent of issues and
20 any impact on airworthiness was photographic or similar evidence
21 to supplement the testimonial evidence. Absent that, I conclude
22 that the Administrator has failed to carry his burden with respect
23 to those specific allegations; and again, I will address specific
24 allegations momentarily.

25 Now, with respect to the Form 337 at Exhibit A-4 for

1 installation of oil pressure and temperature kit including
2 instrument and sensors, Inspector Steffes testified that his
3 inspection revealed the sensors were attached directly at the
4 engine, which did not comply with the STC requirement, and that
5 the oil pressure and temperature gauge was mounted in the cockpit
6 in a location under the yoke where it could not be seen from the
7 pilot's seat. That testimony was essentially uncontradicted as
8 neither Respondent nor Mr. Bland testified regarding the location
9 of the sensor or the gauges.

10 Accordingly, I find that Respondent knowingly falsified
11 the information pertaining to installation of the oil pressure and
12 temperature kit in accordance with the identified STC.

13 Mr. Lawson did testify that he properly placarded the
14 gauges - including the tachometer, oil pressure and temperature
15 gauge, and sea level to altitude markings - before returning the
16 aircraft to service and also that he properly located the oil
17 pressure restrictor or transducer on the firewall, but that those
18 placards and the transducer must have been removed and/or
19 relocated afterwards.

20 I find that explanation unlikely, particularly in light
21 of the lack of logbook entries documenting maintenance to the
22 aircraft in the interim, the extent of problems identified, and my
23 earlier findings regarding Respondent's credibility as to his
24 explanation regarding the engine model and propeller entries.

25 With respect to the final Form 337 for installation of

1 the floatplane reinforcement kit, I find that a preponderance of
2 evidence establishes that the Form 337 was false in the sense that
3 the floatplane kit was not installed fully in accordance with the
4 Cessna drawing and was incomplete. As described by Mr. Bland in
5 his testimony, he found evidence that the kit was provisionally
6 installed. His description of what constituted provisional
7 installation is consistent with both Mr. Lawson and Mr. Steffes'
8 description of the nature of the installation and what was
9 observed. It is also consistent with the fact that floats were
10 never attached to the aircraft.

11 Mr. Bland testified initially that the Form 337 should
12 clearly identify the installation as provisional. As evidenced by
13 his change of position that reinforcement implied provisional
14 installation and Mr. Steffes' disagreement with that conclusion,
15 the evidence establishes to me that the form did not make clear
16 the provisional nature of the installation. While that may raise
17 issues as to the adequacy of the maintenance entry, I conclude
18 that it does not rise to the level of a knowing falsification.

19 Now, Respondent has raised a number of affirmative
20 defenses in his answer to the complaint, most notably the stale
21 complaint rule which he argued during closing argument. With
22 respect to the stale complaint rule, Rule 33 of the Board's Rules
23 of Practice provides that a complaint is subject to dismissal as
24 stale if it sets forth allegations of offenses which occurred more
25 than 6 months prior to the Administrator advising the Respondent

1 as to the reason for the proposed action under 49 U.S.C. Section
2 44709 unless the Administrator either establishes good cause for
3 the delay in providing such notice or presents an issue of lack of
4 qualification on the part of the certificate holder.

5 The Board has consistently held that where a legitimate
6 issue of lack of qualifications is raised, the complaint is not
7 subject to dismissal under that rule. Such an interpretation is
8 consistent with the plain language of the rule itself; and in
9 addressing the rule in Administrator v. Dill, which is at NTSB
10 Order EA-4099, it's a 1994 case, the Board noted that the rule is
11 meant to advance, not retard, safety enforcement, which is the
12 reason why even in the face of lengthy delay the Administrator is
13 permitted to proceed with cases that involve a lack of
14 qualifications.

15 With regard to whether the complaint alleges a lack of
16 qualifications, the Board has repeatedly held that an allegation
17 of intentional falsification is sufficient to raise an issue of
18 lack of qualification. Thus, I find that the complaint clearly
19 alleges a lack of qualifications and dismissal of the
20 Administrator's complaint as stale under the Rule 33 is not
21 warranted here.

22 Respondent also raised the doctrine of laches in his
23 answer to the complaint as an affirmative defense; although, aside
24 from a response to an objection during the hearing, he presented
25 no substantial evidence or made any substantial argument in that

1 regard. However, with respect to the doctrine of laches, the
2 Board precedent has recognized that the affirmative defense of
3 laches may be available even when the stale complaint rule is
4 inapplicable; and I would cite to *Manin v. National Transportation*
5 *Safety Board*, which is 627 F.3d 1239, it's a D.C. Circuit case,
6 2011; and also *Administrator v. Tinlin and White*, it's an NTSB
7 Order EA-5658. That's a 2013 case.

8 In *Manin*, the Court of Appeals for the D.C. Circuit
9 defined the doctrine as an equitable doctrine that applies where
10 there is, (1), a lack of diligence by the party against whom the
11 defense is asserted and, (2), prejudice to the party asserting the
12 defense. The Court indicated consideration of laches is required
13 if an airman could establish actual prejudice in his defense which
14 is attributable to the Administrator's delay.

15 Here Respondent has presented no evidence nor
16 articulated any specific argument as to any actual prejudice
17 suffered as a result of any delay. Much of the delay at issue
18 here was as a result of delay in the alleged violations being
19 brought to the attention of the Administrator. It appears that
20 the Administrator thereafter diligently pursued the investigation
21 and collected documentary and photographic evidence which it made
22 available to Respondent. Respondent was also able to present
23 drafts of prior field approval requests which he suggested
24 revealed an attempt to conceal or falsify evidence related to his
25 application, an allegation which I find no support for.

1 Thus, even if I were to find a lack of diligence on the
2 part of the Administrator, Respondent has failed to meet his
3 burden of establishing that actual prejudice in his ability to
4 defend against the Administrator's certificate action exists as a
5 result of the delay. Thus, I find the complaint is not barred by
6 the doctrine of laches.

7 There were other affirmative defenses raised in the
8 answer to the complaint, but no evidence or argument was presented
9 with respect to those, and I find Respondent has not met his
10 burden of establishing those affirmative defenses. Thus, I find
11 no basis for relief regarding any of those affirmative defenses.

12 I will address the NASA report issue separately, which
13 was raised as an affirmative defense I should note, but I think
14 applies to the sanction phase more appropriately, and I'll address
15 it there.

16 Based on the foregoing evidence and discussion, I make
17 the following findings with respect to the specific allegations in
18 the Administrator's complaint. The standard for my findings is
19 based on a preponderance of reliable, probative, and credible
20 evidence. My findings are based upon that standard.

21 1. Respondent has admitted paragraph 1 of the
22 complaint; thus, that is established.

23 2. I find that Respondent did make an entry in the
24 aircraft logbook on December 20th, 2012, certifying he made major
25 repairs and alterations to N5683T, a Cessna Model 172E, Serial

1 Number 17251583.

2 I find that the evidence establishes that the registered
3 owner of that aircraft is Mr. William Boodt of Gobles, Michigan.

4 The evidence establishes that on or about December 20th,
5 Respondent made a logbook entry in the aircraft maintenance record
6 for N5683T stating that he certifies that the aircraft has been
7 inspected in accordance with the annual inspection and determined
8 to be in airworthy condition.

9 5. The evidence establishes that the above entry was
10 signed by Respondent using his signature and certificate number.

11 6. Respondent described completion of multiple tasks in
12 the above maintenance entry:

13 A. Installation of a Continental engine model IO-360-G
14 in accordance with Supplemental Type Certificate
15 SA00728SE and field approval dated 7/22/11 citing to
16 the Form 337.

17 B. Installation of oil pressure and oil temperature
18 gauge in accordance with STC SA02825NY.

19 C. Repair the lower firewall using parts from an
20 aircraft of the same year and model.

21 D. Installation of a floatplane kit in accordance with
22 Cessna drawing 0500044.

23 E. Installation of a tail cone removed from aircraft of
24 the same model. Striking the words "year and."

25 F. Complied with FAR Section 91.207, AC 43.1&2; and

1 G. Aircraft was reassembled, rigged, and test flown.

2 7. The evidence establishes Respondent completed four
3 FAA Forms 337 certifying work specified in the above-described
4 logbook entry for N5683T. Those forms will be identified as Form
5 337-I, 337-II, 337-III, and 337-IV.

6 8. The evidence establishes each Form 337 for
7 identification (I), (II), (III), and (IV) is signed by Respondent
8 and dated December 26, 2012.

9 9. Form 337-I is stamped and signed by an FAA
10 inspector. The stamp is dated July 22, 2011, and notes that it is
11 subject to a conformity inspection by a person authorized under
12 FAR Part 43, Section 43.7.

13 10. Evidence establishes Forms 337-II, III, and IV are
14 not signed or stamped by the FAA.

15 11. In Form 337-I, Respondent certified the following
16 work, in relevant part, was accomplished:

17 A. Removed the original engine, propeller, and
18 firewall forward complete, installed Continental
19 Model IO-360-G, Serial Number 352609, in accordance
20 with STC SA00728SE;

21 B. Installed propeller McCauley 2A34C 203/90 DCA-12,
22 Serial Number 861575, in accordance with STC
23 SA00728SE and XP191388-II-172B-H, Revision 1R,
24 dated March 6, 2006;

25 C. Respondent made and entered an exception to the STC

1 to increase the propeller diameter from 76 inches
2 to 78 inches;

3 D. That supplemental document XP-172-2 dated May 1,
4 2006, was inserted into the aircraft flight manual
5 Form 337-I; and

6 E. Functional flight test was performed and all
7 operations were normal.

8 12. The evidence establishes that in Form 337-II,
9 Respondent certified the following work in relevant part was
10 accomplished:

11 A. Replaced the lower firewall and tail cone with
12 parts from the same model aircraft.

13 B. Put in fixture to assure alignment of fuselage and
14 tail cone.

15 C. Installed the lower firewall, installed the tail
16 cone, and aligned the tail cone with the fuselage
17 in accordance with Cessna manual and FAR AC 43.1&2.

18 13. In Form 337-III, Respondent certified the following
19 work in relevant part was accomplished: Installed oil pressure
20 and temperature kit including instrument, oil temperature sensor,
21 and oil pressure sensor in accordance with FAA STC SA02825NY.

22 14. In Form 337-IV, Respondent certified the following
23 work in relevant part was accomplished: Installed the floatplane
24 reinforcement kit in accordance with Cessna drawing 0500044 and
25 Advisory Circular 43.13-1&2.

1 15. That on or about March 17th, 2014, an annual
2 inspection of N5683T was begun by a different repair station that
3 resulted in the FAA inspecting N5683T and its maintenance record,
4 striking the word "performed."

5 16. With respect to paragraph 16, the evidence
6 establishes the FAA investigation revealed the following
7 discrepancies with the work certified in maintenance log for
8 N5683T and Form 337 and the Forms 337 referenced:

9 With respect to the subparagraph (a), I find that the
10 evidence does not establish by a preponderance of evidence that
11 special engine mounts required by STC were not installed;

12 Paragraph (b), I find the evidence does not establish
13 that engine mounts used on N5683T were rejected by the STC holder
14 for welds that did not meet STC specifications;

15 As to paragraph (c), I find the evidence establishes
16 that engine placard identifies the engine as a Model IO-360-G-C-K
17 and was known to be a Model IO-360-K when installed in N5683T
18 although STC SA00728SE calls for a Model IO-360-G;

19 With respect to subparagraph (d), I find the tail cone
20 installed was not from an aircraft of the same model as N5683T.
21 As the tail cone placard indicated, it was from a Cessna R172K
22 with a serial number of 17257583; therefore, rivet holes did not
23 align;

24 With respect to subparagraph (e), I find the
25 preponderance of evidence does not establish that new rivets for

1 the tail cone was not installed in accordance with Advisory
2 Circular 43.13-1B, Chapter 4, when the new rivets were installed
3 next to or overlapping existing rivet holes in the fuselage;

4 With respect to subparagraph (f), I find that the
5 evidence does not establish that the brackets used for the tail
6 cone installation appear to have tool damage;

7 Subparagraph (g), the evidence establishes that the new
8 rivets for the lower firewall were aluminum rather than stainless
9 steel as required by Cessna 100 series structural repair manual;

10 Paragraph (h), the evidence establishes no sealant was
11 installed for the lower firewall rivets;

12 Subparagraph (i), I find the evidence does not establish
13 by preponderance that lower firewall rivet edge distance did not
14 comply with Advisory Circular 43.13-1B, Chapter 4;

15 Subparagraph (j), the evidence establishes that the
16 brackets used for the lower firewall installation did not have
17 finished edges and appeared to be cut from bulk material;

18 Paragraph (k), the evidence establishes brackets used
19 for the lower firewall had overlapped rivet heads;

20 Subparagraph (l), the evidence establishes the
21 floatplane or seaplane kit was installed simultaneously with STC
22 SA00728SE kit installation although a floatplane seaplane version
23 of the STC was not certified;

24 Paragraph (m), the evidence establishes installation of
25 a propeller with a diameter of 80 inches violates the STC which

1 requires a standard propeller diameter of 76 inches with a
2 permissible deviation to a maximum of 78 inches;

3 Subparagraph (n), the evidence establishes that an
4 alternator noise filter was not installed in accordance with STC
5 Instruction 1(d);

6 Paragraph (o), evidence establishes a fuel pump switch
7 on throttle arm at the body was not installed in accordance with
8 STC Instruction 4(b);

9 (p), evidence establishes a oil pressure restrictor
10 fitting was not installed in accordance with STC Instruction 4(j);

11 Paragraph (q), evidence establishes that alternate air
12 cable was not installed in accordance with the STC and a spring-
13 loaded alternate air door was installed not approved by STC
14 Instruction 4(l).

15 Paragraph (r), evidence establishes that engine
16 instruments were not marked with green, yellow, and red range
17 markings consistent with Instructions 10a through 10f.

18 Paragraph (s), the evidence establishes that the sea
19 level to altitude gallons per hour placard was not installed in
20 accordance with STC Instruction 13.

21 And subparagraph (t), the evidence establishes an off/on
22 switch was installed for a fuel pump control instead of the
23 high/low/off switch called for by STC SA02825NY.

24 With respect to the subparagraph (u), the evidence does
25 not establish that the exhaust or muffler system was not installed

1 in accordance with the STC. In fact, there was little or no
2 evidence presented by the Administrator with respect to the
3 exhaust system and allegation in subparagraph (u), so I find that
4 the Administrator failed to carry the burden with respect to that
5 subparagraph.

6 17. Evidence establishes that Respondent admitted
7 that he had not installed the aft fuselage and had failed to
8 record who had done the work in the maintenance records. Again,
9 that testimony was largely uncontradicted. Mr. Steffes testified
10 regarding Respondent's admissions in that regard, and there was no
11 testimony on that issue from Respondent or others.

12 18. Evidence establishes that the FAA investigation
13 revealed that STC SA00728SE was unavailable from its owner between
14 the years 2008 and 2013; and, thus, an authorized STC could not
15 have been legally obtained and complied with in December of 2012.
16 Respondent did not hold the STC and did not have written
17 permission from the holder.

18 19. Evidence establishes that Respondent certified on
19 Form 337-I that a propeller of 78 inches in diameter was installed
20 on N5683T; however, an 80-inch diameter propeller was installed.

21 20. On or about April 2nd, 2014, Respondent
22 acknowledged that he knew the approved deviation from the STC was
23 up to 78 inches and the 80-inch propeller was impermissible.

24 21. Evidence establishes that the discrepancies listed
25 in the paragraphs above rendered N5683T unairworthy at the time

1 that Respondent certified the aircraft as airworthy, and that
2 obviously pertains only to those paragraphs or subparagraphs that
3 have been established by the evidence. And specifically I find
4 that as a result of those, the aircraft did not meet its type
5 design and therefore was unairworthy and I need not reach a
6 conclusion or decision on if or how that affected safety of
7 flight.

8 22. Discrepancies listed in paragraph 16 (a) to (u) --
9 and again that is with respect only to those that I found that the
10 evidence has established. But as to those that the evidence has
11 established by preponderance, those discrepancies are such that
12 the STC SA00728SE, even if Respondent had been authorized to
13 utilize it, was not followed prior to returning N5683T to service
14 on December 20, 2012.

15 23. Respondent failed to make entries in the logbook
16 for N5683T identifying persons other than Respondent who performed
17 preventive maintenance and/or altered the airframe, engine, or
18 propeller component parts of N5683T.

19 24. On December 20, 2012, Respondent made an
20 intentionally false entry in N5683T's aircraft maintenance record,
21 to wit, the maintenance entries described in paragraph 6 above.
22 And with respect to that finding and consistent with my earlier
23 discussion, the specific subparagraphs that I find to constitute
24 an intentionally false entry are with respect to subparagraphs 6A,
25 B, D, and E, and with the modification as noted to subparagraph E,

1 echo.

2 25. The evidence establishes that on December 20, 2012,
3 Respondent concealed the true condition of the aircraft by way of
4 a false entry described in paragraphs 4 to 6, or made an entry
5 without inspecting N5683T in a manner which met all applicable
6 airworthiness requirements, the entry indicating the inspection
7 was completed, thereby being false.

8 26. December 26, 2012, Respondent made intentionally
9 false entries in multiple FAA Forms 337, to wit, maintenance
10 entries which were described in paragraph 10. And again, that is
11 with respect to my specific findings and limited to my specific
12 findings as to those enumerated in Forms 337.

13 27. I do find that National Transportation Safety Board
14 precedent has long held that a mechanic who does not ensure the
15 scrupulous accuracy of his representations and records on which
16 air safety critically depends cannot be said to possess the
17 necessary care, judgment, and responsibility required of a
18 certificate holder.

19 And based on those specifically enumerated findings, I
20 find that Respondent committed the following violations: A
21 violation of 14 C.F.R. Section 43.12(a)(1); 14 C.F.R. Section
22 43.13(a) and (b); 14 C.F.R. Section 43.15(a)(1); and 14 C.F.R.
23 Section 43.9(a)(3).

24 With respect to the alleged violation of 14 C.F.R.
25 Section 91.403(d), I do not find a violation of that section.

1 Now, having found that the Administrator has proven
2 those specifically enumerated allegations by a preponderance of
3 reliable, probative, and credible evidence, I turn now to the
4 sanction imposed by the Administrator in this case.

5 On August 3rd, 2012, Public Law 112-153, also known as
6 the Pilot's Bill of Rights, was signed into law by the President.
7 The law applies to all cases before the National Transportation
8 Safety Board involving reviews of actions of the Administrator of
9 the Federal Aviation Administration to deny airman medical
10 certification under 49 U.S.C. Section 44703, or to amend, modify,
11 suspend, or revoke airman certificates under 49 U.S.C. Section
12 44709. That law became effective immediately upon its enactment.

13 It specifically strikes from 49 U.S.C. Section 44709 and
14 44710 language that in cases involving amendments, modifications,
15 suspensions, or revocation of airman certificates, the Board is,
16 "bound by all validly adopted interpretations of law and
17 regulations the Administrator carries out and of written agency
18 policy guidance available to the public relating to sanctions to
19 be imposed under this section unless the Board finds an
20 interpretation as arbitrary, capricious, or otherwise not
21 according to law."

22 Now, while I am no longer bound to give deference to the
23 Federal Aviation Administration by statute, that agency is
24 entitled to judicial deference due all other federal
25 administrative agencies under the Supreme Court's decision in

1 Martin v. Occupational Safety and Health Review Commission. That
2 is at 499 U.S. 144, 111 S.Ct. 1171.

3 Now in applying the principle of judicial deference to
4 the interpretations of laws, regulations, and policies that the
5 Administrator carries out, I must analyze and weigh the facts and
6 circumstances in each case to determine if the sanction selected
7 by the Administrator is appropriate.

8 In the case before me, the Administrator has argued that
9 the appropriate sanction based on deference to FAA sanction
10 guidelines and past precedent is revocation of Respondent's A&P
11 certificate and inspection authorization; that even one
12 intentional falsification demonstrates a lack of qualifications to
13 hold any airman certificate.

14 Respondent has made no specific argument with respect to
15 deference to the Administrator, but has argued that the evidence
16 established that there was no intentional falsification and that
17 revocation is not appropriate. Respondent also asserted that any
18 sanction imposed should be waived as a result of Respondent filing
19 a NASA report under the Aviation Safety Reporting Program, or
20 ASRP.

21 Now, I find this case to be consistent with Board
22 precedent which holds that an individual who does not ensure the
23 scrupulous accuracy of his representations and records on which
24 air safety critically depends cannot be said to possess the
25 necessary care, judgment, and responsibility to hold a

1 certificate. That is based on the decision in Administrator v.
2 Morse, which is NTSB Order EA-3766, and that's a 1992 case.

3 Further, Board precedent firmly establishes that even
4 one intentional falsification compels a conclusion that the
5 falsifier lacks the necessary care, judgment, and responsibility
6 required to hold any airman certificate. That precedent stems
7 from the case of Administrator v. Berry, NTSB Order EA-2689, which
8 is a 1988 case; and since that time the Board has found and
9 continues to find that even one intentional falsification compels
10 a conclusion that the falsifier lacks the necessary care,
11 judgment, and responsibility required to hold any airman
12 certificate.

13 Now, with respect to the NASA report and any waiver of
14 sanctions under the Aviation Safety Reporting Program, Advisory
15 Circular 00-46E sets forth guidelines for that Aviation Safety
16 Reporting Program. That advisory circular makes it clear that
17 waiver of sanction is appropriate only in cases that do not
18 involve an issue of lack of qualifications. And consistent with
19 my findings above, I find that this case does raise an issue of
20 lack of qualifications, and therefore waiver of sanction under the
21 ASRP is not appropriate. Further, the guidelines require that any
22 NASA report filed be filed within 10 days of the violation or of
23 Respondent being aware or when he should have been aware of the
24 violation, and I find that Respondent was aware or should have
25 been aware of the violation as of March 25th or 26th, which is

1 more than 10 days before the NASA report was filed.

2 Therefore, I find that the sanction sought by the
3 Administrator is appropriate and warranted in the public interest
4 in air commerce and air safety; therefore, I find that the
5 Administrator's order, the complaint herein, shall be affirmed as
6 issued.

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26

ORDER

It is hereby ordered that the Emergency Order of Revocation, the complaint herein, be, and is hereby, affirmed; that Respondent's mechanic certificate with airframe and powerplant ratings and inspection authorization are hereby revoked.

Entered this 11th day of June, 2015, in Chicago, Illinois.



EDITED ON

STEPHEN R. WOODY

July 8, 2015

Administrative Law Judge

1 APPEAL

2 ADMINISTRATIVE LAW JUDGE WOODY: That concludes my Oral
3 Initial Decision. Mr. Lawson, you have certain appeal rights.
4 You can appeal my decision. Your counsel may have discussed those
5 with you and I'm sure will discuss those with you at some point.

6 I have here for you, Mr. Hahn, a written copy of the
7 appeal rights. I'm going to hand you two copies -- actually I'm
8 going to hand you three copies. I would ask you to give one copy
9 to the Administrator's counsel. There's one for you and one for
10 your client. I have a copy that I will hand to the court reporter
11 momentarily for insertion in the record.

12 Mr. Hahn, do you desire that I provide any sort of oral
13 advisement of his appeal rights on the record or will you handle
14 that?

15 MR. HAHN: I will handle that, Your Honor.

16 ADMINISTRATIVE LAW JUDGE WOODY: All right. Thank you.
17 The one thing I would emphasize, and obviously you know
18 this, Mr. Hahn, but just -- Mr. Lawson, for your benefit, is just
19 the importance, if you decide to file an appeal, of the deadlines
20 that are set forth in the written appeal rights. Those are
21 generally hard and fast, as I'm sure your counsel will tell you.
22 So those are important deadlines to keep in mind and to meet if
23 you desire to file an appeal of my decision.

24 So with that, Counsel, is there anything of an
25 administrative nature that we need to discuss before we terminate

1 the proceedings?

2 MS. HOYSON: No, your Honor.

3 MR. HAHN: I had two issues of clarification, your
4 Honor. At the outset of your opinion, you mentioned that this
5 trial was taking place in New York City.

6 ADMINISTRATIVE LAW JUDGE WOODY: Did I say that?

7 MR. HAHN: Yes.

8 ADMINISTRATIVE LAW JUDGE WOODY: I'm sorry. Obviously
9 we are in Chicago, Illinois.

10 MR. HAHN: And then with regard to your reference to
11 paragraph 26, that the false entries referred to in paragraph 10
12 on the 337s were false, the ones referred to in paragraph 10,
13 paragraph 10 refers to the 337s 2, 3, and 4 only?

14 ADMINISTRATIVE LAW JUDGE WOODY: Correct.

15 MR. HAHN: So that's your finding as to 2, 3, and 4
16 only?

17 ADMINISTRATIVE LAW JUDGE WOODY: Correct. I made
18 individual findings with respect to the allegations, and my -- the
19 discussion that I provided with respect to the evidence, the
20 overall evidence in the case obviously addressed those various
21 337s. So and I believe I addressed each of those individually and
22 made specific findings as to evidence that related to allegations
23 under those. The complaint is somewhat cumbersome, and so I tried
24 to enumerate my specific findings as I went through the evidence;
25 and I think I did that because I talked about each of those 337s.

1 So what I intended with respect to my -- paragraph 26 was just to
2 indicate that my findings as to paragraph 26 were to be considered
3 in conjunction with and consistent with the specific findings I
4 made as to the evidence supporting that.

5 Does that make sense, or is that more confusing to you?

6 MR. HAHN: I guess I'm trying to determine if you went
7 beyond what the complaint alleged for falsification on 337 number
8 1 or if you're just referring to what is alleged in the complaint.

9 ADMINISTRATIVE LAW JUDGE WOODY: Well, in terms of my
10 findings with respect to paragraph 10, I don't think I went beyond
11 the complaint. I made some specific findings obviously with
12 respect to the Forms 337 and the falsifications that I found
13 thereunder. And again, I think that has to do with the cumbersome
14 nature of the complaint itself and trying to work through each of
15 those allegations. So I don't know how to address that any more
16 clearly only because I think it is perhaps subject to
17 interpretation.

18 MR. HAHN: Thank you.

19 ADMINISTRATIVE LAW JUDGE WOODY: So I hope that helps.
20 I'm not trying to be evasive. I just think that's the best answer
21 I can provide to you.

22 All right. Anything else?

23 MR. HAHN: No, your Honor.

24 ADMINISTRATIVE LAW JUDGE WOODY: Okay. All right.
25 Well, thank you very much. I know it's been -- and again, my

1 apologies for keeping everyone waiting. It took just a bit more
2 time than I anticipated to get my thoughts together. So I
3 appreciate your professionalism and attentiveness the last couple
4 of days.

5 Mr. Lawson, good luck to you, sir.

6 With that, we'll terminate the proceedings. Thank you
7 very much.

8 (Whereupon, at 6:39 p.m., the hearing in the above-
9 entitled matter was adjourned.)

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

CERTIFICATE

This is to certify that the attached proceeding before the

NATIONAL TRANSPORTATION SAFETY BOARD

IN THE MATTER OF: Matt Lawson
DOCKET NUMBER: SE-19747
PLACE: Chicago, Illinois
DATE: June 11, 2015

was held according to the record, and that this is the original,
complete, true and accurate transcript which has been compared to
the recording accomplished at the hearing.

Rhonda Weiland
Official Reporter