

The Role of Aircraft Type Clubs in LOC-I Prevention Transition Training LOC-I in IMC




Thomas P. Turner
Executive Director, ABS Air Safety Foundation
President, Mastery Flight Training, Inc.
October 14, 2015



What is a Type Club?

- Represents and supports owners and operators of a specific *type*, make and model or family of aircraft.
- Usually volunteer-run, with exceptions among the more numerous aircraft types.
- Emphasis is usually on technical support and information sharing, safety and social activities.
- Some type clubs also actively teach pilots, flight instructors and mechanics.



www.eaa.org/typeclubs

- Over 35 member organizations
- Pilot training best practices for type-specific transition and recurrent training



TYPE CLUB COALITION

GA-JSC Request for Input: Best Practices for Teaching Balked Landing/Missed Approach Procedures
October 2, 2012

The General Aviation Joint Steering Committee (GA-JSC) has requested the Type Club Coalition provide industry best practices for teaching Balked Landing (Go-Around) and Missed Approach procedures to support the GA-JSC's work toward reducing accidents in those phases of flight. TCC polled its member organizations and received two responses detailing their recommended procedures:

T-34 Association (www.t-34.com)

The T-34 Association teaches the original U.S. Navy (NATOPS) checklists for the type:

WAVE OFF/GO AROUND

1. Throttle – FULL OPEN
2. Establish positive rate of climb (V_y) – 70 KIAS
3. Gear – AS REQ'D
4. Flaps – UP at 200 FT AGL or above

The NATOPS checklist does not provide a missed approach procedure.

American Bonanza Society (www.bonanza.org)

The American Bonanza Society's Beechcraft Pilot Proficiency Program (BPPP) teaches a "By the Numbers" (BTN) approach to all phases of flight. BTN defines power settings, pitch attitudes and aircraft configurations (flaps and landing gear position) for desired performance in each flight phase. The BTN technique enhances, but does not replace, manufacturer's guidance. BPPP teaches these procedures:

BALKED LANDING

From short final with flaps down and airspeed close to touchdown speed:

- Simultaneously add full power (mixture, prop, throttle) and pitch up to $+10^\circ$.
- Apply right rudder to keep the ball centered.
- With positive climb, raise flaps to approach position (approximately 20° extension in airplanes without an approach flap preselect).
- Raise the gear.
- Maintain positive climb, flaps up.
- Accelerate to V_y minimum. (V_x with an obstacle)

MISSED APPROACH

From the approach descent configuration, assumes missed approach from DH/DAMDA:

- Simultaneously, add full power (mixture, prop, throttle) and pitch up to:
 - Bonanza/Debonair $+8^\circ$.
 - Baron/Travel Air/Duke $+12^\circ$.
- Resulting airspeed will be slightly greater than V_y .
- No trim change should be required.
- With positive climb, raise the gear.
- Be in no hurry to raise the flaps (if approach flaps used).
- A small trim change may be required after flap retraction.

Industry Best Practices

From these we can begin to derive some industry best practices for conducting a balked landing or missed approach:

1. There are subtle differences between a balked landing/go-around and a missed approach, notably, the initial airspeed target and the flap position at the beginning of the procedure. Regularly practice and utilize the checklist procedure for each operation as required.
2. Be prepared for a balked landing or missed approach at any time during every landing attempt.
3. For instrument approaches, commit to memory what defines the Missed Approach Point (MAP), the initial missed approach heading, and the altitude to reach before making any turns in the missed approach, before passing the Final Approach Fix (FAF) inbound. Note these items on a kneeboard or other quick-reference location for verification if needed, without having to find the data on the approach chart while flying the approach.
4. Use all heading and altitude reminders available in the aircraft on all instrument approaches.
5. Follow airplane manufacturer's guidance and checklists when available.
6. Use preplanned power settings, pitch attitudes and airspeeds when performing a balked landing or missed approach.
7. When possible, fly instrument approaches at the missed approach/initial climb indicated airspeed. This means there will be little or no change in trim setting with application of power at the beginning of a missed approach in most airplane types. With a constant trim setting, most airplanes will tend to pitch to the proper attitude and airspeed with the application of missed approach power, making it easier to maintain control during this high-workload transition.
8. Consistent with manufacturer's guidance, retract flaps to an intermediate/approach position if flaps are at full extension when beginning the balked landing or missed approach procedure.
9. In a retractable gear airplane, retract the landing gear after achieving a positive rate of climb, unless manufacturer's guidance directs delaying gear retraction.
10. Know beforehand the expected trim change necessary after flaps and/or gear retraction.
11. Be proficient and current in the operation of navigation systems, especially the SUSPEND or similar modes of GPS units, before flying an instrument approach using those systems.
12. Act deliberately and positively, without undue delay, but do not be rushed or abrupt when transitioning from descent to climb in a balked landing or missed approach.
13. As in all other situations, aviate, navigate and communicate, in that order.


Please let us know if you have questions, and how we can provide additional assistance.

Thomas P. Turner,
Chairman, Type Club Coalition
Executive Director, ABS Air Safety Foundation
asf@bonanza.org
316-945-1700

Type Club Membership and Accident Rates

- Doctoral research correlating type club membership to NTSB accident report rates
- Positive correlation between type club membership and reduced accident rates
- Do type clubs make pilots safer? Or do safer pilots join type clubs?

Available online at <http://docs.lib.purdue.edu/jate>



JATE

Journal of Aviation Technology and Engineering 5:1 (2015) 7-16

The Efficacy of Aircraft Type Club Safety

William Jeffrey “Jeff” Edwards

Saint Louis University

The Challenges of Teaching LOC-I

1. Defining Loss of Control

LOSS OF CONTROL-INFLIGHT (LOC-I)

Loss of aircraft control while, or deviation from intended flightpath, in flight.

Loss of control in flight is an extreme manifestation of a deviation from intended flightpath. The phrase "loss of control" may cover only some of the cases during which an unintended deviation occurred.

Usage Notes:

- Used only for airborne phases of flight in which aircraft control was lost.
- Loss of control can occur during either Instrument Meteorological Conditions (IMC) or Visual Meteorological Conditions (VMC).
- The loss of control during flight may occur as a result of a deliberate maneuver (e.g., stall/spin practice).
- Occurrences involving configuring the aircraft (e.g., flaps, slats, onboard systems, etc.) are included as well as rotorcraft retreating blade stall.
- Stalls are considered loss of control and are included here.
- Rotorcraft occurrences which involve power settling (vortex ring), or settling with power to ground contact are coded here and as Abnormal Runway Contact (ARC) if during normal landing or takeoff.
- Rotorcraft External Load operations involving loss of control related to the external load should be coded as LOC-I as well as External Load Related Occurrences (EXTL).
- Includes Rotorcraft "Loss of Tail Rotor Effectiveness."
- Includes loss of control during practice or emergency autorotation.
- Includes pilot-induced or assisted oscillations.
- For unmanned aircraft events, includes hazardous outcomes involving deviation from intended flightpath associated with anticipated or unanticipated loss of datalink. However, if loss of datalink is the direct result of a system/component failure or malfunction, code the occurrence as System/Component Failure or Malfunction (Non-Powerplant) (SCF-NP) only.
- For icing-related events, which are also loss of control, code both LOC-I and Icing (ICE).
- If the loss of control is a direct result of a system/component failure or malfunction (SCF), code the occurrence as an System/Component Failure or Malfunction (Non-Powerplant) (SCF-NP), or System/Component Failure or Malfunction (Powerplant) (SCF-PP) only. However, loss of control may follow less severe system/component failures, and in this case, code both categories.
- Cockpit crew vision-related events and flight in degraded visual environments (for example, obscuration, black hole approach events, brownouts, or whiteout events), in which the aircraft is flown under control into terrain, water, or obstacles, are coded under Controlled Flight Into or Toward Terrain (CFIT), not LOC-I.

The Challenges of Teaching LOC-I

1. Defining Loss of Control
2. Teaching use of Angle of Attack indicators



The Challenges of Teaching LOC-I

1. Defining Loss of Control
2. Teaching use of Angle of Attack indicators
3. Traditionally equipped airplanes





The American Bonanza Society's Beechcraft Pilot Proficiency Program (BPPP)

Guide to Initial Pilot Checkout: IO-520

Beechcraft Bonanzas and Debonairs Originally Equipped with Continental Motors

Models S35, V35, V35A, V35B, C33A, E33A, E33C, F33A, F33L

Revision 1 November 2012



U.S. Department of Transportation
Federal Aviation Administration

Advisory Circular




Subject: Transition to Unfamiliar Aircraft

Date: 6/29/15

AC No: 90-109A

Initiated by: AFS-800

Change:



NTSB ECPT Initial Pilot Training Panel
10/14/2015

Models 58P and 58TC

December 2012

November 2012

DOT/FAA/AM-02/19

Office of Aerospace Medicine
Washington, DC 20591

**General Aviation Pilot Performance
Following Unannounced In-Flight
Loss of Vacuum System and
Associated Instruments in
Simulated Instrument
Meteorological Conditions**

Kathleen M. Roy
Aircraft Owners and Pilots Association
Air Safety Foundation
421 Aviation Way
Frederick, MD 21701
Dennis B. Beringer
Civil Aerospace Medical Institute
Federal Aviation Administration
Oklahoma City, OK 73125

October 2002

Final Report

This document is available to the public
through the National Technical Information
Service, Springfield, VA 22161.



U.S. Department
of Transportation
**Federal Aviation
Administration**

LOC in IMC: Partial Panel Flight

- 2002 FAA/AOPA study DOT/FAA/AM-02/19

LOC in IMC: Partial Panel Flight

Table 3. Mean recognition time per pilot group.

<i>Pilot Group</i>	<i>Average time to recognize failure (minutes)</i>
Archer A	7.3
Archer B	4.9
Archer C	7.9
Bonanza A	4.6*
Bonanza B	2.6*

Note:

* The only significant difference was between these means. Archer A pilots used standard Archer instrumentation.

Archer B pilots received 30 minutes of partial panel PCATD training prior to their flight.

Archer C pilots had a vacuum annunciator light as a warning when the vacuum system failed.

Bonanza A pilots experienced an AI failure.

Bonanza B pilots experienced both AI and HSI failures.

- 2002 FAA/AOPA study DOT/FAA/AM-02/19
- The average time from failure to recognition ranged from **2.6 minutes** with instrument warning flags to **7.3 minutes** without warning besides the instrument air/vacuum gauge


LOC in IMC: Partial Panel Flight

- Recognition
- Diagnosis
- Control



LOC in IMC: Partial Panel Flight

- Recognition
- Diagnosis
- Control



LOC in IMC: Partial Panel Flight

- Recognition
- Diagnosis
- Control



LOC in IMC: Missed Approach

ABS/BPPP Guide to Initial Pilot Checkout: Normally Aspirated Barons



AIR SAFETY FOUNDATION

The American Bonanza Society's Beechcraft Pilot Proficiency Program (BPPP)


Guide to Initial Pilot Checkout: Normally Aspirated Barons

Models: A44, A44B, A44C, C44, C44B, C44C, SR, C44B

By the Numbers: Power, Attitude, Configuration (PAC) Chart Normally Aspirated Barons

	RPM	ATTITUDE	GEAR	FLAPS	KIAS	VSI	TRIM
	MAX	+7°	UP upon positive rate	UP	Per POH		
Cruise climb	FT	2500	+7°	UP	UP	120	
Cruise	As desired	As desired	Level	UP	UP	XXX	
En route descent	As desired	As desired	-2°	UP	UP	Green arc	
Approach (level)	15" 17"	2300 - 2500	+0° +2°	UP	UP APPROACH	120	
Precision descent	15" 17"	2300 - 2500	+0° +2°	DOWN	UP APPROACH	120	
Nonprecision descent	13" 15"	2300 - 2500	+0° +2°	DOWN	UP APPROACH	120	
MDA level	20" 22"	2300 - 2500	+0° +2°	DOWN	UP APPROACH	120	
Missed approach	FT	2500	+7°	UP	UP	120	
Single engine climb (prop windmilling)	FT	MAX	+3°	UP	UP	Vyse (Blue line)	
Single engine climb (prop feathered)	FT	MAX	+7°	UP	UP	Vyse (Blue line)	

Reducing manifold pressure by one inch results in a roughly 100-fpm descent.
A 5-inch reduction in MP results in a 500 fpm descent.



Pilot Training Panel

10/14/2015

LOC in IMC: Missed Approach

NTSB Identification: CEN11FA302

14 CFR Part 91: General Aviation

Accident occurred Friday, April 22,
2011 in Topeka, KS

Probable Cause Approval Date: 12/05/2012

Aircraft: BEECH 58, registration: N580EA

Injuries: 4 Fatal.

LOC in IMC: Missed Approach

NTSB Identification: CEN11FA302



LOC in IMC: Missed Approach

If you're not on altitude, on course, on speed and in airplane configuration when reaching the Final Approach Fix, do not begin your descent toward the runway. Ask for a hold or a vector while you get prepared. Don't think you can "catch up" while flying the approach.

If you *begin* a missed approach procedure, *fly* the missed approach procedure—even if you subsequently see the runway.

If you miss an approach, climb to the missed approach altitude and enter the hold before trying to set up for, brief and fly a different approach.

If you ask for something (e.g., the GPS 36 approach) and are directed to do something else (the GPS 31 approach), decline the new instructions until everyone's sure that's what you want to do, and you have time to fully prepare.

In IMC, single-engine versus multiengine is less important than familiarity with the airplane being flown, and *much* less important than familiarity with the avionics being used.

The Role of Aircraft Type Clubs in LOC-I Prevention Transition Training LOC-I in IMC



Thomas P. Turner
Executive Director, ABS Air Safety Foundation
President, Mastery Flight Training, Inc.
October 14, 2015

