

National Transportation Safety Board

Sinking of Cargo Vessel *El Faro*Atlantic Ocean, Northeast of Acklins and Crooked Island, Bahamas
October 1, 2015

Brian Young Investigator-in-Charge



Engineering Factors

Brian Young Investigator-in-Charge

Overview – Engineering Factors

- Vessel history
- Major conversion
- Inspections
- Exclusions
- Loss of propulsion



Vessel History

Brian Young Engineering Group Chairman



El Faro



Major Conversion Determination

- Major vessel conversions:
 - Substantially alter stability characteristics, dimensions, or carrying capacity of vessel
 - Change the type of vessel
 - Substantially prolong the vessel's service life

 Major conversions require the vessel to be updated to current safety standards

Major Conversion Determination

- El Faro's lengthening in 1993 was a major conversion
 - Added 90-foot mid-body section
- El Faro's conversion from Ro/Ro to Ro/Con in 2005-2006
 - Added capacity for 1,414 containers
 - Increased draft/lowered freeboard over 2 feet
- After request for reconsideration from company, Ro/Conmodification not designated as a major conversion



Alternate Compliance Program

Brian Young Engineering Group Chairman



Alternate Compliance Program





- ACP avoids redundancies in Coast Guard and authorized classification society (ACS) inspections and surveys
- Coast Guard issues Certificate of Inspection (COI) after ACS verifies compliance with applicable standards
- "US supplement" bridges gap between Coast Guard and ACS standards
- Annual Coast Guard oversight examinations of ACP vessels to confirm ACSs are enforcing compliance

Alternate Compliance Program

- No qualification level required and no formal training program for the Coast Guard ACP examiners
- Communications between Coast Guard and ACSs lacking
- Lack of resources to complete "US supplement" reviews
- Review of targeted ACP vessels that had successfully completed ACS surveys found safety deficiencies; lacked deficiency records



Exclusions

Brian Young
Engineering Group Chairman

Exclusions

- Not factors in accident:
 - Boilers, steering, and electrical systems
 - Riding gang
 - Medical conditions and medication use
 - Structural failure
 - Rogue wave

Exclusions

- Not factors in initial list of vessel:
 - Lashing failure
 - Cargo shift

- Insufficient evidence to determine:
 - Fatigue
 - Drug or alcohol use



Loss of Propulsion

Brian Young Engineering Group Chairman



Loss of Propulsion

0440/0513 – Chief Engineer reported oil levels affected by list

0554 – Captain turned *El Faro* to port


After 0600 – Vessel began losing speed

0616 – Bridge notified of loss of propulsion


Lube Oil System



Lube Oil System



Lube Oil System




Design Standards




Extreme list to port

Design Standards



18° list to port – looking forward

Oil Level in Sump




25" = 1,255 gallons

26" = 1,346 gallons

27" = 1,436 gallons

18° List to Port



Summary – Engineering Factors

Findings

Recommendations