



# National Transportation Safety Board

## Flooding of Cargo Holds

Eric Stolzenberg

Naval Architecture Group Chairman


# Overview

- Increasing seas and waves, resultant windheel
- Flooding sources
- Car lashings
- Bilge pumping
- Bilge high-level alarms in cargo holds
- Watertight hatch open/closed indicators
- Cargo hold ventilation closures
- Hull wreckage examination

# Increasing Seas


- Seas increase rapidly after 0130
- Over 7 meters (23 feet) by 0300
- Build to 9 meters (30 feet)
- Wave period of 11 seconds

**Analysis of Post-Storm (Hindcast Data) Sea/Weather Models  
Along *El Faro's* Track**




# Sustained Windheel

- Increasing winds after 0200 on vessel's port beam
- Wind near 70 knots by 0400
- Effect: increasing and sustained heel (windheel) to starboard
- Hydrostatic analysis shows heel from 5° to 8° for winds 60 to 80 knots on beam




# Watertight Deck



- Boarding seas (green water) was known to enter onto 2<sup>nd</sup> deck in past
- Partially enclosed 2<sup>nd</sup> deck was watertight

# Dynamic Analysis





# Downflooding from Watertight Scuttle (Deck Hatch)

- Hold 3 was flooding at 0543 per VDR
- Small watertight deck hatch (scuttle) to cargo hold 3 on second deck was open
- Open scuttle allowed downflooding through ship's watertight envelope



# Unsecured Scuttle to Hold 3


- Crew did not know when or how scuttle to hold 3 opened
- If bridge had open/close indicator, crew would have known scuttle was open



*El Faro Scuttle*



# El Faro Cargo Hold 3



# Cargo Hold 3 Tanktop (4<sup>th</sup> Deck)



Supply Ventilation  
Trunks (Upper)

Hold  
2A


Lower Supply  
Ventilation Trunk

*El Yunque Hold 3*



# Automobile Lashings in Hold 3

- Automobile lashings did not conform to cargo-securing manual
- Cars were more likely to shift during heavy weather




# Flooding Effect on Car Lashings

- Adverse effects:
  - Small amount of water decreases friction
  - Rising water begins to float cars
  - Mass of sloshing water acts on cars
- Crew said cars were loose
- Water plus vessel's motion loosened cars

# Seawater Inlet Piping to Emergency Fire Pump

- Cars loose in hold 3 at 0544
- Bilge pumps already running
- Scuttle secured about 0600, but hold 3 still flooding
- Piping to fire pump possible source of flooding
- Loose cars could have struck piping to fire pump





# Hold 3 Flooding Effect

- Damaged piping potentially flooded hold 10% to 20% by 0716
- MSC hydrostatic analysis
  - Beam-to 80-knot wind after loss of propulsion
  - Hold 3 flooded 10% to 30%
  - Rolling about sustained windheel
  - Vessel susceptible to capsizing
- Damage to seawater piping in hold 3 most likely led to flooding in the hold, which significantly compromised vessel's stability

# Bilge Pumping

- Two bilge wells per cargo hold (port and starboard)
- Bilge system operated continuously from at least 0544
- Flooding in hold 3 exceeded design capacity of bilge pumps
- Water level continued to rise despite pumping



*El Yunque Bilge Well, Hold 3*

# Bilge Alarm System


- Visible and audible alarms in engine room only
- Hold 3 alarms typically investigated by engineering watch
- No evidence of how flooding in hold 3 detected
- Discussion on VDR of hold 2A alarm
- Crew most likely alerted to water in hold 3 by bilge alarm system

# Bilge Alarm Requirements

- Alarms quickly identify flooding
- Alarms not required on cargo vessels
- Cargo vessels should be equipped with bilge alarms





# Cargo Hold Ventilation System






# Cargo Hold Ventilation System



# Cargo Hold Ventilation Closures


- Ventilation closures most likely remained open throughout sinking
- COI required ventilation of holds at sea
- Intact and damage stability standards consider ventilation openings to be closed
- Vessels should not have conflicting requirements

# Cargo Hold Ventilation Downflooding





# Examination of Wreckage




Side Scan Sonar Images: Main Hull





NTSB





NTSB

# Summary – Flooding of Cargo Holds

- Findings
- Recommendations