

1

National Transportation Safety Board

Motorcoach Collision With Crash Attenuator in Gore Area, US Highway 101, San Jose, California

January 19, 2016



National Transportation Safety Board

Motorcoach Collision With Crash Attenuator San Jose, CA

Jennifer Morrison Investigator-in-Charge

Crash Overview

- Greyhound bus
 - Driver
 - 21 passengers
- Northbound from Los Angeles
- Crashed just south of San Jose
- Dark, rainy, windy





Crash Location



Source: Google Earth image dated March 28, 2015



Crash Location



Source: Google Earth image dated March 28, 2015



Final Rest



Source: California Highway Patrol



Postcrash Damage





On-Scene Staff

- David Rayburn, Highway Factors
- Rafael Marshall, PhD, Human Performance
- Michael Fox, Motor Carrier Operations
- Shawn Currie, Motor Carrier Operations
- Ronald Kaminski, Survival Factors
- David Pereira, Vehicle Factors
- Kristin Poland, PhD, Scene Scanning
- George Haralampopoulos, Recorders
- Jennifer Morrison, Investigator-in-Charge



Report Development Staff

- Ensar Becic, PhD, Project Manager
- Debbie Stocker, Writer-Editor
- Julie Perrot, Safety Recommendations
- Don Eick, Meteorology
- Christy Spangler, Graphics
- Ivan Cheung, PhD, Mapping Graphics
- Dr. Nick Webster, MD, Medical Factors
- Edward Kendall, Legal Counsel
- Katy Chisom, Transportation Disaster Assistance
- Eric Weiss, Media Relations



Parties to Investigation

- Federal Highway Administration
- Federal Motor Carrier Safety Administration
- California Highway Patrol
- Santa Clara Valley Transportation Authority
- Greyhound Lines, Inc.
- Trinity Industries, Inc.



Safety Issues

- Repair of traffic safety devices
- Signage and roadway markings
- Driver risk management
- Maintenance and use of passenger restraints on motorcoaches
- Collision avoidance systems





| National Transportation Safety Board



National Transportation Safety Board

Highway Factors and Traffic Guidance

David Rayburn

Overview

- Traffic metrics
- Accident history
- Inadequacies
 - Maintenance of traffic safety devices
 - Gore delineation
 - Guide signage noncompliance



Traffic Metrics for US 101

- Average daily traffic: 142,000 vehicles
- Truck and bus traffic accounted for 8.5% or 12,000 trucks and buses per day
- Posted speed limit: 65 mph
- Average speed of all traffic near time of crash: 56.6 mph



Accident History

8 crashes at crash site since 2008

5 involved another vehicle striking crash attenuator

5 crashes since 2014



- Crash on December 6, 2015
 - A vehicle struck the crash attenuator and displaced the retroreflective object marker
- Repair

- Cleared the crash site



Repair

- Cleared the crash site
- Reset the cylinders





• Repair

- Cleared the crash site
- Reset the cylinders
- Placed temporary barricades
- Did not replace the retroreflective object marker





• Repair

- Cleared the crash site
- Reset the cylinders
- Placed temporary barricades
- Did not replace the retroreflective object marker





Traffic Safety Devices: Maintenance

- Caltrans policy requires clearing crash scene within 1 day
- Caltrans policy requires crash attenuators to be repaired within 7 days
- 44 days later, retroreflective object marker was still missing
- Unknown when temporary barriers were displaced



Traffic Safety Devices: Work Orders

Integrated maintenance management system

- Tracks initiation of work order
- Does not indicate status of repair
- Does not denote special orders
- Repair checklist for proprietary devices
 - Was never initiated



Gore Delineation



990 feet



Gore Delineation



Source: Google Earth image dated January 31, 2016

MUTCD guidance on gore delineation







Guide Signage

- Three guide signs for left HOV exit
 2 advance signs and 1 exit direction sign
- At time of installation in 2008, signs were compliant with MUTCD standards
- At time of crash, signs were out of compliance with MUTCD standards



Guide Signage Compliance

- Recommendations from Atlanta, GA
- MUTCD revision in 2009
 - Requirement for left exit plaque; compliance date of December 31, 2014
 - Requirement for full border indicating HOV lane or exit; compliance required at end of useful life





Guide Signage Compliance







Current sign - out of compliance -

Compliant

Compliant, new





- Inadequate maintenance of safety devices
- Inadequate gore delineation
- Use of noncompliant guide signage





| National Transportation Safety Board



National Transportation Safety Board

Human Performance and Driver Perception

Rafael Marshall

Overview

- Bus driver background
- Factors that contributed to driver error
 - Incorrect driver expectations
 - Reduced visibility
 - Improper roadway signage and markings



Driver Background

• Experienced and properly licensed

- 28 years driving for Greyhound
- Class "B" commercial license
- Passenger endorsement
- Corrective lens restriction
- Medical certificate good for 1 year due to medical conditions



Driver Perception

- Believed that gore was a travel lane
- Stayed in gore for 8 seconds before crash



Exclusions

- Licensure
- Overall driving experience
- Drug or alcohol use
- In-vehicle distractions
- Fatigue
- Medical condition



Driver Expectations: Route Familiarity



Source: Google Earth image dated January 26, 2016



Driver Expectations: Previous Trip



Source: Google Earth image dated March 28, 2015



Driving and Visibility Conditions

- Darkness
- Moderate/heavy traffic
- Moderate/heavy rain
- 28-mph wind gusts
- Poorly maintained pavement markings
- Absence of retroreflective object markers

















Summary

- Bus driver may have expected HOV exit to have two travel lanes
- Bus driver would not have followed an incorrect travel path
 - Had visibility conditions been better
 - Had gore and crash attenuator been properly delineated





| National Transportation Safety Board



National Transportation Safety Board

Motor Carrier Factors and Managing Driver Risk

Michael Fox

Overview

- Motor carrier oversight and driver risk management issues:
 - Personnel files incomplete and missing data
 - Accident driver's disciplinary record
 - Greyhound had monitoring systems, but no procedures to maximize effectiveness



Greyhound Lines Inc.

- Largest motorcoach company in US and Canada
- Based in Dallas, TX
- 82 terminals
- 1,200 buses
- 792 fixed US routes
- Employs 2,200 drivers





Greyhound Driver Files

- Employed since 1988, 28 years
- Paper system kept at Los Angeles terminal
- Files incomplete and missing 5 years of data
- Prevented timely and adequate oversight
- Need to modernize record keeping to better manage risk



Driver Disciplinary Record

- From 2001 2015:
 - 27 disciplinary actions
 - 4 preventable accidents
 - 19 suspensions totaling 58 days
 - Repeat infractions
 - Reprimanded 5 times for hours-of-service violations
 - Suspended 9 times for speeding violations
- No means to track or assess driver performance due to record keeping limitations



Greyhound Risk Management Systems

- Recommendations from Burnt Cabins, PA
- Fatigue management program
- Cadec fleet management system
- DriveCam system introduced to address at-risk behavior:
 - Driver had 18 critical events
 - On Top 20 list for worst offenders



Managing Driver Risk

• Greyhound

- No policy to address repeat infractions
- No established threshold for suspensions before termination
- Industry best practices
 - Risk assessments
 - Established thresholds





- Files incomplete and missing data
- Extensive disciplinary record
- Greyhound had proactive monitoring systems, but no policies to maximize effectiveness





| National Transportation Safety Board



National Transportation Safety Board

Survival Factors and Occupant Protection

Ronald Kaminski



- Seat belt use by bus passengers
- Pretrip safety briefings not required
- Seat belt use laws



Occupant Injuries

- Driver was partially ejected, lap belted only, sustained minor injuries
- Passengers
 - 2 fatal, ejected
 - 2 serious
 - 11 minor
 - 3 not injured, 2 of whom were belted



3-D Laser Scan Video





Seat Belt Use



- Seat belts were available
- NHTSA statistics
 - 75% of ejected are fatals
 - Restraints reduce fatals by 77%
- Improvements to maximize benefits
 - Maintenance and inspection
 - Pretrip safety briefings



Seat Belt Maintenance and Inspection





Pretrip Safety Briefings

- Pretrip briefing to inform and educate
- Originally recommended in 1999
- Recommendation from Orland, CA
 - Added printed instructions to reinforce seat belt use
- Greyhound pretrip safety briefings
 - Script developed
 - Not required



Seat Belts Use Laws

- Primary enforcement
 - Increased usage
 - 34 states with primary enforcement, average use rate of 92 percent (vs 83 percent)
- NTSB has advocated use of seat belts for 50 years
- Recommendations from Davis, OK
- California considering seat belt enforcement bill





- Increasing seat belt use
- Requirement for pretrip safety briefings
- Primary enforcement of mandatory seat belt use laws for all vehicles





| National Transportation Safety Board



National Transportation Safety Board

Vehicle Factors and Collision Avoidance Systems

David Pereira

Overview

- Mechanical systems inspection
- Collision avoidance testing
- Collision avoidance history



Exclusions

- Major mechanical systems inspected, excluded
 - Steering
 - Suspension
 - Brake
 - Electrical
 - Tires & wheels





Commercial Vehicle Collision Avoidance Systems

- 2014 motorcoach not equipped with collision avoidance system
- Collision avoidance systems
 - Not required
 - No performance standards
- About 20% of Greyhound buses equipped with collision avoidance system



Collision Avoidance Testing

- Testing conducted at Transportation Research Center Inc., East Liberty, Ohio
 - Greyhound
 - Meritor WABCO
 - Trinity Industries, Inc.





Collision Avoidance Testing

• Test findings:

- 18 of 19 trials detected crash attenuator
- Technology capable of detecting stationary hazard
- Collison avoidance system effective in preventing or mitigating crash severity



Recommendation History

- Collision avoidance systems are life-saving technologies
- NTSB has advocated for collision avoidance technologies for more than 20 years
- 2015 Special Investigation Report
- Most Wanted List



Summary

- Mechanical condition of bus was excluded as contributing to collision
- Collision avoidance technology could have alerted driver of forward hazard and mitigated severity of crash





| National Transportation Safety Board