

National Transportation Safety Board

Human Performance Issues

Asiana Flight 214, B777 San Francisco, CA July 6, 2013

Senior Human Performance Investigator



Human Performance Issues

- Flightpath management
- Understanding of automation
- Communication and coordination
- Monitoring
- Go-around decision-making



Human Performance Issues

- Context-dependent, low energy alerting systems
- Expanded low speed protection



Flightpath Management

 Airplane high at 5 nautical miles Delayed deceleration and configuration -Increased flight crew workload »Degraded monitoring »Increased opportunity for error »Reduced likelihood of error detection



Understanding of Automation

- Complex autoflight system logic, inadequate documentation and training
- PF had an inaccurate understanding of the system
 - Did not correctly anticipate the effect of his actions on airspeed control
 - Did not understand the A/T automatic engagement feature



Communication and Coordination

- Asiana SOPs specified that when the A/P was ON:
 - The PF operated the MCP, called out selections
 - The PM verified, called out mode changes
- The flight crew did not consistently follow these SOPs throughout the approach



Communication and Coordination

 The PF did not call out his selection of FLCH

The PM and observer did not notice:
The PF's selection
Subsequent, related mode changes

NTSB

Monitoring





Monitoring

The flight crew did not effectively monitor airspeed below 500 feet

- Expectancy

Automation reliance

- Increased workload

- Fatigue



Go-Around Decision-Making



NTSB

Go-Around Decision-Making

Delayed go-around

• Surprise

Nonstandard communication

Role confusion



Low Airspeed / Low-Energy Alerting

777 low airspeed alert

- Provided visual and aural indication of low speed condition
- Occurred too late to change the outcome of this accident
- Presented as a less urgent "caution" instead of "warning" alert



Low Airspeed / Low-Energy Alerting

- Context-dependent, low-energy alert could:
- Jointly consider
 - Speed
 - Altitude
 - Flight crew response time
 - Engine spool-up time
- Determine most appropriate activation threshold and method of presentation



Expanded Low Speed Protection

• 777 autothrottle system characteristics

Maintained the selected speed when A/T was ON and in SPD mode

- Provided low speed protection in some pitch modes when A/T was disengaged and ARMED
- Did not maintain selected speed or provide low speed protection when the A/T was ON and in HOLD mode



Expanded Low Speed Protection

If automatic low speed protection had been available in HOLD mode, it likely would have increased power 20 seconds before impact





National Transportation Safety Board