



National Transportation Safety Board

NTSB Overview



Jill Demko

Technical Training Officer

Mission


The National Transportation Safety Board is an independent Federal agency charged by Congress with investigating **every civil aviation accident** in the United States and **significant accidents in the other modes** of transportation -- railroad, highway, marine and pipeline -- and **issuing safety recommendations** aimed at preventing future accidents.

Mission


The NTSB is additionally charged with:

- conducting special studies and investigations
- coordinating resources to assist victims and their families after an accident.
- Court of Appeals (through ALJ) for airmen, mechanics, and mariners who have certificate actions against them

The Office of Aviation Safety



NTSB Regional Structure



Your Closest Regional Office

Eastern Regional Aviation (ERA)

45065 Riverside Parkway

Ashburn, Virginia 20147

Phone: 571-223-3930

FAX: 571-223-3926

Chief: Mr. Steven Gottlieb 571-223-3925

Deputy Chief: Mr Jeff Kennedy 305-597-4625

NTSB Communications Center: 202-314-6290

What is an Accident?



What is an Accident?

An occurrence associated with the operation of an aircraft which:

- takes place between the time any person boards the aircraft with the intention of flight and all such persons have disembarked, and in which
- any person suffers death or serious injury, or in which
 - the aircraft receives substantial damage

Serious Injury

Any injury which:

- Requires hospitalization for more than **48 hours, commencing within 7 days** of the date that the injury was received;
- Results in a **fracture** of any bone (except simple fractures of fingers, toes, or nose);

Cont'd:

- Causes severe hemorrhages, nerve, muscle, or tendon damage;
- Involves any **internal organ** or;
- Involves **2nd or 3rd degree burns**, or burns affecting more than 5% of the body surface

Substantial Damage

Substantial Damage is...

Damage or failure which:

- Adversely affects the structural **strength, performance, or flight characteristics** of the aircraft, and which
- Would normally require **major repair or replacement** of the affected component

Substantial Damage is **not**...

- Engine failure or damage limited to an engine if only one engine fails or is damaged,
- Bent fairings or cowling
- Dented skin
- Small punctured holes in the skin or fabric
- Ground damage to rotor or propeller blades
- Damage to landing gear, wheels, tires, flaps, engine accessories, brakes, or wingtips are not considered “substantial damage” for the purpose of this part.

Accident or Incident?



Accident or Incident?



Accident or Incident?



Incidents

Incidents

“An occurrence other than an accident associated with the operation of an aircraft, which affects or could affect the safety of operations.”

- 49 Code Federal Regulations 830.2

Notification and Reporting

The operator of an aircraft shall *immediately* and by the *most expeditious means available* notify the nearest NTSB Field Office when an *aircraft accident* or any of the following *incidents* occur:

- Flight control system malfunction
- Inability of any crew member to perform normal flight duties as a result of injury or illness
- In-flight fire
- Damage to property, exceeding \$25,000
- Aircraft collision in flight

Notification Requirements

Updated Incidents (830.5):

- Uncontained engine failure (turbine)
- Release of propeller blade (not ground)
- Failure of more than 50% of cockpit displays (EFIS, EICAS, PFD, PND, etc.)
- TCAS resolution advisory with risk of collision
- Damage to helicopter rotors (major replacement)

What to do if you are involved in an accident/incident

- ✓ Notify NTSB
- ✓ Preserve wreckage
- ✓ Take photos
- ✓ Retain records
- ✓ Complete NTSB Form 6120 (Pilot/Operator Report)
- ✓ Cooperate with investigators



Accident Reporting

- Notify NTSB field office or NTSB HQ.
- Contact information on NTSB website <http://www.nts.gov>
- Notify local FAA FSDO or ATC
- Law Enforcement will typically notify an FAA Ops Center

Preservation of Wreckage

- Operator is responsible for preserving wreckage and records
- May not be disturbed unless
 - To remove persons injured or trapped
 - To protect from further damage
 - To protect public from injury
- If necessary, operator takes pictures, makes diagrams, etc.



Preliminary Report

- Released about 10 days after accident [Except the one-time Collection Report (CA) 30 days]
- Contains initial information, subject to change
- Available at www.nts.gov

 National Transportation Safety Board PRELIMINARY REPORT AVIATION	NTSB ID: IAD05FA	
	Occurrence Date: 08/01/05	
	Occurrence Type: Aviation	
Location/Time		
Nearest City/Place	State	Zip Code

Factual Report

- Released about 4 to 12 months after accident
- Contains much more detailed information
- Available at: www.nts.gov

National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: CH03FA198	Aircraft Registration Number: N36DR	
Occurrence Date: 05/25/2003		Most Critical Injury: Fatal		
Occurrence Type: Accident		Investigated By: NTSB		
Location/Time				
Nearest City/Place Woodruff	State WI	Zip Code 54568	Local Time 1754	Time Zone CDT
Airport Proximity: Off Airport/Airstrip	Distance From Landing Facility: 0.5		Direction From Airport: 330	
Aircraft Information Summary				
Aircraft Manufacturer Piper	Model/Serial PA-31P		Type of Aircraft Airplane	
Sightseeing Flight: No		Air Medical Transport Flight: No		
Narrative				
Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident: HISTORY OF FLIGHT				
On May 25, 2003, at 1754 central daylight time, a Piper PA-31P, N36DR, piloted by an airline transport pilot, sustained substantial damage when it impacted trees and terrain after takeoff from runway 26 (5,150 feet by 100 feet, asphalt), at the Lakeland Airport/Huble F. Lee Memorial Field (AEV), near Woodruff, Wisconsin. The airplane was consumed by fire subsequent to the impact. The 14 CFR Part 91 flight was operating in visual meteorological conditions and an instrument rules flight plan had been filed but not activated. All four occupants of the airplane were fatally injured. The flight was originating at the time of the accident. The DuPage Airport (DPA), West Chicago, Illinois, was the intended destination.				
The airplane was reported to have been flown from DPA to AEV by the pilot and pilot rated passenger in order to pick up two passengers and return to DPA.				
The airplane impacted into level wooded terrain about 1/2 mile north of the departure end of the runway and left of the extended runway centerline.				
A witness who is a pilot reported seeing the airplane "hardly climbing at 60+ feet just above the (runway) 15 threshold. At this point he was raking across power and no engine abnormalities or prop sounds were heard. The plane was very slow with a 5 (degree) pitch up then I saw the nose leveled and I knew he was in serious trouble. I saw the plane going straight for a few more seconds then lost sight. I listened as I ran to my truck. I then heard it hit the trees and impact."				
Another witness reported seeing the airplane take-off. He reported that the sound was not normal and that this is what drew his attention to the airplane. He said that the airplane sounded labored. He reported that the airplane was not gaining altitude as expected and the airplane was much lower than he was accustomed to seeing. He stated that he lost sight of the airplane due to obstructions to his view. He stated that from the time the airplane drew his attention, to the time the airplane started hitting the trees, the engine sounds did not change.				
PERSONNEL INFORMATION				
The pilot held an airline transport pilot certificate with ratings for multi-engine land airplanes with commercial privileges for single engine land airplanes. The pilot was type rated in Boeing 757, Boeing 767, McDonnell Douglas DC-9, and Dassault 500 series aircraft. The pilot also held a flight engineer certificate for turbojet-powered airplanes and a flight instructor certificate with a rating for single engine airplanes. The pilot's flight logbook was not recovered. The pilot served as a chief pilot for a major airline. According to airline records, the pilot had accumulated 8,524 hours of flight time in Boeing 767 and McDonnell Douglas MD-80 aircraft. An airline representative estimated that the pilot also had approximately 4,000 hours in Boeing 727				
FACTUAL REPORT - AVIATION Page 1				

Brief/Probable Cause Report

National Transportation Safety Board Washington, DC 20594			
Brief of Accident Adopted 12/28/2004			
ANC104 FAD1 6B File No. 16809	12/28/2003	Pecos, AZ	Aircraft Reg No. N274KS Time (Local) 13:12 MST
Make/Model: Schickler / ASK-21 Engine Make/Model: Aircraft Damage: Destroyed Number of Engines: Unknown Operating Certificate: None Type of Flight Operation: Instructional Reg. Flight Conducted Under: Part 91: General Aviation	Crew Pass: 1 Fatal: 1 Serious: 0 Minor/None: 0		
Last Depart. Point: Same as Accident/Incident Location Destination: Same as Accident/Incident Location Airport Proximity: Off Airport/Arstrip	Condition of Light: Day Weather Info Src: Witness Basic Weather: Visual Conditions Lowest Ceiling: None Visibility: 50.00 SM Wind Dir/Speed: Light and Variable Temperature (C): 21 Obsr to Vision: None Precipitation: None		
Pilot-in-Command: Age: 30	Flight Time (Hours): Total At Aircraft: 2630 Last 90 Days: Unknown Total Make/Model: Unknown Total Instrument Time: Unknown		
Certificate(s)/Rating(s): Commercial: Private, Single-engine Land, Glider Instrument Ratings: None	<p>The commercial certificated pilot of an aerobatic glider, with one passenger, was performing a series of aerobatic maneuvers within an aerobatic box, which was adjacent to runway 5L at an uncontrolled airport. The aerobatic box measured 1 kilometer square, and extended from the surface up to 6,600 feet msl (5000' agl). The southern boundary of the aerobatic box was located about 1,400 feet north of runway 5L's centerline. Concurrently, a Piper J3C airplane with the commercial pilot/instructor/airplane owner seated in the front seat, and a private pilot seated in the rear seat, departed runway 5L and made a left downwind turn into the area where the glider was performing the aerobatic maneuvers. Witnesses said that as the glider reached the top of the loop, the nose lowered, eventually pointing straight down. As the glider began to recover from the maneuver, about 600 feet agl, the left wing of the ascending Piper struck the tail of the glider between the spar and the main fuselage, severing the empennage of the glider. Witnesses said that during the collision, a large portion of the left outboard wing of the Piper separated, and both the glider and the Piper entered uncontrolled descents. Both aircraft came to rest close to the center of the aerobatic box. According to the airport facilities directory, aircraft departing from runway 5L are instructed to fly a right-hand traffic pattern. However, the airport's segmented circle depicts a left-hand departure from runway 5L. Radio equipped aircraft may utilize a common traffic advisory frequency of 122.9 MHz. Neither of the aircraft involved in the accident had a radio, nor were they required to. The front seat pilot of the Piper had based the accident airplane at the accident airport for several years, and was familiar with the procedures for operating at the airport.</p>		

Analytical summary

Coding of causes, factors, and findings

Brief of Accident (Continued)			
ANC104 FAD1 6B File No. 16809	12/28/2003	Pecos, AZ	Aircraft Reg No. N274KS Time (Local) 13:12 MST
Occurrence #1: MIDAIR COLLISION Phase of Operation: MANEUVERING	Findings: 1. (C) VISUAL LOOKOUT - INADEQUATE - PILOT IN COMMAND 2. (C) VISUAL LOOKOUT - INADEQUATE - PILOT OF OTHER AIRCRAFT 3. (F) PROCEDURES/DIRECTIVES - NOT FOLLOWED - PILOT OF OTHER AIRCRAFT		
Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: DESCENT - UNCONTROLLED	Findings: 4. TERRAIN CONDITION - GROUND		
Findings Legend: (C) = Cause, (F) = Factor			
<p>The National Transportation Safety Board determines the probable cause(s) of this accident as follows: The inadequate visual lookout by the pilots of both aircraft, which resulted in their failure to see and avoid each other's aircraft and a subsequent midair collision. A factor associated with the accident was the airplane pilot's failure to determine that the aerobatic box was in use by the glider prior to his entry into the aerobatic box.</p>			

Probable Cause statement

Public Docket

- Contains all supporting documents for a case
- Released concurrently with factual report
- Now available on the web

The screenshot displays the NTSB Docket Management System interface. At the top, there is a navigation bar with links for Home, Search, Help, and Support. Below this, the page title is "Docket And Docket Items". A message states: "Below is the Docket you selected and its list of contents. Click on any Document title to view the item."

Project Information

Mode		
Aviation		
NTSB Accident ID	Occurrence Date	Location
IRA10FA283	May 26, 2010	Bosborough, MA, United States
Docket Information		
Creation Date	Last Modified	Public Release Date & Time
Dec 02, 2010	May 24, 2011 15:11	May 24, 2011 15:12
Comments		

Buttons: MS Word TOC, Print TOC

List of Contents Results 1 through 15 of 27 Total Pages 76/Photos 7

Sort: Ascending Descending
Order Documents By: Sequence Date
Document Title: Find

Document	Filing Date	Document Title	Pages	Photo
1	Dec 02, 2010	Commercial Pilot Interview	6	0
2	Dec 02, 2010	Commercial Pilot Statement	1	0
3	Dec 02, 2010	Toxicological Report	1	0
4	Dec 02, 2010	Pilot Operator Aircraft Accident Report, NTSB Form 5120.1	8	0
5	Dec 02, 2010	Witness Interviews	3	0
6	Dec 02, 2010	Designated Pilot Examiner (DPE) Interview	3	0
7	Dec 02, 2010	Operator Interview	3	0
8	Apr 06, 2011	Mechanic Interview	1	0
9	Dec 03, 2010	ATC Pilot (contingency/CFR)	1	1
10	Feb 04, 2011	Operator POH excerpt	2	0
11	Apr 06, 2011	Hanscom Field Airport Recorded METARs	1	0
12	Apr 06, 2011	FAA Inspector Pilot Logbook (excerpt)	12	0
13	Apr 19, 2011	FAA Inspector Flight Experience Paperwork	8	0
14	Apr 07, 2011	Commercial Pilot Logbook (excerpt)	3	0
15	Apr 07, 2011	Schweizer Pilot's Flight Manual (excerpt)	2	0

1 2 Next Last

Where can I find these reports?

The screenshot shows the NTSB website homepage. At the top, there is a navigation bar with links for HOME, NEWS & EVENTS, TRANSPORTATION SAFETY, INVESTIGATIONS, DISASTER ASSISTANCE, LEGAL, and ABOUT. Below this is a main content area featuring a large image of a Beechcraft aircraft and a news article titled "NTSB News" with the sub-headline "NTSB launches team to aviation accident in Thomson Georgia". A "Read More" button is visible. Below the main content, there is a horizontal menu with links for Accident Dockets, Safety Recommendations, Aviation Accident Database, Data & Stats, and Training Center. On the left side, there is a "Public Dockets" section with a list of links: Contact NTSB, Report an Aviation Accident, Submit a TCAS Notification, Eyewitness Report, and FOIA Request. In the center, there is a "Photo of the Week" section featuring a video thumbnail and a "Member Rosekind" section. On the right side, there is a "News @ NTSB" section with several news items and social media links. A red arrow points from the "Public Dockets" box to the "Accident Dockets" link in the horizontal menu. Another red arrow points from the "Reports" box to the "Read More" button in the news article.

Public Dockets

Reports



National Transportation Safety Board