



National Transportation Safety Board

Departure From Controlled Flight

Trans-Pacific Air Charter
Learjet 35A, N452DA
Teterboro, New Jersey
May 15, 2017

Investigator-in-Charge
presentation



Animation



Aerial View of Accident Site



Aerial View of Accident Site



Part 135 Safety Issues

- Flight data monitoring programs
- Safety management systems
- System to identify operators that do not comply with standard operating procedures

Part 135 Safety Issues

- Monitoring pilots with performance deficiencies
- Guidance for crew resource management training
- Leadership training for captains

Safety Issue

- Lack of manufacturer-recommended approach speed wind additives for Learjet 35A in company operations documents

Parties to Investigation

- Federal Aviation Administration
- Trans-Pacific Air Charter
- Bombardier (Learjet)
- Honeywell Aerospace
- National Air Traffic Controllers Association



National Transportation Safety Board