APPENDIX H
Photographs

NTSB Airplane Accident Case No. DCA00MA006
60 miles south of Nantucket, Massachusetts
October 31, 1999
Boeing 767-336, SU-GAP

Photo #1 - Fuselage Section 41

Photo #2 - Fuselage Section 41 View of
Cockpit Window Frames

Photo #3 - Fuselage Section 43

Photo #4 - Fuselage Section 43

Photo #5 - Fuselage Section 45

Photo #6 - Fuselage Section 46

Photo #7 - Fuselage Section 46 - Window Belt

Photo #8 - Fuselage Section 48

Photo #9 - Miscellaneous Fuselage (area 1)

Photo #10 - Miscellaneous Fuselage (area 2)

Photo #11 - Miscellaneous Fuselage (area 3)

Photo #12 - Doors (general)

Photo #13 - Overview of Recovered Wing

Photo #14 - Wing Leading Edge

Photo #15 - Wing Leading Edge - Section 14

Photo #16 - Wing Center Section - Section 11

Photo #17 - Wing Box - Section 12

Photo #18 - Wing Trailing Edge - Section 13

Photo #19 - Landing Gear Beams

Photo #20 - Engine Pylon - Engine #2

Photo #21 - Engine Pylon - Engine #1

Photo #22 - Horizontal Stabilizer

Photo #23 - Vertical Fin

Photo #24 - Miscellaneous Tail

Photo #25 - Main Landing Gear

Photo #26 - Nose Landing Gear

Photo #27 - Tail Skid