

 <b>National Transportation Safety Board</b> <b>PRELIMINARY REPORT</b> <b>AVIATION</b>		NTSB ID: ERA09WA069		Most Critical Injury: Fatal	
		Occurrence Date: 10/28/2008		Investigated By: Foreign	
		Occurrence Type: Accident			
Location/Time					
Nearest City/Place		State	Zip Code	Local Time	Time Zone
Nuqui				1540	UTC
Aircraft Information					
Registration Number		Aircraft Manufacturer		Model/Series Number	
HK-2446		PIPER		PA-34/200T	
Type of Aircraft: Airplane			Amateur Built Aircraft? No		
Injury Summary:		Fatal	4	Serious	3
				Minor	None
Revenue Sightseeing Flight:			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>On October 28, 2008, about 1040 local time, a Piper PA-34-200T, Columbian registration HK-2446, operated by Aeroexpreso Del Pacifico, impacted terrain shortly after takeoff from Reyes Murillo Airport, Nuqui, Columbia. The accident site was located approximately 3 kilometers south of the departure airport. The two crew members were seriously injured. Four passengers were killed, and the other passenger was seriously injured.</p> <p>This investigation is under jurisdiction of the Government of Columbia. For further information contact:</p> <p>Grupo de Investigacin de Accidentes -  Unidad Administrativa Especial Aeronutica Civil  Avenida Eldorado # 103 - 23,  Oficina 204, Bogot - Colombia  Telfonos 57 - 1 - 2662210 57 - 1 - 2663068</p> <p>This report is for informational purposes only and contains information released by, or obtained for release, from the Government of Columbia.  Updated on Dec 20 2008 10:57AM</p>					
PRELIMINARY INFORMATION - SUBJECT TO CHANGE					

 <p>National Transportation Safety Board <b>PRELIMINARY REPORT</b> AVIATION</p>	NTSB ID: ERA09WA069	
	Occurrence Date: 10/28/2008	
	Occurrence Type: Accident	

Other Aircraft Involved		
Registration Number	Aircraft Manufacturer	Model/Series Number

Accident Information	
Aircraft Damage: Substantial	Accident Occurred During:

Crew	Name	Certificate No.	Injury
Pilot			
2			
3			
4			
5			
6			

Operator Information		
Name Aeroexpreso Del Pacifico	Operator Designator Code	Doing Business As

Street Address	City	State	Zip Code
----------------	------	-------	----------

-Type of Certificate(s) Held: None
Air Carrier Operating Certificate(s):

Operating Certificate:	Operator Certificate:
Regulation Flight Conducted Under: Non-U.S., Commercial	
Type of Flight Operations Conducted: Scheduled; International; Passenger Only	

Flight Plan/Itinerary			
Type of Flight Plan Filed: Unknown			
Last Departure Point Nuqui	State	Airport Identifier	
Destination Quibdo	State	Airport Identifier	

Weather Information			
Investigator's Source:	Facility ID:	Observation Time (Local):	
Sky/Lowest Cloud Condition:		Ft. AGL	
Lowest Ceiling:	Ft. AGL	Visibility:	SM Altimeter: "Hg

 <p>National Transportation Safety Board <b>PRELIMINARY REPORT</b> AVIATION</p>	NTSB ID: ERA09WA069	
	Occurrence Date: 10/28/2008	
	Occurrence Type: Accident	

Weather Information (Continued from page 2)			
Temperature: °C	Dew Point: °C	Wind Direction:	
Wind Speed: Kts.	Gusts: Kts.	Weather Conditions at Accident Site:	

Administration Data	
Notification From Civil Aeronautica Colombia	Date
FAA District Office/Coordinator	Investigator-In-Charge (IIC) Michael C. Huhn