

		NTSB ID: ERA09WA094		Aircraft Registration Number: LV-MYX		
		Occurrence Date: 12/18/2008		Most Critical Injury: Fatal		
		Occurrence Type: Accident		Investigated By: Foreign		
Location/Time						
Nearest City/Place Buenos Aires		State	Zip Code	Local Time 0810	Time Zone UTC	
Airport Proximity: Off Airport/Airstrip		Distance From Landing Facility:				
Aircraft Information Summary						
Aircraft Manufacturer PIPER		Model/Series PA-31T		Type of Aircraft Airplane		
Revenue Sightseeing Flight:			Air Medical Transport Flight:			
Narrative						
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>On December 18, 2008, at 0810 universal time coordinated, a Piper Aircraft, PA-31T, LV-MYX, operated by Aviacenter SA, impacted the ground a few minutes after takeoff from San Fernando Airport (SADF), Buenos Aires, Argentina. Visual flight rules prevailed. The airplane was substantially damaged. The two pilots were killed.</p> <p>The investigation is under the jurisdiction of the Government of Argentina. Further information pertaining to this accident may be obtained from:</p> <p>FUERZA AÉREA ARGENTINA COMANDO DE REGIONES AEREAS Junta de Investigaciones de Accidentes de Aviación Civil 1370 Belgrano Avenue 11th Floor Buenos Aires, República Argentina C1093AAO Fax number 54-11-4381-6333</p> <p>This report is for information purposes only and contains only information released by the Government of Argentina. Updated on Dec 26 2008 9:59AM</p>						
FACTUAL REPORT - AVIATION						
Page 1						

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: ERA09WA094				
		Occurrence Date: 12/18/2008				
		Occurrence Type: Accident				
Landing Facility/Approach Information						
Airport Name San Fernando Airport		Airport ID: SADF	Airport Elevation Ft. MSL	Runway Used N/A	Runway Length	Runway Width
Runway Surface Type:						
Runway Surface Condition:						
Approach/Arrival Flown: NONE						
VFR Approach/Landing: None						
Aircraft Information						
Aircraft Manufacturer PIPER		Model/Series PA-31T		Serial Number 31-7904045		
Airworthiness Certificate(s): Normal						
Landing Gear Type: Retractable - Tricycle						
Amateur Built Acft? No		Number of Seats:		Certified Max Gross Wt. LBS	Number of Engines: 2	
Engine Type:		Engine Manufacturer:		Model/Series:		Rated Power:
- Aircraft Inspection Information						
Type of Last Inspection		Date of Last Inspection	Time Since Last Inspection Hours		Airframe Total Time Hours	
- Emergency Locator Transmitter (ELT) Information						
ELT Installed?/Type		ELT Operated?		ELT Aided in Locating Accident Site?		
Owner/Operator Information						
Registered Aircraft Owner		Street Address				
		City		State	Zip Code	
Operator of Aircraft		Street Address				
		City		State	Zip Code	
Operator Does Business As:				Operator Designator Code:		
- Type of U.S. Certificate(s) Held: None						
Air Carrier Operating Certificate(s):						
Operating Certificate:			Operator Certificate:			
Regulation Flight Conducted Under: Unknown						
Type of Flight Operation Conducted:						

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: ERA09WA094	
	Occurrence Date: 12/18/2008	
	Occurrence Type: Accident	

First Pilot Information

Name	City	State	Date of Birth	Age
------	------	-------	---------------	-----

Sex:	Seat Occupied:	Occupational Pilot?	Certificate Number:
------	----------------	---------------------	---------------------

Certificate(s):

Airplane Rating(s):

Rotorcraft/Glider/LTA:

Instrument Rating(s):

Instructor Rating(s):

Current Biennial Flight Review?

Medical Cert.:	Medical Cert. Status:	Date of Last Medical Exam:
----------------	-----------------------	----------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot In Command(PIC)										
Instructor										
Instruction Received										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

Seatbelt Used?	Shoulder Harness Used?	Toxicology Performed?	Second Pilot?
----------------	------------------------	-----------------------	---------------

Flight Plan/Itinerary

Type of Flight Plan Filed: Unknown

Departure Point	State	Airport Identifier	Departure Time	Time Zone
San Fernando		SADF		
Destination	State	Airport Identifier		
Victoria				

Type of Clearance: Unknown

Type of Airspace:

Weather Information

Source of Wx Information:

Unknown

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: ERA09WA094
	Occurrence Date: 12/18/2008
	Occurrence Type: Accident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation Ft. MSL	WOF Distance From Accident Site NM	Direction From Accident Site Deg. Mag.
Sky/Lowest Cloud Condition:				Ft. AGL	Condition of Light:
Lowest Ceiling:			Ft. AGL	Visibility: SM	Altimeter: "Hg
Temperature: °C	Dew Point: °C	Weather Conditions at Accident Site:			
Wind Direction:		Wind Speed:		Wind Gusts:	
Visibility (RVR): Ft.		Visibility (RVV) SM			
Precip and/or Obscuration:					

Accident Information		
Aircraft Damage: Destroyed	Aircraft Fire: Unknown	Aircraft Explosion

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot	1				1
Second Pilot	1				1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants					
Other Crew					
Passengers					
- TOTAL ABOARD -	2				2
Other Ground					
- GRAND TOTAL -	2				2

 National Transportation Safety Board FACTUAL REPORT AVIATION	NTSB ID: ERA09WA094	
	Occurrence Date: 12/18/2008	
	Occurrence Type: Accident	

Administrative Information

Investigator-In-Charge (IIC)

Shawn Etcher

Additional Persons Participating in This Accident/Incident Investigation: