



National Transportation Safety Board

Washington, DC 20594

Safety Recommendation

Date: June 21, 2016

In reply refer to: A-16-12

The Honorable Michael P. Huerta
Administrator
Federal Aviation Administration
Washington, DC 20591

On June 7, 2016, we adopted our report concerning the December 8, 2014, accident in which an Embraer EMB-500 (marketed as the Phenom 100), N100EQ, registered to and operated by Sage Aviation LLC, crashed while on approach to runway 14 at Montgomery County Airpark, Gaithersburg, Maryland.¹ Additional information about this accident and the resulting recommendations may be found in the report of the investigation, which can be accessed at our [Aviation Information Resources](#) webpage under report number NTSB/AAR-16/01.

As a result of this investigation, we issued three new recommendations, including one to the General Aviation Manufacturers Association, one to the National Business Aviation Association, and the following recommendation to the Federal Aviation Administration:

A-16-12

Work with the General Aviation Manufacturers Association to develop a system that can automatically alert pilots when the ice protection systems should be activated on turbofan airplanes that require a type rating and are certified for single-pilot operations and flight in icing conditions.

Chairman HART, Vice Chairman DINH-ZARR, and Members SUMWALT and WEENER concurred in this recommendation.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate receiving a response from you within 90 days detailing the actions you have taken or intend to take to implement it. When replying, please

¹ National Transportation Safety Board, *Aerodynamic Stall and Loss of Control During Approach, Embraer EMB-500, N100EQ, Gaithersburg, Maryland, December 8, 2014*, NTSB/AAR-16/01 (Washington, DC: National Transportation Safety Board, 2016).

refer to the safety recommendation by number. We encourage you to submit your response electronically to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.

[Original Signed]

By: Christopher A. Hart,
Chairman