APPENDIX B

Caldive International 10/13/06 Dive Survey

West Cote Blanche Bay
MAR07MM001

DAILY LOG

DATE: 10-13-06 CUSTOMER: Gulf Port Energy JOB NO: 4591-51

TIME	DESCRIPTION
06-00	Arrive POI Office, N.I. Loading gear and recieving Paperwork/job pack
06-30	Departed POI for texaco Ivanhoe dock
07-15	Arrived Ivanhoe dock. Signing in
08-00	Drove to coast guard meeting @ Bayview on Cypermort point
08 45	Loading JIU Boat Chevy Elevator
09-30	Underway to west cote blanche bay
11-30	Arrival west cote blanche bay
11 40	Walk way set, conferring with State Police Hazmat team.
-58	Conducted safety meeting / JSA discussion
12-33	Diver #1 Mike Gann in water to inspect 6" pl. & Diver reports pl is severed, 3" pl. crossing 25 ft. from break
47	Diver #1 LB.
13-00	Called Gulf Port Energy & CDI to inform of findings.
13-30	Breaking down equipment, stowing for travel.
1350	Underway. Enroute to texaco Ivanhoe dock.
15 58	Arrival at texaco Ivanhoe dock
16-10	Truck arrived, offloading gear from boat.
34	Truck loaded, departing for POI
05	Attended NTSB investigation meeting
18-38	Departed meeting for POI
18-52	Arrived POI

FORM #F-105


Stern side P/L
At Break
Bow Side
has a clean
break
6" GaP
@ 6 o'clock position running all the way back
to the 3" P/L
SPUD
cable
6"
6"
25'
3" P/L
3" hole