

EXHIBIT 2-Q

Docket No. DCA-08-MR009

**NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C. 20594**

**Trouble Tickets, March to September 2008, from
Control Point Bernson to Control Point Davis**

View Signal Trouble

8:29A 9/17/08

Logged:	Date	Time	Entry	Ent By	Position	Status
	4/21/08	7:01A	487	MNGR KR	CON 1	Active

Reported by: DISP. NMO

Occurred:	Date	Time	Station	Milepost	ID	Call Sign
	4/20/08	1:30P	1VENTU	446.80		N/A

Crossing: CP BERSON DOT Crossing: N/A

Region: Municipality:

Problem: TK Track indication

Comment: A TRACK INDICATION REMAINED ON THE MAIN TRACK
BEHIND THE LOCAL WHO WAS WORKING BETWEEN CP BERSON
AND CP RAYMER.

Action Taken Prior To Repair: N/A

Notified:	Date	Time	Person	Call Sign
	4/20/08	1:30P	R MONGIELLO	C&S 13

Law Enforcement				
Notified:	Date	Time	Person	Agency
	4/20/08	1:30P	N/A	N/A

Corrected:	Date	Time
	4/21/08	2:30P

Cause: 601 Switch, open points.

Comment: FOUND A GAP IN THE SWITCH POINTS AT MP 447.10 MNTR
SPIKED AND CLAMPED. TRK DEPT. CLOSED THE GAP IN
THE POINTS. MNTR ADJUSTED AND TESTED W/OUT EXCEPTN

Logged:	Date	Time	Entry	Ent By	Position	Status
	6/12/08	3:34P	687	MNGR GCA	CON 1	Active

Reported by: MRZ DISP

Occurred:	Date	Time	Station	Milepost	ID	Call Sign
	6/12/08	3:32P	IVENTU	444.40		

Crossing: CP TOPANGA DOT Crossing: CP4444
 Region: VENTURA Municipality: CHATSWORTH
 Problem: WFR Switch, Failed to reverse.
 Comment: SWITCH FAILED TO REVERSE.

Action Taken Prior To Repair: N/A

Notified:	Date	Time	Person	Call Sign
	6/12/08	3:34P	D COTTON	C&S 12

Law Enforcement Notified:	Date	Time	Person	Agency
	6/12/08	3:34P	N/A	N/A

Corrected:	Date	Time
	6/12/08	7:13P

Cause: 610 Switch, gage rod.

Comment: MNTR FOUND A GAP POINT ON THE REVERSE SIDE OF THE SWITCH DUE TO A B/O GAGE ROD. TRACK DEPT MADE REPAIRS TO ROD AND SW. WAS RE-ADJUSTED AND TESTED.

View Signal Trouble

8:29A 9/17/08

Logged:	Date	Time	Entry	Ent By	Position	Status
	9/08/08	1:41P	20	MNGR GCA	CON 1	Active
Reported by:	ML 110					

Occurred:	Date	Time	Station	Milepost	ID	Call Sign
	9/08/08	8:50A	1VENTU	445.20		
Crossing:	INTERMEDIATE 4452			DOT Crossing: MP4452		
Region:	VENTURA			Municipality: CHATSWORTH		
Problem:	SCR Signal, Changing colors repeatedly					
Comment:	ML 110 REPORTED THAT THE INTERMEDIATE 4452 WAS GREEN, CHANGED TO YELLOW, AND BACK TO GREEN AGAIN.					

Action Taken Prior To Repair: N/A

Notified:	Date	Time	Person	Call Sign
	9/08/08	8:50A	J MCINTYRE	C&S 10

Law Enforcement Notified:	Date	Time	Person	Agency
	9/08/08	8:50A	N/A	N/A

Corrected:	Date	Time

Cause: 0 *****OPEN TICKET*****

Comment: PROBLEM REPORTED TO SUPERVISOR AND LATER TO MNTR. WORKING ON THE PROBLEM AT THE END OF MY SHIFT.

Logged:	Date	Time	Entry	Ent By	Position	Status
	9/12/08	6:39P	36	MNGR KR	CON 1	Active
Reported by:		M111				

Occurred:	Date	Time	Station	Milepost	ID	Call Sign
	9/12/08	4:22P	1VENTU	444.40		N/A

Crossing: CP TOPANGA DOT Crossing: CP4444
 Region: VENTURA Municipality: CHATSWORTH
 Problem: ATT Accident, train / train

Comment: M111 AND UP8491 COLLIDED APPROXIMATELY 200 FT.
 WEST OF CP TOPANGA.

Action Taken Prior To Repair: N/A

Notified:	Date	Time	Person	Call Sign
	9/12/08	4:27P	J MCINTYRE	C&S 13

Law Enforcement Notified:	Date	Time	Person	Agency
	9/12/08	4:25P	CORT	METROLINK SHERIFF

Corrected:	Date	Time

Cause: 0 *****OPEN TICKET*****

Comment: UNDER INVESTIGATION