



National Transportation Safety Board

Washington, DC 20594

Safety Recommendation

Date: December 26, 2012

In reply refer to: H-12-52 and -53

Mr. Mitch Bainwol
President
Alliance of Automobile Manufacturers
1401 Eye Street, NW
Suite 900
Washington, DC 20005

Mr. Michael J. Stanton
President
Global Automakers
1050 K Street, NW
Suite 650
Washington, DC 20001

Mr. Gary Shapiro
President
Consumer Electronics Association
1919 Eads Street
Arlington, VA 22202

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. The NTSB determines the probable cause of the accidents and issues safety recommendations aimed at preventing future accidents. In addition, the NTSB carries out special studies concerning transportation safety and coordinates the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters. We are providing the following information to urge your organization to take action on the safety recommendations being issued in this letter.

On December 11, 2012, the NTSB adopted its special investigation report concerning wrong-way driving, which addressed the safety issues associated with wrong-way driving collisions and provided countermeasures to prevent such accidents.¹ Additional information about this special investigation and the resulting recommendations may be found in the report of the investigation, which can be accessed at our website, <http://www.nts.gov>, under report number NTSB/SIR-12/01.

¹ See *Wrong-Way Driving*, Highway Special Investigation Report NTSB/SIR-12/01 (Washington, DC: National Transportation Safety Board, 2012).

As a result of this investigation, the NTSB issued 16 new recommendations, including 5 to the Federal Highway Administration; 2 to the National Highway Traffic Safety Administration; 1 to the 33 states that do not mandate the use of alcohol ignition interlock devices for all driving while intoxicated offenders, the Commonwealth of Puerto Rico, and the District of Columbia; 1 to the 50 states, the Commonwealth of Puerto Rico, and the District of Columbia; 1 to the American Association of State Highway and Transportation Officials; 1 to the Automotive Coalition for Traffic Safety, Inc.; 1 to the International Association of Chiefs of Police; 1 to the National Sheriffs' Association; 1 to SAE International; and the following 2 recommendations to the Alliance of Automobile Manufacturers, Global Automakers, and the Consumer Electronics Association:

H-12-52

Work with SAE International to develop standards for global positioning system (GPS) wrong-way navigation alerts.

H-12-53

Inform your members of the benefits of incorporating wrong-way navigation alerts into global positioning system (GPS) navigation systems.

These safety recommendations are derived from the NTSB's investigation and are consistent with the evidence we found and the analysis we performed. Chairman HERSMAN, Vice Chairman HART, and Members SUMWALT, ROSEKIND, and WEENER concurred in these recommendations.

The NTSB is vitally interested in these recommendations because they are designed to prevent accidents and save lives. We would appreciate receiving a response from you within 90 days detailing the actions you have taken or intend to take to implement them. When replying, please refer to the safety recommendations by number. We encourage you to submit your response electronically to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. To avoid confusion, please do not submit both an electronic copy and a hard copy of the same response.

[Original Signed]

By: Deborah A.P. Hersman
Chairman