

 National Transportation Safety Board FACTUAL REPORT AVIATION		NTSB ID: DCA08RA063		Aircraft Registration Number: N704CK	
		Occurrence Date: 05/25/2008		Most Critical Injury: None	
		Occurrence Type: Accident		Investigated By: Foreign	
Location/Time					
Nearest City/Place Brussels		State	Zip Code	Local Time 1143	Time Zone
Airport Proximity:		Distance From Landing Facility:			
Aircraft Information Summary					
Aircraft Manufacturer Boeing		Model/Series B747-200		Type of Aircraft Airplane	
Revenue Sightseeing Flight: No			Air Medical Transport Flight: No		
Narrative					
<p>Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:</p> <p>On May 25, 2008, at about 1331 AM local time, a Kalitta Air Boeing 747-200, registration N704CK, overran runway 20 after a rejected takeoff at Brussels International Airport, Brussels, Belgium. There were no serious injuries to the 4 crew members or 1 passenger on board the airplane. The airplane airplane was destroyed. There was no fire.</p> <p>The accident investigation is being conducted by the Air Accident Investigation Unit (Belgium). The NTSB has assigned an Accredited Representative to assist the investigation under the provisions of ICAO Annex 13 as the State of Manufacture and Design of the airframe and powerplants, the State of Registry, and State of the Operator. The US Federal Aviation Administration, Boeing, Pratt & Whitney, and Kalitta Air have been designated as technical advisors to the US Accredited Representative.</p> <p>Inquiries should be directed to: Air Accident Investigation Unit (Belgium) Ministry of Mobility and Transport of Belgium Centre Communications Nord -2ème étage Rue du Progrès, 80 - Bte 5 1030 Bruxelles Belgique Website: http://www.mobilit.fgov.be</p>					
FACTUAL REPORT - AVIATION					
					Page 1

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>		NTSB ID: DCA08RA063			
		Occurrence Date: 05/25/2008			
		Occurrence Type: Accident			
Landing Facility/Approach Information					
Airport Name	Airport ID:	Airport Elevation Ft. MSL	Runway Used	Runway Length	Runway Width
Runway Surface Type:					
Runway Surface Condition:					
Approach/Arrival Flown:					
VFR Approach/Landing:					
Aircraft Information					
Aircraft Manufacturer Boeing		Model/Series B747-200		Serial Number	
Airworthiness Certificate(s):					
Landing Gear Type:					
Amateur Built Acft? No	Number of Seats:	Certified Max Gross Wt.	LBS	Number of Engines:	
Engine Type:	Engine Manufacturer:	Model/Series:	Rated Power:		
- Aircraft Inspection Information					
Type of Last Inspection	Date of Last Inspection	Time Since Last Inspection Hours	Airframe Total Time Hours		
- Emergency Locator Transmitter (ELT) Information					
ELT Installed?/Type	ELT Operated?	ELT Aided in Locating Accident Site?			
Owner/Operator Information					
Registered Aircraft Owner		Street Address			
		City	State	Zip Code	
Operator of Aircraft KALITTA AIR		Street Address			
		City	State	Zip Code	
Operator Does Business As:			Operator Designator Code: CKSR		
- Type of U.S. Certificate(s) Held:					
Air Carrier Operating Certificate(s): Flag Carrier/Domestic; Supplemental					
Operating Certificate:			Operator Certificate:		
Regulation Flight Conducted Under: Part 121: Air Carrier					
Type of Flight Operation Conducted: Non-scheduled; International; Cargo					

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: DCA08RA063	
	Occurrence Date: 05/25/2008	
	Occurrence Type: Accident	

First Pilot Information

Name	City	State	Date of Birth	Age
------	------	-------	---------------	-----

Sex:	Seat Occupied:	Occupational Pilot?	Certificate Number:
------	----------------	---------------------	---------------------

Certificate(s):

Airplane Rating(s):

Rotorcraft/Glider/LTA:

Instrument Rating(s):

Instructor Rating(s):

Current Biennial Flight Review?

Medical Cert.:	Medical Cert. Status:	Date of Last Medical Exam:
----------------	-----------------------	----------------------------

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot In Command(PIC)										
Instructor										
Instruction Received										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

Seatbelt Used?	Shoulder Harness Used?	Toxicology Performed?	Second Pilot?
----------------	------------------------	-----------------------	---------------

Flight Plan/Itinerary

Type of Flight Plan Filed:

Departure Point	State	Airport Identifier	Departure Time	Time Zone
Same as Accident/Incident Location				


Destination	State	Airport Identifier	
Bahrain			

Type of Clearance:

Type of Airspace:

Weather Information

Source of Wx Information:

 <p>National Transportation Safety Board FACTUAL REPORT AVIATION</p>	NTSB ID: DCA08RA063
	Occurrence Date: 05/25/2008
	Occurrence Type: Accident

Weather Information					
WOF ID	Observation Time	Time Zone	WOF Elevation Ft. MSL	WOF Distance From Accident Site NM	Direction From Accident Site Deg. Mag.
Sky/Lowest Cloud Condition:				Ft. AGL	Condition of Light:
Lowest Ceiling:			Ft. AGL	Visibility: SM	Altimeter: "Hg
Temperature: °C	Dew Point: °C	Weather Conditions at Accident Site:			
Wind Direction:		Wind Speed:		Wind Gusts:	
Visibility (RVR): Ft.		Visibility (RVV) SM			
Precip and/or Obscuration:					

Accident Information		
Aircraft Damage: Destroyed	Aircraft Fire:	Aircraft Explosion

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot				1	1
Second Pilot				1	1
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer				1	1
Cabin Attendants					
Other Crew				1	1
Passengers				1	1
- TOTAL ABOARD -				5	5
Other Ground	0	0	0		0
- GRAND TOTAL -	0	0	0	5	5

National Transportation Safety Board

FACTUAL REPORT

AVIATION



NTSB ID: DCA08RA063

Occurrence Date: 05/25/2008

Occurrence Type: Accident

Administrative Information

Investigator-In-Charge (IIC)

Joe Sedor

Additional Persons Participating in This Accident/Incident Investigation:

Vikki Anderson