

The following Safety Recommendations were issued as a result of NTSB Highway Accident Report, "Pickup Truck Centerline Crossover Collision with Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017." Report Number HAR-18-02. Adopted on October 16, 2018 and published on November 20, 2018.

Safety Recommendation Number	Safety Recommendation Recipient	Safety Recommendation Text
H-18-056	National Highway Traffic Safety Administration	Develop and disseminate best practices, identify model specifications, and create a conforming products list for oral fluid drug screening devices.
H-18-057	National Highway Traffic Safety Administration	Evaluate best practices and countermeasures found to be the most effective in reducing fatalities, injuries, and crashes involving drug-impaired drivers and provide additional guidance to the states on drug-impaired driving in <i>Countermeasures That Work: A Highway Safety Countermeasure Guide for State Highway Safety Offices</i> .
H-18-058	National Highway Traffic Safety Administration	Amend Federal Motor Vehicle Safety Standard 210 to increase the minimum anchorage spacing for individual seat belt assemblies, taking into account the dynamic testing of seat belt designs, seat belt fit, and vehicle configuration.
H-18-059	National Highway Traffic Safety Administration	Amend Federal Motor Vehicle Safety Standard 208 to require lap/shoulder belts for each passenger seating position on all new buses with a gross vehicle weight rating of more than 10,000 pounds but not greater than 26,000 pounds.

Safety Recommendation Number	Safety Recommendation Recipient	Safety Recommendation Text
H-18-060	State of Texas	Conduct an executive-level review of your impaired driving program and implement data-driven strategies that result in a downward trend in the number of fatalities, injuries, and crashes involving alcohol- and other drug-impaired drivers.
H-18-061	Texas Department of Transportation	Promote the importance of attending drug-impaired driving enforcement training and increase training access to meet the demands of local and state law enforcement.
H-18-062	ARBOC Specialty Vehicles, LLC; Coach & Equipment Manufacturing Corporation; REV Group, Inc.; Diamond Coach Corporation; Forest River, Inc.; Girardin Blue Bird; SVO Group, Inc.; and Thomas Built Buses	Install lap/shoulder belts in all seating positions as standard, rather than optional, equipment in all newly manufactured medium-size buses.
H-18-063	Freedman Seating Company and HSM Transportation Solutions	Supply seating systems equipped with lap/shoulder belts as standard, rather than optional, equipment for medium-size buses.

The following Safety Recommendations were reiterated as a result of NTSB Highway Accident Report, "Pickup Truck Centerline Crossover Collision with Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017." Report Number HAR-18-02. Adopted on October 16, 2018 and published on November 20, 2018.

Safety Recommendation Number	Safety Recommendation Recipient	Safety Recommendation Text
H-12-033	National Highway Traffic Safety Administration	Develop and disseminate to appropriate state officials a common standard of practice for drug toxicology testing, including (1) the circumstances under which tests should be conducted, (2) a minimum set of drugs for which to test, and (3) cutoff values for reporting the results.

November 20, 2018

Heidi King
Deputy Administrator
National Highway Traffic Safety Administration

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*, NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations are four new recommendations and one reiterated recommendation issued to the National Highway Traffic Safety Administration, which can be found on pages 46 and 47 of the report.

The NTSB is vitally interested in these recommendations because they are designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement these recommendations. When replying, please refer to the safety recommendations by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Honorable Greg Abbott
Governor
State of Texas

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*, NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to the state of Texas, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. James M. Bass
Executive Director and CEO
Texas Department of Transportation

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*, NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to the Texas Department of Transportation, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. Don Roberts
President
ARBOC Specialty Vehicles, LLC

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*, NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to ARBOC Specialty Vehicles and other manufacturers of medium-size buses, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. Jim McMullen
CEO
Coach & Equipment Manufacturing Corporation

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*, NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to Coach & Equipment Manufacturing Corporation and other manufacturers of medium-size buses, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. Tim Sullivan
President and CEO
REV Group, Inc.

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*,

NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to REV Group, Inc., and other manufacturers of medium-size buses, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. John Resnik
CEO
Diamond Coach Corporation

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*, NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to Diamond Coach Corporation and other manufacturers of medium-size buses, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. David Wright
President
Forest River, Inc.

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*, NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to Forest River, Inc., and other manufacturers of medium-size buses, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. Steve Girardin
President and CEO
Girardin Blue Bird

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*, NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to Girardin Blue Bird and other manufacturers of medium-size buses, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. Alex Foris
President
SVO Group, Inc.

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*,

NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to SVO Group, Inc., and other manufacturers of medium-size buses, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. Caley Edgerly
President and CEO
Thomas Built Buses

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*,

NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to Thomas Built Buses and other manufacturers of medium-size buses, which can be found on page 46 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. Craig Freedman
President and CEO
Freedman Seating Company

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017*,

NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to Freedman Seating Company and one other seating manufacturer, which can be found on page 47 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



November 20, 2018

Mr. Mark S. Jones
President and CEO
HSM Transportation Solutions

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant accidents in other modes of transportation—railroad, highway, marine, and pipeline. We determine the probable cause of the accidents and issue safety recommendations aimed at preventing future accidents. In addition, we carry out special studies concerning transportation safety and coordinate the resources of the federal government and other organizations to provide assistance to victims and their family members affected by major transportation disasters.

On October 16, 2018, the NTSB adopted its report *Pickup Truck Centerline Crossover Collision With Medium-Size Bus on US Highway 83, Concan, Texas, March 29, 2017,*

NTSB/HAR-18/02. The details of this investigation and the resulting safety recommendations may be found in the attached report, which can also be accessed at www.ntsb.gov.

Among the safety recommendations is one new recommendation issued to HSM Transportation Solutions and one other seating manufacturer, which can be found on page 47 of the report.

The NTSB is vitally interested in this recommendation because it is designed to prevent accidents and save lives. We would appreciate a response within 90 days, detailing the actions you have taken or intend to take to implement it. When replying, please refer to the safety recommendation by number. We encourage you to submit your response to correspondence@ntsb.gov. If it exceeds 10 megabytes, including attachments, please e-mail us at the same address for instructions. Please do not submit both an electronic copy and a hard copy of the same response.



Safety Recommendation Reiteration List

SR Number	Reiteration Number	Report Number	Report Date	Accident Description	Accident City	Accident State	Accident Date
H-18-059	1	HAR-21-01	6/3/2021	Medium-Size Bus Roadway Departure, Return, and Rollover	Bryce Canyon City	UT	9/20/2019

Safety Recommendation Reiteration List

SR Number	Reiteration Number	Report Number	Report Date	Accident Description	Accident City	Accident State	Accident Date
H-18-062	1	HAR-21-01	6/3/2021	Medium-Size Bus Roadway Departure, Return, and Rollover	Bryce Canyon City	UT	9/20/2019

Safety Recommendation Reiteration List

SR Number	Reiteration Number	Report Number	Report Date	Accident Description	Accident City	Accident State	Accident Date
H-18-063	1	HAR-21-01	6/3/2021	Medium-Size Bus Roadway Departure, Return, and Rollover	Bryce Canyon City	UT	9/20/2019