

Maryland State Police
District Heights, MD
September 27, 2008
MIA08MA203

**NATIONAL TRANSPORTATION SAFETY BOARD
WASHINGTON, D.C.**

ATTACHMENT 1

PHOTOGRAPHS

12 Pages



Photo 1. Rear of surviving victim's vehicle (Courtesy: Charles County Sheriff's Office)




Photo 2. Rear of surviving victim's vehicle (Courtesy: Charles County Sheriff's Office)



Photo 3. Driver's side of surviving victim's vehicle
(Courtesy: Charles County Sheriff's Office)



Photo 4. Second vehicle involved in the motor vehicle accident
(Courtesy: Charles County Sheriff's Office)



Photo 5. Forward-facing view of a sister ship's HSA (Courtesy: Maryland State Police)



Photo 6. Aft-facing view of a sister ship's HSA (Courtesy: Maryland State Police)



Photo 7. Aircraft wreckage on the morning of September 28th
(Note the location of both crew helmets forward of the main wreckage)



Photo 8. Main wreckage of N92MD lying on its left side
(Courtesy: Maryland State Police)



Photo 9. Underside of N92MD (Courtesy: Maryland State Police)



Photo 10. The tail and aft, left sliding door of N92MD (Courtesy: Maryland State Police)



Photo 11. The HSA of N92MD (Note the floor fixture for the primary patient's litter on the left side of the helicopter)



Photo 12. The primary (left) and secondary litters after being removed from the wreckage (Courtesy: Maryland State Police)



Photo 13. The toe end of the yellow backboard (note the fractures)



Photo 14. The underside of the yellow backboard and the fractured wooden support



Photo 15. Pilot seat



Photo 16. Pilot's seatbelt buckle and lapbelts



Photo 17. Pilot's undamaged shoulder harness attachment fitting



Photo 18. Medic seat



Photo 19. Field provider's seatbelt buckle



Photo 20. The door handle of the left-side primary patient entry door



Photo 21. N92MD's Dorne & Margolin emergency locator transmitter



Photo 22. Crew helmets



Photo 23. Damage to medic's helmet



Photo 24. Damage to pilot's helmet