

PHOTOGRAPH LOG
5 Photographs

(7 Pages)

PHOTOGRAPH LOG

VICTORIA, TEXAS

HWY-08-MH-011

1. Rear of Accident Vehicle showing Schedule
2. Rear License Mexico and Texas Plates on Accident Vehicle
3. Annual Inspection Stickers on Windshield of Accident Vehicle
4. Vehicle Identification Number (VIN) plate on Volvo accident vehicle – without FMVSS Certification Statement
5. Vehicle Identification Number (VIN) plate on exemplar vehicle (Van Hool) with FMVSS Certification Statement



PHOTO #1: Rear of accident vehicle showing schedule



PHOTO # 2: Rear License Mexico and Texas plates on accident vehicle.



PHOTO # 3: Annual Inspection Stickers on windshield of accident Vehicle




PHOTO # 4: VIN plate on Volvo accident vehicle – without FMVSS certification statement



PHOTO # 5: VIN plate on exemplar vehicle (Van Hool) with FMVSS certification statement