




Sinking of the Small Passenger Vessel
Panther
DCA03MM018

Intact Rudder Assembly and Support Plate



Exhaust Removed- Preparing to Remove Plate



Top Support Block with Plate Removed



Support Block After Removal- Sent to NTSB Lab



Rudder Assembly and Support Plate removed
with stringers visible



Middle Block



Starboard Stringer Deflection

