

National Transportation Safety Board

Biloxi, Mississippi March 7, 2017

Pete Kotowski, IIC

1

Biloxi, Mississippi


- 2016 Van Hool
 - 60-year-old driver
 - 49 passengers
 - ECHO Transportation
- CSX Freight Train
 - 3 locomotives, 52 cars
 - 49-year-old engineer
 - 37-year-old conductor








Crash Trip






Crash Location

Stopped at crossbar Raised rear axle Started across tracks **Became grounded** Unable to free the motorcoach Heard signals activate • Told passengers to evacuate





Crash Sequence





Train Horn





Train Approach





Scene Photos









Injury Information

Fatalities

4 motorcoach passengers
Serious injuries
21 motorcoach passengers
1 motorcoach driver

 Minor injuries
 16 motorcoach passengers

• None

 8 motorcoach passengers

• 2 train crew members



On-Scene Staff

- Pete Kotowski
- Steven Prouty
- Sheryl Harley
- Michele Beckjord
- Dennis Collins
- Michael LaPonte
- Brian Bragonier
- Tim DePaepe

Highway Factors Survival Factors Survival Factors Human Performance **Motor Carrier Factors** Vehicle Factors **Rail Signals**



On-Scene Staff

- Tomas Torres
- Jane Foster
- Elias Kontanis, PhD
- Steve Blackistone
- Peter Knudson
- Pummy Bawa
- James Anderson

Rail Operations Recorders Specialist Chief, TDA **Government Affairs** Media Relations **Computer Support** AV Specialist



Report Development Staff

- Ensar Becic, PhD
- Gwynne O'Reagan
- Julie Perrot
- Michael Hamilton

Project Manager Editor Safety Recommendations Safety Recommendations



Parties to Investigation

- Biloxi Police Department
- Federal Motor Carrier Safety Administration
- Federal Railroad Administration
- Biloxi Department of Engineering
- CSX Transportation
- TBL Group ECHO Tours & Charters
- ABC Bus c/o Van Hool
- Federal Highway Administration, Office of Infrastructure Research & Development (Turner-Fairbank Laboratory)
- Mississippi Department of Transportation Rails Division



Exclusions

- Motorcoach driver, engineer, and conductor
 - Properly licensed and medically qualified
 - Not distracted by cell phone use
 - No substance impairment or medical conditions
- Mechanical condition of the motorcoach
- Railroad signal system operation



Safety Issues

- High-profile grade crossings
 - Signage and reconstruction guidelines
 - Coordination of maintenance activities and monitoring of safety risk







Emergency egress and extrication



